

**FIFTH FIVE-YEAR REVIEW REPORT FOR
PORTLAND CEMENT (KILN DUST 2 & 3) SUPERFUND SITE
SALT LAKE COUNTY, UTAH**



Prepared by

**Utah Department of Environmental Quality
Division of Environmental Response and Remediation**

For

**U.S. Environmental Protection Agency
Region 8
Denver, Colorado**

Betsy Smidinger, Director
Superfund and Emergency Management Division

Table of Contents

LIST OF ABBREVIATIONS & ACRONYMS.....	2
I. INTRODUCTION.....	3
FIVE-YEAR REVIEW SUMMARY FORM	5
II. RESPONSE ACTION SUMMARY.....	5
Basis for Taking Action	5
Response Actions	6
Status of Implementation	9
IC Summary Table	10
Systems Operations/Operation & Maintenance	11
III. PROGRESS SINCE THE LAST REVIEW	12
IV. FIVE-YEAR REVIEW PROCESS.....	13
Community Notification, Involvement & Site Interviews	13
Data Review.....	14
Site Inspection.....	16
V. TECHNICAL ASSESSMENT	17
QUESTION A: Is the remedy functioning as intended by the decision documents?	17
QUESTION B: Are the exposure assumptions, toxicity data, cleanup levels, and remedial action objectives (RAOs) used at the time of the remedy selection still valid?.....	17
QUESTION C: Has any other information come to light that could call into question the protectiveness of the remedy?.....	18
VI. ISSUES/RECOMMENDATIONS	18
OTHER FINDINGS.....	18
VII. PROTECTIVENESS STATEMENT.....	19
VIII. NEXT REVIEW	20
APPENDIX A – REFERENCE LIST	21
APPENDIX B – SITE MAPS	23
APPENDIX C – PUBLIC NOTICE.....	26
APPENDIX D – COMMUNITY INTERVIEW SUMMARY REPORTS	27
APPENDIX E – ANALYTICAL RESULTS FOR GROUNDWATER AND SURFACE WATER	31
APPENDIX F – SITE INSPECTION PHOTOS	38
APPENDIX G – SITE INSPECTION CHECKLIST	45

Tables

Table 1: Soil Contaminants of Concern	7
Table 2: Cleanup Goals for OU3 Groundwater.....	8
Table 3: Surface Water POC Performance Standards	8
Table 4: Alternate Concentration Limits	9
Table 5: Summary of Planned and/or Implemented ICs	10
Table 6: Protectiveness Determinations/Statements from the 2017 FYR	12
Table 7: Status of Recommendations from the 2017 FYR.....	13

LIST OF ABBREVIATIONS & ACRONYMS

ACL	Alternate Concentration Limits
BLL	Blood Lead Level
BLRV	Blood Lead Reference Value
BRA	Baseline Risk Assessment
CDC	Center for Disease Control
CERCLA	Comprehensive Environmental Response, Compensation, and Liability Act
CKD	Cement Kiln Dust
CFR	Code of Federal Regulations
COCs	Contaminants of Concern
COPCs	Contaminants of Potential Concern
EPA	United States Environmental Protection Agency
FYR	Five-Year Review
ICs	Institutional Controls
IEUBK	Integrated Exposure Uptake and Biokinetic Model
LEPAC	Lead Exposure Prevention and Advisory Committee
LSI	Lone Star Industries
MNA	Monitored Natural Attenuation
mg/kg	Milligrams per Kilogram
mg/L	Milligrams per Liter
µg/dL	Micrograms per Deciliter
µg/L	Micrograms per Liter
ug/m ³	Micrograms per cubic Meter
NCP	National Oil and Hazardous Substances Pollution Contingency Plan
NPL	National Priorities List
O&M	Operation and Maintenance
ORP	Oxidation Reduction Potential
OU	Operable Unit
PA	Preliminary Assessment
POC	Point of Compliance
PRP	Potentially Responsible Party
PCU	Portland Cement Company of Utah
PVC	Polyvinyl Chloride
RA	Remedial Action
RAGS	Risk Assessment Guidance for Superfund
RAO	Remedial Action Objectives
RI	Remedial Investigation
RI/FS	Remedial Investigation/Feasibility Study
ROD	Record of Decision
RPM	Remedial Project Manager
SRE	Streamlined Human Health Risk Evaluation
SRI	Streamlined Remedial Investigation
TCLP	Toxicity Characteristic Leaching Procedure
UDEQ/DERR	Utah Department of Environmental Quality, Division of Environmental Response and Remediation
UU/UE	Unlimited Use and Unrestricted Exposure

I. INTRODUCTION

The purpose of a Five-Year Review (FYR) is to evaluate the implementation and performance of a remedy in order to determine if the remedy is and will continue to be protective of human health and the environment. The methods, findings, and conclusions of reviews are documented in FYR reports such as this one. In addition, FYR reports identify issues, if any, found during the review and document recommendations to address them.

The Utah Department of Environmental Quality, Division of Environmental Response and Remediation (UDEQ/DERR) is preparing this FYR report for the U.S. Environmental Protection Agency (EPA) pursuant to the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA) Section 121, consistent with the National Contingency Plan (NCP)(40 Code of Federal Regulations (CFR) Section 300.430(f)(4)(ii)), and considering EPA policy.

This is the fifth FYR for the Portland Cement (Kiln Dust 2 & 3) Superfund Site (Site). The triggering action for this statutory review is the previous FYR completed on September 26, 2017. This FYR has been prepared due to the fact that hazardous substances, pollutants, or contaminants remain at the site above levels that allow for unlimited use and unrestricted exposure (UU/UE).

The Site consists of three Operable Units (OUs) and all three OUs are addressed in this FYR.

- Operable Unit 1 (OU1) addressed Cement Kiln Dust (CKD) at the Site.
- Operable Unit 2 (OU2) addressed chromium-bearing bricks and contaminated soils.
- Operable Unit 3 (OU3) addressed contaminated groundwater.

This Portland Cement (Kiln Dust 2 & 3) Superfund Site FYR was led by Tony Howes, UDEQ/DERR Project Manager. Participants included Athena Jones, EPA Remedial Project Manager (RPM); and Dave Allison, UDEQ/DERR Community Involvement Coordinator and Scott Everett, UDEQ/DERR Toxicologist. The review began on 11/30/2021.

EPA has determined in the Five-Year Review that the cleanup at the Portland Cement (Kiln Dust 2 & 3) Superfund Site is protective of human health and the environment. Land Use Easements that act as Institutional Controls restrict groundwater use and provide procedures for managing contaminated soils during redevelopment activities. UDEQ/DERR provides oversight of redevelopment activities that would impact groundwater monitoring wells and disturb contaminated soils.

Site Background

The Site is in Salt Lake City, Utah, on the west side of Redwood Road (1700 west) at 1000 south, within a triangular area defined by Indiana Avenue, Redwood Road and the Jordan River overflow canal (Surplus Canal) (Appendix B - Figure 1). The Site comprises approximately 71 acres and is divided into three smaller adjacent areas known as Site Two (approximately 17 acres), Site Three (approximately 19 acres), and the West Site (approximately 35 acres) (Appendix B - Figure 2). The majority of the Site has been developed and supports a variety of uses including the Wallace Stagner Academy charter school, J.G. Cooksey Boiler Makers Training Center, and the Redwood Depot commercial warehouse retail area.

The Site was used for the disposal of CKD and chromium-bearing refractory bricks from 1963 to 1983. CKD is a by-product of burning raw cement materials in a rotary kiln and chromium-bearing bricks are used as a liner in the kiln. All of the CKD and chromium-bearing bricks disposed of at the Site came from the Portland Cement plant located at 619 West 700 South in Salt Lake City, Utah. The plant was owned and operated by the Portland Cement Company of Utah (PCU) until September 1979, when Lone Star Industries (LSI) purchased the stock of PCU. Although the CKD was placed on the Site by PCU and LSI, neither company owned the land comprising the Site. Land at the Site was owned by the Horman Family Trust, and Williamsen Family Interests. LSI, the

Horman Family Trust, and Williamsen Family Interests were identified by the EPA as Potentially Responsible Parties (PRPs) for the Site.

LSI filed for bankruptcy in 1990, and as part of the settlement claim, a total of 18.5 million dollars in securities was paid to the EPA, US Department of Interior, and the State of Utah. With this action, the liability of LSI relating to the Site was fully resolved. Funds from this settlement were used by UDEQ/DERR to address contamination associated with the disposal of the CKD and chromium-bearing bricks at the Site. The Horman Family Trust resolved their liabilities relating to the Site in 1997 under a settlement agreement with the EPA, and the Williamsen Family Interests resolved their liabilities relating to the Site in 1998 under a settlement agreement with the EPA.

Approximately 500,000 cubic yards of CKD, ranging in thickness from three to eight feet, and 360 tons of chromium-bearing bricks were disposed of at the Site. Disposal of these wastes resulted in the contamination of both soil and groundwater with metal contaminants that exceeded residential health-based action levels. The highly alkaline nature of the CKD also posed human health/environmental risks.

Groundwater aquifers of interest at the Site are the shallow and intermediate aquifers. Both of these aquifers are located above the Salt Lake Valley Principal Aquifer that supplies a majority of the drinking water to the Salt Lake Valley. The shallow aquifer is unconfined, while the intermediate aquifer is confined between two continuous clay layers. Vertical flow between the two aquifers is upward from the intermediate aquifer to the shallow aquifer.

Horizontal groundwater flow in the shallow (contaminated) aquifer is complex due to interaction with local surface water and utility pathways. Primary areas of recharge are the unlined surplus canal along the southern boundary of the Site and underflow along the eastern site boundary. Shallow groundwater discharges to the City Drain, an unlined storm water ditch that bisects the Site and flows east to west. The Site is also bisected from north to south by a sanitary sewer. The sewer line bedding material acts as a conduit removing groundwater from the Site and routing it into the City Drain. Together, these two features ensure that shallow groundwater beneath the Site is discharged into the City Drain.

FIVE-YEAR REVIEW SUMMARY FORM

SITE IDENTIFICATION		
Site Name: Portland Cement (Kiln Dust 2 & 3)		
EPA ID: UTD980718670		
Region: 8	State: UT	City/County: Salt Lake City/ Salt Lake County
SITE STATUS		
NPL Status: Final		
Multiple OUs? Yes	Has the site achieved construction completion? Yes	
REVIEW STATUS		
Lead agency: State		
Author name: Tony Howes		
Author affiliation: UDEQ/DERR		
Review period: 11/1/2021 - 8/15/2022		
Date of site inspection: 11/17/2021		
Type of review: Statutory		
Review number: 5		
Triggering action date: 9/26/2017		
Due date (five years after triggering action date): 9/26/2022		

II. RESPONSE ACTION SUMMARY

Basis for Taking Action

The EPA and UDEQ/DERR performed a Preliminary Assessment (PA) of the Site in 1983. The assessment found that there was a potential risk to human health from metal constituents found in the CKD, specifically arsenic and lead. Subsequent investigations also supported the findings of the PA and determined that unacceptable concentrations of arsenic (up to 55 mg/kg), lead (up to 2,730 mg/kg), and other heavy metals were present in the CKD and soils at the Site.

In April 1984, LSI, one of the Site's PRPs, voluntarily began an investigation at the Site. This investigation found that groundwater beneath the Site had been contaminated with metals associated with the CKD and identified arsenic concentrations in groundwater as high as 50 milligrams per liter (mg/L). This investigation also found high pH levels in groundwater that resulted from the high alkalinity of the CKD and soils. The Site was formally placed on the NPL on June 10, 1986.

LSI also completed a Remedial Investigation (RI) in 1986 with UDEQ/DERR oversight in connection with a 1985 Consent Order for Remedial Investigation/Feasibility Study (RI/FS) issued by the State of Utah. The chief objective of the RI was to determine the nature and extent of contamination and the potential risk to human health

and the environment from the CKD and chromium-bearing bricks disposed of at the Site. The RI found levels of arsenic, cadmium, chromium 3, chromium 6, lead, and molybdenum in site soils and groundwater that exceeded background and residential health-based action levels. The RI specifically identified arsenic and lead levels in soils at the Site as a primary concern, since arsenic and lead levels were on average four and ten times higher, respectively, than background soil levels.

A baseline risk assessment (BRA) completed by the EPA in 1991 as part of the OU2 RI evaluated the CKD, chromium-bearing bricks and soil at the Site. The BRA only evaluated risks to human health. The BRA identified arsenic, cadmium, chromium 3, chromium 6, lead, and molybdenum as contaminants of potential concern (COPCs) in the CKD, chromium-bearing bricks, and soils found at the Site. The BRA identified lead levels in soils as a primary concern that would pose an unacceptable risk for hypothetical future residential use of the Site. The 1991 BRA also identified the high alkalinity of the CKD and soils as a health concern since direct contact with skin could result in burns and severe irritation.

UDEQ/DERR completed a Streamlined Human Health Risk Evaluation (SRE) for groundwater in 1995. The SRE evaluated hypothetical future residential exposure to groundwater and determined that contaminated groundwater beneath the Site posed unacceptable risks to human health. The SRE identified arsenic, cadmium, chromium, lead, manganese, molybdenum, and pH (a water quality parameter) as groundwater COPCs. The SRE found that arsenic levels in groundwater posed an unacceptable cancer risk to future residents if they used groundwater for drinking water purposes. The SRE also found that arsenic, cadmium, chromium, manganese, and molybdenum levels in groundwater posed an unacceptable acute (non-cancer) risks to human health. The EPA's Integrated Exposure Uptake and Biokinetic Model (IEUBK) was used in the SRE to evaluate health risks posed by lead concentrations in groundwater. As stated in the SRE, the IEUBK evaluation found that lead concentrations in several wells posed an unacceptable risk to children if groundwater at the site was used for drinking water purposes.

In 1996 UDEQ/DERR completed a Streamlined Remedial Investigation (SRI) for groundwater. The SRI characterized the hydrogeology, nature and extent, and fate and transport of contamination in groundwater. The hydrogeologic characterization was largely based on existing groundwater data collected during previous investigations and determined the following:

- The CKD was the source for groundwater contamination.
- An upward vertical flow of groundwater from the intermediate to the shallow aquifer provides an effective hydraulic barrier that restricts the downward migration of contaminated groundwater found in the shallow aquifer.
- Groundwater in the shallow aquifer is discharged to the City Drain, an unlined storm water ditch, as a result of the natural horizontal groundwater flow direction and flow along the sanitary sewer line.
- Arsenic concentrations above the established cleanup goal will persist in the shallow aquifer for at least 100 years as a result of slow travel times and flat hydraulic gradients.

Response Actions

For construction purposes, the Site was divided into three OUs:

- OU1 addressed the CKD.
- OU2 addressed the chromium-bearing bricks and contaminated soils.
- OU3 addressed contaminated groundwater.

A Record of Decision (ROD) for OU1 was signed on July 19, 1990. The selected remedy would address CKD and chromium-bearing refractory kiln brick and dispose of it in the Salt Lake Valley Landfill. The OU1 ROD did not list Remedial Action Objectives (RAOs).

The remedy components listed in the OU1 ROD were:

- Excavation and off-site disposal of CKD in a UDEQ/DERR- and EPA-approved, non-commercial, double-lined, industrial landfill.
- Separation of chromium-bearing refractory kiln brick from the CKD and temporary storage of the kiln brick at an acceptable on-site location for treatment and off-site disposal under OU2.
- Initiation of groundwater monitoring.

A ROD for OU2 was signed on March 31, 1992. The selected remedy would remove and treat additional contaminated soil and chromium-bearing bricks. The OU2 ROD did not list RAOs.

The OU2 ROD identified six Contaminants of Concern (COCs) for soil and developed action levels for two of the COCs:

Table 1: Soil Contaminants of Concern

Contaminant	Action Level (mg/kg)
Arsenic	70
Lead	500
Cadmium	NA
Chromium 3	NA
Chromium 6	NA
Molybdenum	NA

mg/kg = Milligrams per Kilogram

NA = Not applicable

The remedy components listed in the OU2 ROD were:

- Excavation of all soils with lead concentrations greater than 500 mg/kg and/or arsenic concentrations greater than 70 mg/kg.
- Solidification of all excavated soils exceeding 5 mg/L lead as measured by Toxicity Characteristic Leaching Procedure (TCLP) analysis.
- Treatment of chromium-bearing bricks using chemical fixation followed by solidification.
- Disposal of treated bricks and soil at an off-site facility.
- Installation of a protective layer consisting of clean fill at least 18 inches thick over the Site.

An amended ROD signed on September 29, 1995 combined OU1 and OU2 and addressed contaminant sources at the Site including CKD and chromium-bearing brick. The amended ROD also addressed contaminated soil underlying the CKD. The amended ROD did not list RAOs.

The remedy components listed in the amended ROD are:

- Removal and off-site disposal of all CKD (East Carbon Landfill, Carbon County, Utah).
- Removal and off-site disposal of all soils with contaminant concentrations above action levels to a maximum depth of 24 inches (East Carbon Landfill, Carbon County, Utah).
- Removal, off-site treatment, and disposal of chromium-bearing bricks (Grassy Mountain disposal facility, Tooele County, Utah).
- Reuse of non-hazardous debris as Site fill material.
- Installation of a protective layer consisting of clean fill at least 18 inches thick.
- Institutional controls (ICs) for contaminated soil left in place at the Site.

A ROD for OU3 was signed on August 17, 1998, and addressed groundwater contamination which occurred as a direct result of CKD that had been disposed of at the Site. The selected remedy for OU3 was monitored natural attenuation (MNA).

The OU3 ROD identified the following RAOs:

- Prevention of human exposure to Site groundwater that would result in excess cancer risk equal to or exceeding 1×10^{-6} , or a hazard quotient exceeding one, for a reasonably maximally exposed individual.
- Prevention of off-site migration of contaminants to unprotected groundwater.
- Restoration of groundwater to its beneficial use to the extent practicable.
- Prevention of unacceptable impacts to surface water associated with the Site.

The OU3 ROD established cleanup levels for the shallow aquifer that would result in attainment of the RAOs listed above. The cleanup goals for each COC are shown below:

Table 2: Cleanup Goals for OU3 Groundwater

Contaminant	Cleanup Goal (µg/L)
pH	<8.00
Arsenic	64
Cadmium	6.2
Chromium	100
Lead	15
Manganese	440
Molybdenum	182

µg/L = Micrograms per Liter

Since contaminated groundwater in the shallow aquifer discharges into the City Drain and eventually the Farmington Bay Waterfowl Management Area of the Great Salt Lake, the OU3 ROD identified surface water performance standards based on 125% of Class 3D Aquatic Wildlife Water Quality standards. The City Drain, where it passes underneath Indiana Avenue (Appendix B - Figure 2), was identified as a Point of Compliance (POC) where the in-stream dissolved concentrations were not to exceed the performance standards as shown below:

Table 3: Surface Water POC Performance Standards

Analyte	Performance Standard (µg/L)	Analyte	Performance Standard (µg/L)
pH	8.13 - 11.25	Iron	1250
Aluminum	180.75	Lead	3.13
Arsenic	187.5	Mercury	0.01
Cadmium	0.3125	Nickel	65
Chromium	92.5	Selenium	5.75
Chromium 6	13.75	Silver	2
Copper	11.25	Zinc	150

µg/L = Micrograms per Liter

The OU3 ROD established alternate concentration limits (ACLs) for groundwater discharging into the City Drain to ensure that in-stream dissolved metal concentrations do not exceed the surface water performance standards. These ACLs were calculated by determining what concentrations of individual chemicals in groundwater would cause an exceedance of the surface water POC performance standards. The groundwater ACLs are shown below:

Table 4: Alternate Concentration Limits

Analyte	ACL (µg/L)	Analyte	ACL (µg/L)
Aluminum	4,502.33	Lead	666.71
Arsenic	9,832.68	Mercury	0.62
Cadmium	139.08	Nickel	20,667.94
Chromium	26,339.81	Selenium	258.75
Chromium 6	569.26	Silver	6.21
Copper	1,564.50	Zinc	13,914.05
Iron	25,875.48		

µg/L = Micrograms per Liter

The remedy components listed in the OU3 ROD are:

- Long-term groundwater and surface-water monitoring to ensure the efficacy of the remedy and protection of human health and the environment.
- ICs in the form of groundwater use restrictions.

Status of Implementation

The Remedial Action (RA) for the Site was initiated in December 1995. Actual construction work began March 31, 1996, and RA activities for OU1 and OU2 were completed in November 1997. The scope included the following activities:

- Excavation of CKD from Sites 2 and 3.
- Excavation of CKD, debris and soil from West Site.
- Separation of chromium-bearing refractor brick from the CKD in Sites 2 and 3.
- Transportation and off-site disposal of the CKD.
- Transportation and off-site disposal of chromium-bearing refractory bricks.
- Backfilling, contouring and revegetation of the Site.
- Installation of the monitoring well network.
- Establishment of ICs in the form of land-use easements to ensure protectiveness.

The IC land-use easements include prohibitions on: the use or disturbance of groundwater until clean-up levels are achieved, excavation activities, disturbance of clean fill, and any other activities or actions that might interfere with the implemented remedy. The easements require that UDEQ/DERR be notified of activities that would impact the integrity of the cover and requires UDEQ/DERR approval of construction work on the Site. The easements also provide UDEQ/DERR with an irrevocable right of access to the property to perform inspections and groundwater monitoring.

The IC land-use easements for soil were modified in 2007 and 2009 by the property owners and UDEQ/DERR to facilitate property redevelopment. This modification was completed through a Partial Release and Quitclaim of land-use easement that released most of the Site from the original 1998 and 1999 land-use easements for soil and applied the 1998 and 1999 easements to specific locations or "hot spots" where lead concentrations were above 500 mg/kg. The Partial Release and Quitclaims provide descriptions and a map showing the specific locations in

which the IC land-use easements for soil still apply. See Table 5 for a complete list and chronology of the ICs implemented at the Site. See figure 3 for map of hot spots.

Redevelopment activities at the Site over the course of the last five years have complied with institutional controls. UDEQ/DERR received notification of redevelopment construction activities at the Site from a property owner in 2020 and provided oversight for the flush mounting of three monitoring wells. In addition to this, UDEQ/DERR and the property owner discussed compliance with the soil land-use easement and determined that contaminant hot spots located beneath the property that was being developed would remain covered and not be impacted by construction activities. UDEQ/DERR and the EPA were recently notified by a property owner about their plans to construct a new commercial warehouse retail building at the Site and are currently working with the property owner to ensure compliance with the IC land-use easements.

IC Summary Table

Table 5: Summary of Planned and/or Implemented ICs

Media, engineered controls, and areas that do not support UU/UE based on current conditions	ICs Needed	ICs Called for in the Decision Documents	Impacted Parcel(s)	IC Objective	Title of IC Instrument Implemented and Date (or planned)
Soil	Yes	Yes	Site 2, and Site 3	Provides procedures for managing soils during redevelopment and prevents unacceptable human exposure to contaminants that remain on Site.	Land Use Easement Soils Restrictions March 1998
Groundwater	Yes	Yes	Site 2, and Site 3	Prohibits construction of wells	Land Use Easement Well Ban March 1998
Soil	Yes	Yes	West Site	Provides procedures for managing soils during redevelopment and prevents unacceptable human exposure to contaminants that remain on Site.	Land Use Easement Soils Restrictions March 1999
Groundwater	Yes	Yes	West Site	Prohibits construction of wells	Land Use Easement Well Ban March 1999

Media, engineered controls, and areas that do not support UU/UE based on current conditions	ICs Needed	ICs Called for in the Decision Documents	Impacted Parcel(s)	IC Objective	Title of IC Instrument Implemented and Date (or planned)
Soil	Yes	Yes	Site 2, and Site 3	Releases March 1998 restrictions from clean areas of the Site and applies the 1998 restrictions to specific locations where contaminated soil is greater than the lead action level of 500 mg/kg.	Partial Release and Quitclaim of Land Use Easements August 2007
Soil	Yes	Yes	West Site	Releases March 1999 restrictions from clean areas of the Site and applies the 1999 restrictions to specific locations where contaminated soil is greater than the lead action level of 500 mg/kg.	Partial Release and Quitclaim of Land Use Easements January 2009

Systems Operations/Operation & Maintenance

For OU1 and OU2, Operation and Maintenance (O&M) includes maintaining 18" of protective clean backfill over the site as well as assuring vegetative cover meets the requirements set out in the amended OU1 and OU2 ROD. There are no systems requiring active operation for these OUs.

For OU3 Operation and Maintenance, UDEQ/DERR performs routine annual groundwater and surface water monitoring and sampling. Reports summarizing the results of each annual monitoring and sampling event are prepared by UDEQ/DERR and submitted to the EPA. In February 2022, an EPA hydrogeologist completed a groundwater optimization review that evaluated existing groundwater data from 2010 to 2019. Recommendations from this review included the following:

- For purposes of evaluating fluctuation in COC levels, Oxidation Reduction Potential (ORP) should be added to the list of field parameters measured and recorded during each sampling event.
- Perform groundwater sampling and analysis every five years in conjunction with the FYR for intermediate monitoring wells P2M, and PWS.
- Collect groundwater elevations and field parameters annually from intermediate monitoring wells P2M, and PWS.

The previous FYR completed on September 26, 2017, found that several monitoring wells had been removed and recommended that the remaining wells be evaluated to determine if the monitoring well network was sufficient. The EPA evaluated the remaining number of wells in the February 2022 optimization study and found that the number of existing monitoring wells were adequate for evaluating the groundwater remedy. Therefore, replacement of the removed monitoring wells is not necessary.

In October 2021, existing monitoring wells P2CA, P2DA, and P2HA were modified and flush-mounted to accommodate the construction of a new Redwood Depot commercial retail building. UDEQ/DERR worked

closely with the developer to ensure these modifications did not impact the integrity of the monitoring wells and that IC requirements for soil were also followed.

III. PROGRESS SINCE THE LAST REVIEW

This section includes the protectiveness determinations and statements from the last FYR as well as the recommendations from the last FYR and the current status of those recommendations.

Table 6: Protectiveness Determinations/Statements from the 2017 FYR

OU #	Protectiveness Determination	Protectiveness Statement
1	Protective	The remedy implemented at OU1 is protective of human health and the environment. The immediate threats posed by contamination from the CKD and chromium-bearing brick have been addressed. The excavation and off-site disposal of contaminated soil has effectively eliminated the majority of the risk associated with the COCs. The risk associated with any contaminated soil remaining after construction activities is effectively reduced by clean fill, top soil and vegetation.
2	Protective	The remedy implemented for OU2 is protective of human health and the environment. The immediate threats posed by contamination associated with OU2 have been addressed. The excavation and off-site disposal of contaminated soil have effectively reduced the risk of exposure to the COCs. The risk associated with any contaminated soil remaining after construction activities is effectively reduced by clean fill, top soil and vegetation.
3	Protective	The remedy implemented for OU3 appears to be functioning as described in the OU3 ROD. Present levels of COCs in groundwater are consistent with the concentrations and extent of contamination summaries described in the OU3 ROD. Neither off-site migration in the shallow aquifer nor migration of COC from the shallow aquifer to the intermediate aquifer is apparent. Additional data is required to assess the effectiveness of the MNA remedy given the expected time frame of 100 years for cleanup goals to be achieved. Future groundwater monitoring will continue to assist with determining the progress of MNA at the Site.
Sitewide	Protective	The Site is protective of human health and the environment. The immediate threats posed by the COCs have been addressed. The excavation and off-site disposal of contaminated soil effectively reduces the risk of exposure to lead and arsenic. Contaminated soil above unrestricted use levels is currently managed through the existing ICs. There have been no changes in the physical conditions of the Site that would affect the protectiveness of the remedy. There have been no changes in the toxicity factors for the COCs or risk assessment methodology that could affect the protectiveness of the remedies for the Site.

Table 7: Status of Recommendations from the 2017 FYR

OU #	Issue	Recommendations	Current Status	Current Implementation Status Description	Completion Date (if applicable)
1, 2, and 3	Considerable development has taken place on parcels within the Site, some of which has not been coordinated with UDEQ/DERR. Some property owners are not aware of the existence of the land-use easements nor of the prohibitions on groundwater use, coordination with UDEQ/DERR, or access granted for monitoring associated with the Site.	Increased coordination with Salt Lake City Public Utilities and Salt Lake Valley Health Department regarding construction activities and building permits near and within the Site boundaries. Determine if land-use easements are being attached to property titles during property transfers.	Ongoing	UDEQ/DERR continues to work with Salt Lake City Public Utilities, Salt Lake Valley Health Department, developers and current property owners to inform them of land-use easements, groundwater use restrictions and access. UDEQ/DERR conducted a records search with the Salt Lake County Recorder's Office and determined that land-use easements are being attached to property titles during property transfers.	NA
3	Due to property ownership changes and development/construction activities, several monitoring wells have been damaged or removed.	Coordinate repair/replacement of wells with property owners. Evaluate effectiveness of remaining wells to determine if monitoring well network is sufficient.	Completed	EPA completed a groundwater optimization review in February 2022 and found that there is an adequate number of existing wells to evaluate the groundwater remedy.	2/14/2022

IV. FIVE-YEAR REVIEW PROCESS

Community Notification, Involvement & Site Interviews

A public notice was made available by a newspaper posting (Appendix C) in the Salt Lake Tribune on 3/13/2022, stating that there was a five-year review and inviting the public to submit any comments to the EPA and UDEQ/DERR. The results of the five-year review and the report will be made available at the Site information repository located at UDEQ/DERR, 195 North 1950 West 1st Floor Salt Lake City, Utah and at <http://eqedocs.utah.gov>. The report will also be available in the EPA Superfund Records Center 1595 Wynkoop Street, Denver, Colorado 80202-1129, and on the EPA webpage at <https://www.epa.gov/superfund/portland-cement>. To request an appointment for the EPA Superfund Records Center, please call 303-312-7273.

The UDEQ/DERR conducted community interviews with individuals knowledgeable about the Site. Individuals that were interviewed included personnel with Salt Lake City Public Utilities, which maintains the City Drain, and Terramerica Corporation & Affiliates, which is the primary developer and property owner at the Site. None of the interviewees expressed any health or environmental concerns.

The Terramerica Corporation & Affiliates was aware of the land-use easements and has consulted with UDEQ/DERR numerous times to ensure compliance with the requirements of the easements. Salt Lake City Public Utilities was aware of the cleanup activities and land-use easements that have been completed at the Site and was not aware of any recent Site activities or conditions that would impact the City Drain. Reports summarizing the interviews are included in Appendix D.

Data Review

OU1 and OU2 are not subject to monitoring due to the nature of the cleanup that was completed for these two OUs.

Annual groundwater monitoring and sampling is performed by UDEQ/DERR for OU3 in accordance with the OU3 ROD and O&M Plan. Reports summarizing the results of each monitoring and sampling event are prepared and provided to the EPA.

The groundwater monitoring system for OU3 consists of ten shallow aquifer monitoring wells, four intermediate aquifer monitoring wells, and one surface water point of compliance sampling location along the City Drain (Appendix B - Figure 2). Five of the shallow aquifer monitoring wells located near the City Drain and sanitary sewer line are used for comparing dissolved metal concentration to ACLs. The ACLs are values that if exceeded would result in an exceedance of the surface water performance standard applicable to the City Drain.

Contaminant concentrations in samples collected within the last five years (i.e., May 2017 to June 2021) from the shallow and intermediate aquifer monitoring wells, surface water point of compliance, and comparison of dissolved metal concentrations to ACLs for wells near the City Drain and sewer line are provided in Appendix E. A discussion of groundwater and surface monitoring data for the last five years is provided in the following paragraphs.

Groundwater Flow Direction:

Based on a review of the Annual Groundwater and Surface Water Monitoring and Sampling Reports completed within the last five years, horizontal and vertical groundwater flow directions at the Site were consistent with previously observed flow directions. Horizontal groundwater flow direction in the shallow aquifer was towards the City Drain and vertical flow direction was upward from the intermediate aquifer to the shallow aquifer.

COCs in the Shallow Aquifer

pH:

pH levels in the shallow aquifer were above the established cleanup goal of less than 8 standard units over the period of the last five years with levels as high as 10.1 standard units in monitoring well P3FA.

Arsenic:

Arsenic concentrations in the shallow aquifer were above the established cleanup goal of 64 µg/L over the course of the last five years with concentrations as high as 1,000 µg/L in monitoring well P3CC.

Cadmium:

Laboratory detection limits for cadmium were above the cleanup goal of 6.2 µg/L for the majority of sample events completed within the last five years. Detection limits for the June 2021 sampling event were below the cleanup goal and cadmium was detected above the cleanup goal in two monitoring wells (P2FA and P3CC). The June 2021 cadmium concentrations in monitoring wells P2FA and P3CC were 7.4 µg/L and 7.8 µg/L, respectively and exceeded the cleanup goal of 6.2 µg/L.

Chromium

With the exception of the May 2017 chromium concentration in monitoring well P2FA and the June 2018 chromium concentration in monitoring well P3FA, chromium levels in the shallow aquifer during the last five years were below the cleanup goal of 100 µg/L. The May 2017 chromium concentration in well P2FA was 160 µg/L and the June 2018 chromium concentration in monitoring well P3FA was 106 µg/L. These exceedances appear to have been an isolated event since chromium concentrations after the May 2017 sample event in well P2FA were below the cleanup goal and chromium concentrations in well P3FA were below the cleanup goal before and after the June 2018 sample event.

Lead

With the exception of monitoring well P3FA, lead concentrations in the shallow aquifer during the last five years were below the cleanup goal of 15 µg/L. The June 2018 and June 2019 lead concentrations in well P3FA were 165 µg/L and 106 µg/L, respectively and exceeded the cleanup goal. These exceedances appear to have been an isolated event since lead concentrations in well P3FA before June 2018 and after June 2019 were below the cleanup goal.

Manganese

With the exception of monitoring well P3FA, Manganese concentrations in the shallow aquifer during the last five years were below the cleanup goal of 440 µg/L. The June 2018 and June 2019 manganese concentrations in well P3FA were 3,640 µg/L and 2,070 µg/L, respectively and exceeded the cleanup goal. These exceedances appear to have been an isolated event since manganese concentrations before June 2018 and after June 2019 were below the cleanup goal.

Molybdenum

Molybdenum concentrations in the shallow aquifer were above the cleanup goal of 182 µg/L over the course of the last five years with concentrations as high as 31,000 µg/L in monitoring well P3CC.

*COCs in the Intermediate Aquifer***pH:**

pH levels in the intermediate aquifer fluctuated slightly above the cleanup goal of 8 standard units six times during the last five years with levels as high as 8.48 standard units in monitoring well P3EA.

Arsenic:

With the exception of monitoring well P2M, arsenic concentrations in the intermediate aquifer were less than the cleanup goal of 64 µg/L. The May 2017 laboratory detection limit for arsenic in well P2M was greater than the cleanup goal of 64 µg/L and does not appear to be a concern since arsenic concentrations detected after May 2017 sample event were below the cleanup goal.

Cadmium:

With the exception of the May 2017 sampling event, cadmium concentrations in the intermediate aquifer during the last five years were below the cleanup goal of 6.2 µg/L. The May 2017 laboratory detection limit for cadmium in all four intermediate monitoring wells was greater the cleanup goal and the results may have exceeded the cleanup goal. Cadmium is believed to not be a concern since cadmium levels after the May 2017 sampling event were below the cleanup goal.

Lead

With the exception of monitoring well P3EA, lead concentrations in the intermediate aquifer over the period of the last five years were below the cleanup goal of 15 µg/L. The lead concentrations in the intermediate aquifer monitoring well P3EA for the June 2018 and June 2021 sampling events were 34.7 µg/L and 36 µg/L, respectively and appear to be increasing.

Manganese, molybdenum, and chromium concentrations in the intermediate aquifer over the course of the last five years were below their respective cleanup goals.

Comparison of dissolved metal concentrations to ACL values

With the exception of the June 2018 aluminum and iron concentrations in monitoring well P3FA, dissolved metal concentrations detected in the five shallow aquifer monitoring wells located near the City Drain and sewer line were below ACL values during the period of the last five years. In the last five years, silver was detected only in 2021 which concentrations being below the ACL. In 2017-2019 samples, the detection limit was above the ACL for silver which was corrected in 2021. The June 2018 aluminum and iron concentrations in well P3FA were 8,960 µg/L and 37,500 µg/L, respectively. These exceedances appear to have been an isolated event since dissolved concentrations in well P3FA before and after the June 2018 sampling event were below their ACL values.

With the exception of the June 2021 sample event, the laboratory detection limit for dissolved silver were greater than the ACL value during the last five years. The laboratory detection limit for the June 2021 sample event was below the ACL value for silver in all five ACL wells and detected silver concentrations were well below the ACL of 6.21 µg/L.

Surface water point of compliance

The laboratory detection limits for dissolved cadmium, mercury, selenium, and silver were greater than the performance standards and the results may have exceeded the performance standards. This was corrected in 2021 for cadmium, selenium, and silver. However, mercury detection limits must be further reduced to assess whether the concentration of mercury at the POC exceeds performance standards. It is unlikely that cadmium, mercury, selenium, and silver releases from the Site are a concern since concentrations in the shallow aquifer near the City Drain (PWEA) and sewer line (P3CC, PF2A) were less than their ACL values and an exceedance of the ACL in the shallow aquifer would result in an exceedance of the surface water performance standard.

Site Inspection

The inspection of the Site was conducted on 11/17/2021 by UDEQ/DERR Project Manager Tony Howes. The purpose of the inspection was to assess the protectiveness of the remedy.

Redevelopment activities were observed during the inspection along with existing monitoring wells, the City Drain, the surface water point of compliance sample location, and overall general condition of the Site. With the exception of well P2M, all monitoring wells were found to be intact and accessible. The protective steel “stick

up” casing and polyvinyl chloride (PVC) casing for monitoring well P2M were damaged and broken at the ground surface. Photographs of the Site are provided in Appendix F and the completed Site Inspection check list is included in Appendix G.

V. TECHNICAL ASSESSMENT

QUESTION A: Is the remedy functioning as intended by the decision documents?

Question A Summary:

The remedies for OU1, OU2 and OU3 are functioning as intended by the decision documents.

The excavation and disposal of CKD and contaminated soils, removal of chromium-bearing bricks, backfilling with clean soil and revegetation at OU1 and OU2 effectively removed the majority of the source of groundwater contamination. IC land use easements for soil establish procedures for managing contaminated soils that remain on Site at specific locations where lead concentrations are greater than the cleanup goal of 500 mg/kg and prevents unacceptable human exposure. See figure 3 for the map of remaining hot spots on Site.

The OU3 groundwater MNA remedial action continues to function as intended by the ROD and O&M Plan. Annual groundwater and surface water monitoring and sampling is conducted and indicates that arsenic and molybdenum concentrations and pH in the shallow aquifer were consistently above their cleanup goals during the last five years as they have been in previous FYRs. Monitoring data from the past five years shows that horizontal and vertical groundwater flow directions have remained consistent and groundwater contamination remains confined to the Site and is not migrating to unprotected groundwater. Surface water sample results collected in 2021 from the City Drain Point of Compliance indicate contaminant levels are below performance standards with the exception of mercury for which the detection limits remained above performance standards. The samples collected from 2017-2019 were analyzed with detection levels above performance standards which is noted in the findings of this FYR as an area of improvement in future data collection. . IC land use easements prohibit the use or disturbance of groundwater until clean up levels are achieved and prevents unacceptable human exposure to contaminated groundwater at the Site. Soil ICs remain in place for hot spots on site as shown in figure 3 in appendix A. Redevelopment is monitored by UDEQ to ensure awareness and compliance with ICs.

Given the expected time frame of 100 years for cleanup goals to be achieved, additional groundwater data and trend evaluation is required in order to assess the effectiveness of the groundwater MNA remedy in reducing contaminant levels. Future groundwater monitoring and sampling events will provide data for evaluating the effectiveness of the groundwater MNA remedy.

QUESTION B: Are the exposure assumptions, toxicity data, cleanup levels, and remedial action objectives (RAOs) used at the time of the remedy selection still valid?

Question B Summary:

The clean-up numbers were derived from the exposure assumptions and toxicity data in the HHRA for the Portland Cement (Kiln Dust 2 & 3) Site. There have been changes to the exposure assumptions and toxicity information since those documents. Because these documents were developed prior to the EPA’s Risk Assessment Guidance for Superfund (RAGS) Part F (2009), the exposure assumptions for the inhalation exposure pathway were conducted differently. The exposure metric that was used in the RODs and the HHRA used inhalation concentrations that were based on ingestion rate and body weight (mg/kg-day). The updated methodology uses the concentration of chemical in the air, with the exposure metric of micrograms per cubic meter (ug/m³). The inhalation pathway is minor compared to the soil ingestion pathway which is the major risk factor at the Site.

Under the current EPA Office of Land and Emergency Management policy, the soil lead screening level was established so that a typical child or similarly exposed group of children would have an estimated probability of no more than 5 percent of exceeding a blood lead level (BLL) of 10 micrograms per deciliter ($\mu\text{g}/\text{dL}$). The 10 $\mu\text{g}/\text{dL}$ BLL target concentration is based (in part) on the 1991 Center for Disease Control's (CDC) blood lead "level of concern." In 2012, CDC accepted the recommendations of its Advisory Committee on Childhood Lead Poisoning Prevention that the "level of concern" be replaced by a reference value based on the 97.5th percentile of the National Health and Nutrition Examination Survey-generated BLL distribution in children 1-5 years old (i.e., 5 $\mu\text{g}/\text{dL}$). In 2021 CDC updated its blood lead reference value (BLRV) from 5 $\mu\text{g}/\text{dL}$ to 3.5 $\mu\text{g}/\text{dL}$ in response to the Lead Exposure Prevention and Advisory Committee (LEPAC) recommendations.

For lead in soil, the EPA's Office of Solid Waste and Emergency Response Directives 9355.4-12 (EPA, 1994) and 9200.4-27P (EPA, 1998), were identified as federal chemical-specific To Be Considered guidance documents. However, since 1994 and 1998 when those documents were issued, increasing evidence has shown that blood lead levels below 10 $\mu\text{g}/\text{dL}$ may also have negative health impacts. The EPA is currently evaluating its lead cleanup policy based on recent studies that suggest adverse health effects are associated with blood levels less than 10 $\mu\text{g}/\text{dL}$. The EPA will continue using current lead policy until the Agency provides modified guidance for sites with lead contamination.

QUESTION C: Has any other information come to light that could call into question the protectiveness of the remedy?

No additional information has come to light that could call into question the protectiveness of the remedy.

VI. ISSUES/RECOMMENDATIONS

Issues/Recommendations
OU(s) without Issues/Recommendations Identified in the FYR:
1, 2 and 3
Issues and Recommendations Identified in the FYR:
None

OTHER FINDINGS

The following are recommendations that were identified during the FYR that do not affect current and/or future protectiveness:

- Based on the EPA's February 2022 optimization review, UDEQ/DERR will perform groundwater sampling and analysis every five years in conjunction with the FYR for intermediate monitoring wells P2M, and PWS. Groundwater elevations and field parameters will continue to be collected for these wells during each sampling event. UDEQ/DERR will also add the measurement, recording, and reporting of the ORP field parameter for surface water and shallow monitoring wells.
- Oxidation Reduction Potential (ORP) should be added to the list of field parameters measured and recorded during each sampling event
- Development activities associated with the completion of the Redwood Depot is anticipated in the near future. UDEQ/DERR will work with property developer to ensure compliance with ICs and preservation of existing groundwater monitoring system.
- The protective steel "stick up" casing and PVC casing for monitoring well P2M were broken at the ground surface and need to be repaired. It is anticipated that well P2M will be modified in the near future

to be flush with the existing grade in order to accommodate the construction of a new Redwood Depot building. UDEQ/DERR will work with the property developer to ensure that well P2M is properly modified and the integrity of the well is maintained.

- The O&M Plan needs to be updated by UDEQ/DERR to reflect reduction in the number of monitoring wells sampled at the Site, additional field parameters recorded during each sampling event and the change in frequency of monitoring and sampling events from semiannual to annual.
- The laboratory detection limits for cadmium, chromium, mercury, selenium and silver were greater than the established action levels for these contaminants. UDEQ/DERR will work with the contract laboratory to ensure that detection limits are below the established action levels and performance standards.
- Recommend conducting an optimization study of the MNA remedy for OU3 to determine current performance.

VII. PROTECTIVENESS STATEMENT

Protectiveness Statement

Operable Unit: 1 *Protectiveness Determination: Protective*

Protectiveness Statement: The remedy at OU1 is protective of human health and the environment. The immediate threats posed by contamination from the CKD have been addressed. The excavation and off-site disposal of the CKD has effectively eliminated the majority of the risk associated with the COCs.

Protectiveness Statement

Operable Unit: 2 *Protectiveness Determination: Protective*

Protectiveness Statement: The remedy at OU2 is protective of human health and the environment. The immediate threats posed by contamination associated with OU2 have been addressed. The off-site disposal of chromium bearing bricks and the excavation and off-site disposal of contaminated soils and have effectively reduced the risk of exposure to the COCs. The risk associated with any contaminated soil remaining after construction activities is effectively reduced by clean fill, top soil and vegetation. IC land-use easements provide procedures for managing soils during redevelopment and prevents unacceptable human exposure to contaminants that remain on Site at specific locations.

Protectiveness Statement

Operable Unit: 3 *Protectiveness Determination: Protective*

Protectiveness Statement: The remedy at OU3 is protective of human health and the environment. The remedy implemented for OU3 is functioning as intended by the OU3 ROD. COC levels in groundwater are consistent with levels documented in annual groundwater reports and previous FYRs. Groundwater contamination remains confined to the Site and is not migrating to unprotected groundwater. There are no unacceptable impacts from groundwater discharging to surface water. IC land use easements prohibit the use or disturbance of groundwater and prevent unacceptable human exposure to contaminated groundwater

Sitewide Protectiveness Statement

Protectiveness Determination: Protective

Protectiveness Statement: The Site is protective of human health and the environment. The remedial actions implemented for OU1 and OU2 effectively addressed risks associated with source materials and contaminated soil. The OU3 groundwater remedy is functioning as intended since COC levels are consistent with previous concentrations and are not migrating to unprotected groundwater. IC land use easements prohibit the use or disturbance of groundwater and provide procedures for managing contaminated soil during redevelopment activities.

VIII. NEXT REVIEW

The next five-year review report for the Portland Cement (Kiln Dust 2 & 3) Superfund Site is required five years from the completion date of this review.

APPENDIX A – REFERENCE LIST


- Dames and Moore, 1986, Remedial Investigation Cement Kiln Dust Waste Disposal Sites First Report Submitted January 1986 Lone Star Industries, 173p. SEMS 1613376
- State of Utah, 1985, Consent Order between State of Utah and Lone Star Industries Inc, dba Portland Cement Company of Utah, 16p.
- Utah Department of Health, US Environmental Protection Agency Region VIII, 1990, Record of Decision, Portland Cement Co. (Kiln Dust #2 & #3) Operable Unit 1 Salt Lake City Utah, 144p. SEMS 1611134
- Utah Department of Environmental Quality Division of Environmental Response and Remediation, 1995, Streamlined Human Health Risk Evaluation; Portland Cement Operable Unit No. 3 Site; Salt Lake City Utah. SEMS 1064255, 1612742
- Utah Department of Environmental Quality Division of Environmental Response and Remediation, 1996, Streamlined Remedial Investigation Portland Cement Operable Unit No. 3 Site Salt Lake City, Utah, 373p. SEMS 1612462
- Utah Department of Environmental Quality Division of Environmental Response and Remediation, 2017, Semi-annual Monitoring Report November 2017 Portland Cement Site OU3, 183p.
- Utah Department of Environmental Quality Division of Environmental Response and Remediation, 2018, Annual Monitoring Report Portland Cement Site OU3, 155p.
- Utah Department of Environmental Quality Division of Environmental Response and Remediation, 2019, Annual Groundwater and Surface Water Monitoring and Sampling Report Portland Cement OU3 Site, 133p.
- Utah Department of Environmental Quality Division of Environmental Response and Remediation, 2021, Annual Groundwater and Surface Water Monitoring and Sampling Report Portland Cement OU3 Site, 109p.
- U.S. Environmental Protection Agency Office of Solid Waste and Emergency Response, 1994, Revised Interim Soil Lead Guidance for CERCLA Sites and RCRA Corrective Action Facilities Directive 9355.4-12. SEMS 123472
- U.S. Environmental Protection Agency Office of Solid Waste and Emergency Response. 1998, Clarification to the 1994 Revised Interim Soil Lead Guidance for CERCLA Sites and RCRA Corrective Action Facilities, 16p. SEMS 140867
- U.S. Environmental Protection Agency Office of Superfund Remediation and Technology Innovation Environmental Protection Agency, 2009, Risk Assessment Guidance for Superfund Volume I: Human Health Evaluation Manual (Part F, Supplemental Guidance for Inhalation Risk Assessment), 68p. SEMS 1772070
- US Environmental Protection Agency Region VIII, 1991, Portland Cement Company of Utah Waste Cement Kiln Dust Disposal Site Salt Lake City, Utah Remedial Investigation Report Operable Unit 2 and Base Line Risk Assessment, 229p.
- US Environmental Protection Agency Region VIII, 1992, Record of Decision Portland Cement Co. (Kiln Dust #2 & #3) Operable Unit No. 2 Salt Lake City, Utah, 29p. SEMS 1051898
- US Environmental Protection Agency Region VIII, 1995, Record of Decision Amendment: Portland Cement (Kiln Dust 2 & 3) EPA ID: UTD 980718670 OU2 Salt Lake City, UT, 27p. SEMS 1050948


US Environmental Protection Agency Region VIII, 1998, Portland Cement Superfund Site (Kiln Dust #2 and #3)
Salt Lake City, Utah Record of Decision Operable Unit Three – Ground Water, 240p. SEMS 493505

US Environmental Protection Agency Region VIII, 2022, Portland Cement OU3 Optimization Review, 31p.

US Environmental Protection Agency Region VIII, 2017, Fourth Five-Year Review Report for Portland Cement
Superfund Site, 83p. SEMS 100001612

APPENDIX B – SITE MAPS








Figure 3: Map of lead hot spots remaining on the Site

APPENDIX C – PUBLIC NOTICE

PUBLIC NOTICE Five-Year Review Planned for the Portland Cement (Kiln Dust #2 & #3) Superfund Site Salt Lake City, Utah

The Utah Department of Environmental Quality, Division of Environmental Response and Remediation (UDEQ/DERR) and the U.S. Environmental Protection Agency (EPA) is conducting the fifth Five-Year Review of the remedial actions performed for the Portland Cement Superfund site. The purpose of a Five-Year Review is to evaluate the implementation and performance of a remedy in order to determine if it is or will be protective of human health and the environment. The Five-Year Review is scheduled to be completed by September 30, 2022.

The Portland Cement Site is 71 acres of land near 100 South Redwood Road in Salt Lake City, Utah. Approximately 825,000 tons of Cement Kiln Dust (CKD) and contaminated soil was excavated and removed off site for proper disposal. The site was backfilled with clean soil, re-graded, and seeded to complete remedy construction in 1998. Restrictions on future property use were imposed to protect the soil cover. The UDEQ and EPA agreed on the use of monitored natural attenuation as the most appropriate method for addressing groundwater contamination. Long-term monitoring and administrative restrictions on the use of site ground water ensure that public health and the environment are protected until the ground water is clean.

UDEQ and EPA invites community participation in the Five-Year Review process: As part of the Five-Year Review process, community members are encouraged to contact UDEQ staff with any information that may help EPA make its determination regarding the protectiveness and effectiveness of the remedies at the site. Additional site information is available at: DERR Offices located on the 1st Floor, at 195 North 1950 West, Salt Lake City, Utah, 84114. Please call for an appointment to review records at (801) 536-4100, Monday through Friday, from 8:30 A.M. to 4:30 P.M. Project documents are available online at: <http://eqedocs.utah.gov/> using the search phrase "Portland Cement." Or visit the EPA website at: <https://cumulis.epa.gov/supercpad/cursites/csitinfo.cfm?id=0800690>

If you would like more information about the review, please contact:

Tony Howes
UDEQ Project Manager
Phone: (385) 391-5917
Email: thowes@utah.gov

Dave Allison
UDEQ Community Involvement
Phone: (385) 391-8143
Email: dallison@utah.gov

Athena Jones
EPA Remedial Project Manager
Phone: (303) 312-6497
Email: Jones.Athena@epa.gov

APPENDIX D – COMMUNITY INTERVIEW SUMMARY REPORTS

Portland Cement (Kiln Dust 2 & 3) Superfund Site Five-Year Review Interview

Site Name: EPA ID: UTD980718670	March 10, 2022
Type of Contact: Remote Meeting	Contact Made By: Dave Allison, UDEQ/DERR Community Involvement Coordinator and Tony Howes, UDEQ/DERR Project Manager
Person Contacted	
Chris Howells, President	Terramerica Corporation & Affiliates 5320 S 900 E #250 Salt Lake City, UT 84117

- 1. Is your organization/department aware of the Superfund Site and the actions taken/underway to address environmental contamination?** Chris Howells is the President and Real Estate Broker of Terramerica Corporation, a real estate brokerage and property management company which developed a Master Plan in 2015 and began constructing buildings over approximately 45 acres of the former Portland Cement cleanup Site in 2016/17. Howells oversees the day to day operations of Terramerica and the Horman Group of Companies and is active in leasing it's industrial, retail, and office spaces, particularly at the former Superfund Site.
- 2. What's your overall impression (your general sentiment) of the actions taken/underway at the Superfund Site?** Howells said the development of property at a Superfund Site can be daunting if you don't realize what you're working with. Once you develop an understanding and a willingness to comply to the measures, working with UDEQ has been great and without any issues. The Superfund history really hasn't slowed development and is more of a market driven indicator and if construction costs weren't as high we would be onto the next building.
- 3. Does your office conduct routine communications and/or activities (site visits, inspections, reporting activities, participation in meetings, etc.) which pertain to or involve the Superfund Site? If so, please briefly summarize the purpose and results of these communications and/or activities over the last five years.** As a property owner, Howells said he is on Site regularly overseeing the overall master plan and development process. Howells works with the engineers, architects, and City to get approvals and his company maintains ownership after leasing. "So we're out there all the time," said Howells.
- 4. Are you aware of any community concerns regarding the Superfund Site, as it pertains to actions taken or underway to address environmental contamination? If so, please give details.** Howells said no one has ever approached him with any environmental concerns. From a leasing standpoint, Howells said they have standard disclosure language regarding the Site, and it's only come up once where a client was unable to lease a building based upon their company's policy. Maintaining ownership keeps any liability with their company as well.
- 5. Over the past five years, have there been any complaints, violations, or other incidents (e.g., vandalism, trespassing, or emergency responses) at or related to the Superfund Site requiring your office to respond? If so, please give details of the events and results of the response.** Nothing which is related to impacting the Superfund Site and the naturally monitored groundwater remedy. Howells said there is a trespassing history with transient or homelessness on their undeveloped properties which have required a considerable expense. Also, Howells said a

major issue with company vehicles having batteries removed or even stolen has occurred. Howells said the local police have been great to respond but have limitations going onto private property for the property owner to handle the issue.

6. **Do you feel well informed about the activities and progress over the last five years at the Superfund Site? Do you know how to contact the Environmental Protection Agency and/or UDEQ – DERR if you have questions or concerns about the Superfund Site?** Howells said when building a building on Site they contact DERR Project Managers first to discuss concepts and go over the management plan on the property to coordinate protocols, make sure contractors know about the monitoring wells and any hot spots within the Site footprint. Any hot spots are identified in case they dig in a suspect area, and work prescribes placing compromised soil back in the trench or haul it off Site. Howells said he's worked well with DERR Project Managers and knows the easement requirements and has no issues contacting DERR.
7. **Over the past five years, have there been any changes in your department's policies or regulations that might impact the Superfund Site from a perspective of land use, water rights, redevelopment, and site management? Any changes to your role? If so, please describe the changes and potential impact each might have.** Howells said any regulations he's familiar with haven't changed since Terramerica has developed property at the Site.
8. **Over the past five years, have there been any changes in land use surrounding the Superfund Site to your knowledge? Are you aware of potential future changes in land use? If so, please describe including any concerns you and/or your agency might have with land use changes.** Howells said land use has not changed from the Site's current M-1 industrial commercial use.
9. **Do you have any comments, suggestions, or recommendations regarding the Superfund Site management (for example, questions pertaining to institutional controls)? If you have questions or are aware of potential problems in the future, what problems might arise?** "No problems," said Howells, "working on this Site is unique and made getting the development off the ground challenging. We've been aware of the Site history forever and it wasn't a big deal. The biggest challenge might be educating tenants or lenders about the groundwater monitoring if they have any concerns, but we've been able to work through that and it just hasn't been an issue." Howells requested to be kept informed on any Site activities.

**Portland Cement (Kiln Dust 2 & 3) Superfund Site
Five-Year Review Interview**

Site Name: EPA ID: UTD980718670	March 31, 2022
Type of Contact: Phone	Contact Made By: Dave Allison, UDEQ/DERR Community Involvement Coordinator
Person Contacted	
Scott Swanger, Drainage Maintenance Supervisor	Salt Lake City Public Utilities Operations & Maintenance 1530 South West Temple Salt Lake City, Utah 84115

- 1. Is your organization/department aware of the Superfund Site and the actions taken/underway to address environmental contamination?** Scott Swanger is a Drainage Maintenance Supervisor and has worked for the Salt Lake Public Utilities Department for 31 years. Swanger said he doesn't know the extent of the Portland Cement Superfund Site history as the Site has remained the same since he has worked in the area. Public Utilities maintains the storm drain system throughout the City including the portion of the City Drain that runs through the middle of the former Superfund Site and what is known as the Redwood Road Industrial Depot. Swanger's department routinely cleans the drain and monitors for storm drain pollution, which is fed from runoff of streets, sidewalks, businesses, yards and gutters. Swanger's department also works to inform the public on keeping toxic and hazardous materials from running into storm drains and ultimately harming our water.
- 2. What's your overall impression (your general sentiment) of the actions taken/underway at the Superfund Site?** As a portion of the City Drain runs across the middle of the former cleanup Site, Swanger is only familiar with the location and condition of the drain at the Site. The drain (the City Drain – CWA-1) is unlined and on the ground or surface level and is 12 feet in depth in areas of the Site, initiating a few blocks away at 1700 West. Swanger said the drain does not release or leak water onto the property. Swanger said the drain is part of an intricate drainage system and a critical public service that protects both private and public property from water damage. Swanger said the drain has remained unchanged over the last five years and since he has worked on the Site. Swanger said to his knowledge, the City Drain does not contribute or affect groundwater conditions at the Site and is above the aquifer conditions monitored by UDEQ for arsenic.
- 3. Does your office conduct routine communications and/or activities (site visits, inspections, reporting activities, participation in meetings, etc.) which pertain to or involve the Superfund Site?** Swanger said his department mows weeds regularly along this portion of the drain, monthly during growing periods. No communications would be necessary unless a problem with the drain would occur.
- 4. Are you aware of any community concerns regarding the Superfund Site, as it pertains to actions taken or underway to address environmental contamination? If so, please give details.** Swanger said he has not heard of any health or environmental community concerns regarding the drain and the Superfund Site.
- 5. Over the past five years, have there been any complaints, violations, or other incidents (e.g., vandalism, trespassing, or emergency responses) at or related to the Superfund Site requiring your office to respond? If so, please give details of the events and results of the response.** Swanger said he is not aware of any incidents or emergency responses for this portion of the drain. Swanger says his department has dredged the drain four or five times over the last five years to keep the phragmites weeds down, even dredging to where the root balls start. They've also

had to pull construction debris out of the drain over the years but nothing requiring emergency measures over the last five years.

6. **Do you feel well informed about the activities and progress over the last five years at the Superfund Site? Do you know how to contact the Environmental Protection Agency and/or UDEQ – DERR if you have questions or concerns about the Superfund Site?** Swanger has not had any reason to contact the EPA or State regulators and has the UDEQ contact information provided during the Five-Year Review. Swanger said any communication to the EPA or UDEQ would probably come from SLC Managers, and he would have no problem notifying UDEQ if any issues related to the Site raised a concern regarding the drain.
7. **Over the past five years, have there been any changes in your department's policies or regulations that might impact the Superfund Site from a perspective of land use, water rights, redevelopment, and site management? Any changes to your role? If so, please describe the changes and potential impact each might have.** Swanger said there have not been any changes to the City Drain permit over the last five years and nothing which would affect groundwater conditions on Site.
8. **Over the past five years, have there been any changes in land use surrounding the Superfund Site to your knowledge? Are you aware of potential future changes in land use? If so, please describe including any concerns you and/or your agency might have with land use changes.** Swanger said the City Drain fills an important role for the drainage network system and he does not foresee any anticipated scenarios where the drain would be redirected or removed from the Site. Swanger said any development alterations may involve piping sections of the drain, which would have to be coordinated with construction permits and communicated with property managers. Construction digging or placement of the pipe may require coordination with UDEQ but Swanger can't imagine any drain alterations happening anytime soon.
9. **Do you have any comments, suggestions, or recommendations regarding the Superfund Site management (for example, questions pertaining to institutional controls)? If you have questions or are aware of potential problems in the future, what problems might arise?** Swanger offered any assistance his department could be regarding drain maintenance and its location on the former Superfund Site. Swanger did not have any recommendations and would want to be informed as necessary with any City Drain related developments.

APPENDIX E – ANALYTICAL RESULTS FOR GROUNDWATER AND SURFACE WATER

Shallow Aquifer Monitoring Well - PWEA								
	Analyte µg/L							
	pH	Arsenic	Cadmium	Chromium	Chromium 6	Lead	Manganese	Molybdenum
Cleanup Goals	<8.00	64	6.2	100	**	15	440	182
May-17	9.66	83	<10	<100	<5	<10	<25	3150
June-18	9.7	86.9	<10 U	<100 U	<5	<10 U	<25 U	2830
June-19	9.62	161 J	<10 U	<100 U	<5	<10 U	<50 U	6170 J
June-20	NS	NS	NS	NS	NS	NS	NS	NS
June-21	9.89	430	2.7	2.2	<5	1 UJ	9 J	9600

Shallow Aquifer Monitoring Well - PWBA								
	Analyte µg/L							
	pH	Arsenic	Cadmium	Chromium	Chromium 6	Lead	Manganese	Molybdenum
Cleanup Goals	<8.00	64	6.2	100	**	15	440	182
May-17	9.7	74.5	<10	<100	NA	<10	<25	1600
June-18	9.61	168	<10 U	<100 U	NA	<10 U	51.3	4850
June-19	9.66	70.1 J	<10 U	<100 U	NA	<10 U	<25 U	2140 J
June-20	NS	NS	NS	NS	NA	NS	NS	NS
June-21	9.72	73	0.37	3.8	NA	1 UJ	7.6 J	1600

Shallow Aquifer Monitoring Well - P2BA								
	Analyte µg/L							
	pH	Arsenic	Cadmium	Chromium	Chromium 6	Lead	Manganese	Molybdenum
Cleanup Goals	<8.00	64	6.2	100	**	15	440	182
May-17	8.39	<100	<10	<100	NA	14	<25	325
June-18	8.33	29.0 J	<10 U	<100 U	NA	<10 U	15.7 J	109
June-19	8.29	<100 UJ	<10 U	<100 U	NA	<10 U	33.7	150 J
June-20	NS	NS	NS	NS	NA	NS	NS	NS
June-21	8.32	7.3	0.2 U	0.53 J	NA	1 UJ	34 J	300

Shallow Aquifer Monitoring Well - P2FA								
	Analyte µg/L							
	pH	Arsenic	Cadmium	Chromium	Chromium 6	Lead	Manganese	Molybdenum
Cleanup Goals	<8.00	64	6.2	100	**	15	440	182
May-17	9.22	287	<10	160	76	<10	<25	81200
June-18	8.75	57.7	<5 U	<50 U	<5	<5 U	<25	6770
June-19	8.97	70.6 J	<10 U	<100 U	<5	<10 U	12 J	16800 J
June-20	NS	NS	NS	NS	NS	NS	NS	NS
June-21	9.22	35	7.4	5.6	<5	1 UJ	36 J	31000

µg/L Micro grams per Liter

NA Not Analyzed

NS Not Sampled

U Undetected

J Estimated positive result

UJ Undetected; the associated quantitation or reporting limit is considered to be an estimated value.

Note: Values are total concentrations

The OU3 ROD did not establish a cleanup goal for chromium 6 and values are provided for comparison purposes.

Shallow Aquifer Monitoring Well - P2HA								
	Analyte µg/L							
	pH	Arsenic	Cadmium	Chromium	Chromium 6	Lead	Manganese	Molybdenum
Cleanup Goals	<8.00	64	6.2	100	**	15	440	182
May-17	9.8	461	<10	<100	NA	<10	<25	14400
June-18	9.3	274	<10 U	<100 U	NA	<10 U	<25 U	21500
June-19	9.36	252 J	<10 U	<100 U	NA	<10 U	<25 U	20800 J
June-20	NS	NS	NS	NS	NA	NS	NS	NS
June-21	9.38	250	4.5	1.7 J	NA	1 UJ	20 J	8900

Shallow Aquifer Monitoring Well - P3BB								
	Analyte µg/L							
	pH	Arsenic	Cadmium	Chromium	Chromium 6	Lead	Manganese	Molybdenum
Cleanup Goals	<8.00	64	6.2	100	**	15	440	182
May-17	NS	NS	NS	NS	NA	NS	NS	NS
June-18	8.14	56.7	<1 U	<10 U	NA	<1 U	39.1	<5.00 U
June-19	8.48	48.2 J	<1 U	<10 U	NA	<1 U	40.8	<5.00 J
June-20	NS	NS	NS	NS	NA	NS	NS	NS
June-21	8.99	44	0.2 U	1.9 J	NA	1 UJ	130 J	420

Shallow Aquifer Monitoring Well - P3CC								
	Analyte µg/L							
	pH	Arsenic	Cadmium	Chromium	Chromium 6	Lead	Manganese	Molybdenum
Cleanup Goals	<8.00	64	6.2	100	**	15	440	182
May-17	9.98	790	<10.0	<100	<5	<10	<25	24400
June-18	NS	NS	NS	NS	NS	NS	NS	NS
June-19	NS	NS	NS	NS	NS	NS	NS	NS
June-20	NS	NS	NS	NS	NS	NS	NS	NS
June-21	9.99	1000	7.8	4.3	<5	1 UJ	29 J	31000

Shallow Aquifer Monitoring Well - P3DA								
	Analyte µg/L							
	pH	Arsenic	Cadmium	Chromium	Chromium 6	Lead	Manganese	Molybdenum
Cleanup Goals	<8.00	64	6.2	100	**	15	440	182
May-17	9.78	562	<10	<100	<5	<10	<25	5400
June-18	8.72	70.7	<2 U	11.2 J	<5	<2 U	28.7	131
June-19	NS	NS	NS	NS	NS	NS	NS	NS
June-20	NS	NS	NS	NS	NS	NS	NS	NS
June-21	8.51	110	0.37	6.7	<5	3 J+	48 J	1300

µg/L Micro grams per Liter

NA Not Analyzed

NS Not Sampled

U Undetected

J Estimated positive result

UJ Undetected; the associated quantitation or reporting limit is considered to be an estimated value.

Note: Values are total concentrations

The OU3 ROD did not establish a cleanup goal for chromium 6 and values are provided for comparison purposes.

Shallow Aquifer Monitoring Well - P3FA								
	Analyte µg/L							
	pH	Arsenic	Cadmium	Chromium	Chromium 6	Lead	Manganese	Molybdenum
Cleanup Goals	<8.00	64	6.2	100	**	15	440	182
May-17	10.1	868	<10	<100	<5	<10	20.6	7470
June-18	10	916	4.31 J	106	<10	165	3640	5150
June-19	9.77	572 J	3.42	41.4	<5	106	2070	2790 J
June-20	NS	NS	NS	NS	NS	NS	NS	NS
June-21	9.99	780	1 J-	16	<5	25 J	320 J	3200

Shallow Aquifer Monitoring Well - P3GB								
	Analyte µg/L							
	pH	Arsenic	Cadmium	Chromium	Chromium 6	Lead	Manganese	Molybdenum
Cleanup Goals	<8.00	64	6.2	100	**	15	440	182
May-17	8.48	<100	<10	<10	NA	<10	<25	202
June-18	8.4	<100 U	<10 U	<10 U	NA	<10 U	182	886
June-19	8.63	5.15 J	<1 U	<1 U	NA	<1 U	12.3 J	95.4 J
June-20	NS	NS	NS	NS	NA	NS	NS	NS
June-21	8.63	13	0.42	0.42	NA	1 UJ	16 J	1800

µg/L Micro grams per Liter

NA Not Analyzed

NS Not Sampled

U Undetected

J Estimated positive result

UJ Undetected; the associated quantitation or reporting limit is considered to be an estimated value.

Note: Values are total concentrations

The OU3 ROD did not establish a cleanup goal for chromium 6 and values are provided for comparison purposes.

Intermediate Aquifer Monitoring Well - PWS							
	Analyte µg/L						
	pH	Arsenic	Cadmium	Chromium	Lead	Manganese	Molybdenum
Cleanup Goals	<8.00	64	6.2	100	15	440	182
May-17	7.61	30.4	<10	<100	<10	30	<50
June-18	7.74	29.4	<1 U	<10 U	<1 U	25.5	<5 U
June-19	7.94	35.5 J	<1 U	<10 U	<1 U	45.2	<5 UJ
June-20	NS	NS	NS	NS	NS	NS	NS
June-21	8.13	35	0.2 U	0.53 J	1 UJ	33 J	10 U

Intermediate Aquifer Monitoring Well - P2M							
	Analyte µg/L						
	pH	Arsenic	Cadmium	Chromium	Lead	Manganese	Molybdenum
Cleanup Goals	<8.00	64	6.2	100	15	440	182
May-17	7.8	<100	<10	<100	<10	42.4	<50
June-18	7.8	25.6	<1 U	<10 U	<1 U	40.1	<5 U
June-19	7.87	24.8 J	<1 U	<10 U	<1 U	44.1	9.76 J
June-20	NS	NS	NS	NS	NS	NS	NS
June-21	7.91	28	0.34	0.43 J	1 UJ	42 J	10 U

Intermediate Aquifer Monitoring Well - P3EA							
	Analyte µg/L						
	pH	Arsenic	Cadmium	Chromium	Lead	Manganese	Molybdenum
Cleanup Goals	<8.00	64	6.2	100	15	440	182
May-17	7.93	33.5	<10	<100	<10	90.3	<50
June-18	8.31	45	<1 U	8.3 J	34.7	179	153
June-19	NS	NS	NS	NS	NS	NS	NS
June-20	NS	NS	NS	NS	NS	NS	NS
June-21	8.48	50	3.6	12 J	36 J	160 J	53

Intermediate Aquifer Monitoring Well - P3O							
	Analyte µg/L						
	pH	Arsenic	Cadmium	Chromium	Lead	Manganese	Molybdenum
Cleanup Goals	<8.00	64	6.2	100	15	440	182
May-17	8.16	32.7	<10	<100	<10	40.5	173
June-18	NS	NS	NS	NS	NS	NS	NS
June-19	8.44	30.8 J	<1 U	26.7	14.5	102	80.6 J
June-20	NS	NS	NS	NS	NS	NS	NS
June-21	8.17	29 J	0.2 U	1.8 J	1 UJ	44 J	54 J

µg/L Micro grams per Liter

NS Not Sampled

U Undetected

J Estimated positive result

UJ Undetected; the associated quantitation or reporting limit is considered to be an estimated value.

Note: Values are total concentrations

ACL Monitoring Well Dissolved Concentrations - P2FA													
	Analyte µg/L												
	Aluminum	Arsenic	Cadmium	Chromium	Chromium 6	Copper	Iron	Lead	Mercury	Nickel	Selenium	Silver	Zinc
ACL	4502.33	9832.68	139.08	26339.81	569.26	1564.50	25875.48	666.71	0.62	20667.94	258.75	6.21	13914.05
May-17	<250	274	7.76	297	NA	41.9	<1250	<10	NA	<50	169	<50	<100
June-18	179 J	35.8 J	<5 U	39.7 J	NA	<10 U	<1250 U	<5	NA	<50 U	<50 U	<25 U	<100 U
June-19	217 J	<100 U	<10 U	105	NA	14.5	<1250 U	<10 U	NA	NA	<100 U	<50	<100 U
June-20	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS
June-21	20 UJ	22	8	5.2	NA	1.8 J	24 J	1 UJ	0.2 U	11	5 U	0.18 J	4.9 J

ACL Monitoring Well Dissolved Concentrations - P3CC													
	Analyte µg/L												
	Aluminum	Arsenic	Cadmium	Chromium	Chromium 6	Copper	Iron	Lead	Mercury	Nickel	Selenium	Silver	Zinc
ACL	4502.33	9832.68	139.08	26339.81	569.26	1564.50	25875.48	666.71	0.62	20667.94	258.75	6.21	13914.05
May-17	<250	661	<10	138	NA	12.2	<1250	<10	NA	<50	<100	<50	<100
June-18	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS
June-19	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS
June-20	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS
June-21	20 UJ	1100	7.5	4.3	NA	2 J	52 J	1 UJ	0.2 U	6.3	5 U	1 U	4.4 J

ACL Monitoring Well Dissolved Concentrations - P3DA													
	Analyte µg/L												
	Aluminum	Arsenic	Cadmium	Chromium	Chromium 6	Copper	Iron	Lead	Mercury	Nickel	Selenium	Silver	Zinc
ACL	4502.33	9832.68	139.08	26339.81	569.26	1564.50	25875.48	666.71	0.62	20667.94	258.75	6.21	13914.05
May-17	<250	565	<10	<100	NA	<10	<1250	<10	NA	<50	<100	<50	<100
June-18	<250 U	73.3	<5 U	<50 U	NA	<10 U	<1250 U	<5	NA	<50 U	<50 U	<25 U	<100 U
June-19	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS
June-20	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS
June-21	260 J	100	0.32	2.6 J	NA	3.3 J	320 J	1.5 J	0.2 U	1.5 J	5 U	0.17 J	4.8 J

µg/L Micro grams per Liter

NA Not Analyzed

NS Not Sampled

U Undetected

J Estimated positive result

UJ Undetected; the associated quantitation or reporting limit is considered to be an estimated value.

Note: Values are dissolved concentrations

ACL Monitoring Well Dissolved Concentrations - P3FA													
	Analyte µg/L												
	Aluminum	Arsenic	Cadmium	Chromium	Chromium 6	Copper	Iron	Lead	Mercury	Nickel	Selenium	Silver	Zinc
ACL	4502.33	9832.68	139.08	26339.81	569.26	1564.50	25875.48	666.71	0.62	20667.94	258.75	6.21	13914.05
May-17	<250	863	<10	74.1	NA	<10	<1250	<10	NA	<50	<100	<50	<100
June-18	8960	767	<5 U	106	NA	<2 U	37500	19.3	NA	<10 U	<50 U	<25 U	165
June-19	<250 U	620	<2 U	61.2	NA	<10 U	<1250 U	<2 U	NA	NA	<20 U	<10 U	<100 U
June-20	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS
June-21	860 J	780	0.85	2.1 J	NA	7 J	1100 J	1.9 J+	0.2 U	12	13	0.17 J	8.3 J

ACL Monitoring Well Dissolved Concentraions - PWEA													
	Analyte µg/L												
	Aluminum	Arsenic	Cadmium	Chromium	Chromium 6	Copper	Iron	Lead	Mercury	Nickel	Selenium	Silver	Zinc
ACL	4502.33	9832.68	139.08	26339.81	569.26	1564.50	25875.48	666.71	0.62	20667.94	258.75	6.21	13914.05
May-17	258	77.9	<10	63.8	NA	<10	<1250	<10	NA	<50	<100	<50	<100
June-18	347	125	<10 U	80.4	NA	<10 U	<1250 U	<10 U	NA	<50 U	14.1 J	<50 U	<100 U
June-19	332 J	51.4 J	<10 U	91 J	NA	<20 U	<2500 U	<10 U	NA	NA	<100 U	<50 U	<200 U
June-20	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS
June-21	11 J	420	2.6	1.8 J	NA	3.3 J	32 J	1 UJ	0.2 U	17	5 U	0.23 J	9.2 J

ACL Alternate concentration limits

µg/L Micro grams per Liter

NA Not Analyzed

NS Not Sampled

U Undetected

J Estimated positive result

UJ Undetected; the associated quantitation or reporting limit is considered to be an estimated value.

Surface Water Sample Dissolved Concentrations - CDPOC														
		Analyte µg/L												
	pH	Aluminum	Arsenic	Cadmium	Chromium	Chromium 6	Copper	Iron	Lead	Mercury	Nickel	Selenium	Silver	Zinc
Performance Standard	8.13 - 11.25	180.75	187.5	0.3125	92.5	13.75	11.25	1250	3.13	0.01	65	5.75	2	150
May-17	8.16	77	143	<2	18.9	NA	6.97	<250	<2	NA	<10	<20	<10	<20
June-18	7.90	30.8 J	51	<2 U	23.1	NA	<2 U	<250 U	<2 U	NA	<10 U	<20 U	<10 U	<20 U
June-19	8.06	53.2	76.1	<2 U	26.3 J	NA	2.67	112 J	<2 U	NA	NA	<20 U	<10 U	<20 U
June-20	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS
June-21	8.29	19J	74	0.1 J	1 J	NA	3.4 J	67 J	1 UJ	0.2 U	4.5 J	5 U	0.29 J	7.6 J

Surface Water Sample Total Concentrations - CDPOC														
		Analyte µg/L												
	pH	Aluminum	Arsenic	Cadmium	Chromium	Chromium 6	Copper	Iron	Lead	Mercury	Nickel	Selenium	Silver	Zinc
May-17	8.16	112	146	<2	<20	<5	22.9	<1,250	<2.00	<0.1	<50	<20	<10	<100
June-18	7.90	309	52.0	<2 U	<20 U	<5	9.58	505	2.99	<0.1 U	<10 U	<20 U	<10 U	37.1
June-19	8.06	90.6	74.7	<2 U	<20 U	<5	6.23	256	1.18 J	<0.1 U	NA	<20 U	<10 U	12.2 J
June-20	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS
June-21	8.29	880	80	0.16 J	3.9 J	< 5	14	1300	7.3 J+	0.2 U	5.5	5 U	0.2 J	37

µg/L Micro grams per Liter

NA Not Analyzed

NS Not Sampled

U Undetected

J Estimated positive result

UJ Undetected; the associated quantitation or reporting limit is considered to be an estimated value

APPENDIX F – SITE INSPECTION PHOTOS



Commercial area along Bending River Road



Monitoring wells PWS and PWBA



City Drain adjacent to the Wallace Stagner Academy



City Drain POC sample location



Monitoring well P2CA



Damaged and broken monitoring well P2M



New Redwood Depot building

APPENDIX G – SITE INSPECTION CHECKLIST

FIVE-YEAR REVIEW SITE INSPECTION CHECKLIST															
I. SITE INFORMATION															
Site name: Portland Cement		Date of inspection: November 17, 2021													
Location and Region: Salt Lake County, UT Region 8		EPA ID: UTD980718670													
Agency, office, or company leading the five-year review: Utah Department of Environmental Quality Division of Environmental Response and Remediation		Weather/temperature: Clear/39° Fahrenheit													
Remedy Includes: (Check all that apply) <table style="width: 100%; border: none;"> <tr> <td><input checked="" type="checkbox"/> Landfill cover/containment</td> <td><input checked="" type="checkbox"/> Monitored natural attenuation</td> </tr> <tr> <td><input type="checkbox"/> Access controls</td> <td><input type="checkbox"/> Groundwater containment</td> </tr> <tr> <td><input checked="" type="checkbox"/> Institutional controls</td> <td><input type="checkbox"/> Vertical barrier walls</td> </tr> <tr> <td><input type="checkbox"/> Groundwater pump and treatment</td> <td></td> </tr> <tr> <td><input type="checkbox"/> Surface water collection and treatment</td> <td></td> </tr> <tr> <td><input type="checkbox"/> Other</td> <td></td> </tr> </table>				<input checked="" type="checkbox"/> Landfill cover/containment	<input checked="" type="checkbox"/> Monitored natural attenuation	<input type="checkbox"/> Access controls	<input type="checkbox"/> Groundwater containment	<input checked="" type="checkbox"/> Institutional controls	<input type="checkbox"/> Vertical barrier walls	<input type="checkbox"/> Groundwater pump and treatment		<input type="checkbox"/> Surface water collection and treatment		<input type="checkbox"/> Other	
<input checked="" type="checkbox"/> Landfill cover/containment	<input checked="" type="checkbox"/> Monitored natural attenuation														
<input type="checkbox"/> Access controls	<input type="checkbox"/> Groundwater containment														
<input checked="" type="checkbox"/> Institutional controls	<input type="checkbox"/> Vertical barrier walls														
<input type="checkbox"/> Groundwater pump and treatment															
<input type="checkbox"/> Surface water collection and treatment															
<input type="checkbox"/> Other															
Attachments: <input type="checkbox"/> Inspection team roster attached <input type="checkbox"/> Site map attached															
II. INTERVIEWS (Check all that apply)															
1. O&M site manager Name: _____ Title: _____ Date: _____ Interviewed <input type="checkbox"/> at site <input type="checkbox"/> at office <input type="checkbox"/> by phone Phone no. _____ Problems, suggestions; <input type="checkbox"/>															
2. O&M staff Name: _____ Title: _____ _____ Date Interviewed <input type="checkbox"/> at site <input type="checkbox"/> at office <input type="checkbox"/> by phone Phone no. _____ Problems, suggestions; <input type="checkbox"/>															
3. Local regulatory authorities and response agencies (i.e., State and Tribal offices, emergency response office, police department, office of public health or environmental health, zoning office, recorder of deeds, or other city and county offices, etc.) Fill in all that apply. Agency _____ Contact _____ <div style="display: flex; justify-content: space-between; margin-top: 10px;"> Name Title Date Phone no. </div> Problems; suggestions; <input type="checkbox"/> Report attached _____ _____															
4. Other interviews (optional) <input checked="" type="checkbox"/> Reports attached as Appendix D															
Individuals that were interviewed included personnel with Salt Lake City Public Utilities and Terramerica Corporation & Affiliates.															
III. ON-SITE DOCUMENTS & RECORDS VERIFIED (Check all that apply)															
1. O&M Documents <table style="width: 100%; border: none; margin-top: 10px;"> <tr> <td><input checked="" type="checkbox"/> O&M manual</td> <td><input checked="" type="checkbox"/> Readily available</td> <td><input checked="" type="checkbox"/> Up to date</td> <td><input type="checkbox"/> N/A</td> </tr> <tr> <td><input type="checkbox"/> As-built drawings</td> <td><input type="checkbox"/> Readily available</td> <td><input type="checkbox"/> Up to date</td> <td><input checked="" type="checkbox"/> N/A</td> </tr> <tr> <td><input type="checkbox"/> Maintenance logs</td> <td><input type="checkbox"/> Readily available</td> <td><input type="checkbox"/> Up to date</td> <td><input checked="" type="checkbox"/> N/A</td> </tr> </table> Remarks: _____				<input checked="" type="checkbox"/> O&M manual	<input checked="" type="checkbox"/> Readily available	<input checked="" type="checkbox"/> Up to date	<input type="checkbox"/> N/A	<input type="checkbox"/> As-built drawings	<input type="checkbox"/> Readily available	<input type="checkbox"/> Up to date	<input checked="" type="checkbox"/> N/A	<input type="checkbox"/> Maintenance logs	<input type="checkbox"/> Readily available	<input type="checkbox"/> Up to date	<input checked="" type="checkbox"/> N/A
<input checked="" type="checkbox"/> O&M manual	<input checked="" type="checkbox"/> Readily available	<input checked="" type="checkbox"/> Up to date	<input type="checkbox"/> N/A												
<input type="checkbox"/> As-built drawings	<input type="checkbox"/> Readily available	<input type="checkbox"/> Up to date	<input checked="" type="checkbox"/> N/A												
<input type="checkbox"/> Maintenance logs	<input type="checkbox"/> Readily available	<input type="checkbox"/> Up to date	<input checked="" type="checkbox"/> N/A												

2.	Site-Specific Health and Safety Plan	<input type="checkbox"/> Readily available	<input type="checkbox"/> Up to date	<input checked="" type="checkbox"/> N/A
	<input type="checkbox"/> Contingency plan/emergency response plan	<input type="checkbox"/> Readily available	<input type="checkbox"/> Up to date	<input checked="" type="checkbox"/> N/A
Remarks: _____				
3.	O&M and OSHA Training Records	<input type="checkbox"/> Readily available	<input type="checkbox"/> Up to date	<input checked="" type="checkbox"/> N/A
Remarks: _____				
4.	Permits and Service Agreements			
	<input type="checkbox"/> Air discharge permit	<input type="checkbox"/> Readily available	<input type="checkbox"/> Up to date	<input checked="" type="checkbox"/> N/A
	<input type="checkbox"/> Effluent discharge	<input type="checkbox"/> Readily available	<input type="checkbox"/> Up to date	<input checked="" type="checkbox"/> N/A
	<input type="checkbox"/> Waste disposal, POTW	<input type="checkbox"/> Readily available	<input type="checkbox"/> Up to date	<input checked="" type="checkbox"/> N/A
	<input type="checkbox"/> Other permits _____	<input type="checkbox"/> Readily available	<input type="checkbox"/> Up to date	<input checked="" type="checkbox"/> N/A
Remarks: _____				
5.	Gas Generation Records	<input type="checkbox"/> Readily available	<input type="checkbox"/> Up to date	<input checked="" type="checkbox"/> N/A
Remarks: _____				
6.	Settlement Monument Records	<input type="checkbox"/> Readily available	<input type="checkbox"/> Up to date	<input checked="" type="checkbox"/> N/A
Remarks: _____				
7.	Groundwater Monitoring Records	<input checked="" type="checkbox"/> Readily available	<input checked="" type="checkbox"/> Up to date	<input type="checkbox"/> N/A
Remarks: <u>UDEQ/DERR conducts annual groundwater monitoring and reports are provided to EPA.</u>				
8.	Leachate Extraction Records	<input type="checkbox"/> Readily available	<input type="checkbox"/> Up to date	<input checked="" type="checkbox"/> N/A
Remarks: _____				
9.	Discharge Compliance Records			
	<input type="checkbox"/> Air	<input type="checkbox"/> Readily available	<input type="checkbox"/> Up to date	<input checked="" type="checkbox"/> N/A
	<input type="checkbox"/> Water (effluent)	<input type="checkbox"/> Readily available	<input type="checkbox"/> Up to date	<input checked="" type="checkbox"/> N/A
Remarks: _____				
10.	Daily Access/Security Logs	<input type="checkbox"/> Readily available	<input type="checkbox"/> Up to date	<input checked="" type="checkbox"/> N/A
Remarks: _____				
IV. O&M COSTS				
1.	O&M Organization			
	<input type="checkbox"/> State in-house	<input type="checkbox"/> Contractor for State		
	<input type="checkbox"/> PRP in-house	<input type="checkbox"/> Contractor for PRP		
	<input type="checkbox"/> Federal Facility in-house	<input type="checkbox"/> Contractor for Federal Facility		
	<input type="checkbox"/> _____			

2. O&M Cost Records <input type="checkbox"/> Readily available <input type="checkbox"/> Up to date <input type="checkbox"/> Funding mechanism/agreement in place <input type="checkbox"/> Unavailable Original O&M cost estimate _____ <input type="checkbox"/> Breakdown attached Total annual cost by year for review period if available From <u>mm/dd/yyyy</u> To <u>mm/dd/yyyy</u> _____ <input type="checkbox"/> Breakdown attached Date Date Total cost From <u>mm/dd/yyyy</u> To <u>mm/dd/yyyy</u> _____ <input type="checkbox"/> Breakdown attached Date Date Total cost From <u>mm/dd/yyyy</u> To <u>mm/dd/yyyy</u> _____ <input type="checkbox"/> Breakdown attached Date Date Total cost From <u>mm/dd/yyyy</u> To <u>mm/dd/yyyy</u> _____ <input type="checkbox"/> Breakdown attached Date Date Total cost From <u>mm/dd/yyyy</u> To <u>mm/dd/yyyy</u> _____ <input type="checkbox"/> Breakdown attached Date Date Total cost			
3. Unanticipated or Unusually High O&M Costs During Review Period			
V. ACCESS AND INSTITUTIONAL CONTROLS <input checked="" type="checkbox"/> Applicable <input type="checkbox"/> N/A			
A. Fencing			
1. Fencing damaged <input type="checkbox"/> Location shown on site map <input type="checkbox"/> Gates secured <input checked="" type="checkbox"/> N/A Remarks: <u>The Site has been developed and is a commercial warehouse retail area.</u>			
B. Other Access Restrictions			
1. Signs and other security measures <input type="checkbox"/> Location shown on site map <input checked="" type="checkbox"/> N/A Remarks: _____			
C. Institutional Controls (ICs)			
1. Implementation and enforcement Site conditions imply ICs not properly implemented <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> N/A Site conditions imply ICs not being fully enforced <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> N/A Type of monitoring (e.g., self-reporting, drive by) <u>Routine Inspections</u> Frequency <u>Semiannual</u> Responsible party/agency <u>UDEQ/DERR</u> Contact <u>Tony Howes</u> <u>Environmental Scientist</u> <u>801-536-4100</u> Name Title Phone no. Reporting is up-to-date <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A Reports are verified by the lead agency <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A Specific requirements in deed or decision documents have been met <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A Violations have been reported <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A Other problems or suggestions: <input type="checkbox"/> Report attached			
2. Adequacy <input checked="" type="checkbox"/> ICs are adequate <input type="checkbox"/> ICs are inadequate <input type="checkbox"/> N/A Remarks: Land use easements that act as ICs are adequate and restrict groundwater use and provide procedures for managing contaminated soil that may be encountered during redevelopment activities.			
D. General			

1. Vandalism/trespassing <input type="checkbox"/> Location shown on site map <input checked="" type="checkbox"/> No vandalism evident Remarks:		
2. Land use changes on site <input type="checkbox"/> N/A Remarks: The site continues to be developed for commercial warehouse and retail use		
3. Land use changes off site <input checked="" type="checkbox"/> N/A Remarks:		
VI. GENERAL SITE CONDITIONS		
A. Roads <input checked="" type="checkbox"/> Applicable <input type="checkbox"/> N/A		
1. Roads damaged <input type="checkbox"/> Location shown on site map <input type="checkbox"/> Roads adequate <input checked="" type="checkbox"/> N/A Remarks: The Site has been developed and is accessible by city streets and parking areas		
B. Other Site Conditions		
Remarks:		
VII. LANDFILL COVERS <input checked="" type="checkbox"/> Applicable <input type="checkbox"/> N/A		
A. Landfill Surface		
1. Settlement (Low spots) <input type="checkbox"/> Location shown on site map <input checked="" type="checkbox"/> Settlement not evident Arial extent _____ Depth _____ Remarks: _____		
2. Cracks <input type="checkbox"/> Location shown on site map <input checked="" type="checkbox"/> Cracking not evident Lengths _____ Widths _____ Depths _____ Remarks: _____		
3. Erosion <input type="checkbox"/> Location shown on site map <input checked="" type="checkbox"/> Erosion not evident Arial extent _____ Depth _____ Remarks: _____		
4. Holes <input type="checkbox"/> Location shown on site map <input checked="" type="checkbox"/> Holes not evident Arial extent _____ Depth _____ Remarks: _____		
5. Vegetative Cover <input type="checkbox"/> Grass <input type="checkbox"/> Cover properly established <input type="checkbox"/> No signs of stress <input type="checkbox"/> Trees/Shrubs (indicate size and locations on a diagram) Remarks: <u>The Site has been developed and a vegetative grass cover is no longer needed</u>		
6. Alternative Cover (armored rock, concrete, etc.) <input checked="" type="checkbox"/> N/A Remarks: _____		
7. Bulges <input type="checkbox"/> Location shown on site map <input checked="" type="checkbox"/> Bulges not evident Arial extent _____ Height _____ Remarks: _____		
8. Wet Areas/Water Damage <input checked="" type="checkbox"/> Wet areas/water damage not evident <input type="checkbox"/> Wet areas <input type="checkbox"/> Location shown on site map Arial extent _____ <input type="checkbox"/> Ponding <input type="checkbox"/> Location shown on site map Arial extent _____ <input type="checkbox"/> Seeps <input type="checkbox"/> Location shown on site map Arial extent _____ <input type="checkbox"/> Soft subgrade <input type="checkbox"/> Location shown on site map Arial extent _____ Remarks: _____		
9. Slope Instability <input type="checkbox"/> Slides <input type="checkbox"/> Location shown on site map <input checked="" type="checkbox"/> No evidence of slope instability Arial extent _____ Remarks: _____		

B. Benches <input type="checkbox"/> Applicable <input checked="" type="checkbox"/> N/A (Horizontally constructed mounds of earth placed across a steep landfill side slope to interrupt the slope in order to slow down the velocity of surface runoff and intercept and convey the runoff to a lined channel.)			
1. Flows Bypass Bench	<input type="checkbox"/> Location shown on site map	<input type="checkbox"/> N/A or okay	
Remarks: _____			
2. Bench Breached	<input type="checkbox"/> Location shown on site map	<input type="checkbox"/> N/A or okay	
Remarks: _____			
3. Bench Overtopped	<input type="checkbox"/> Location shown on site map	<input type="checkbox"/> N/A or okay	
Remarks: _____			
C. Letdown Channels <input type="checkbox"/> Applicable <input checked="" type="checkbox"/> N/A			
1. Settlement (Low spots)	<input type="checkbox"/> Location shown on site map	<input type="checkbox"/> No evidence of settlement	
Arial extent _____		Depth _____	
Remarks: _____			
2. Material Degradation	<input type="checkbox"/> Location shown on site map	<input type="checkbox"/> No evidence of degradation	
Material type _____		Arial extent _____	
Remarks: _____			
3. Erosion	<input type="checkbox"/> Location shown on site map	<input type="checkbox"/> No evidence of erosion	
Arial extent _____		Depth _____	
Remarks: _____			
4. Undercutting	<input type="checkbox"/> Location shown on site map	<input type="checkbox"/> No evidence of undercutting	
Arial extent _____		Depth _____	
Remarks: _____			
5. Obstructions	Type _____	<input type="checkbox"/> No obstructions	
<input type="checkbox"/> Location shown on site map	Arial extent _____		
Size _____			
Remarks: _____			
6. Excessive Vegetative Growth	Type _____		
<input type="checkbox"/> No evidence of excessive growth			
<input type="checkbox"/> Vegetation in channels does not obstruct flow			
<input type="checkbox"/> Location shown on site map	Arial extent _____		
Remarks: _____			
D. Cover Penetrations <input type="checkbox"/> Applicable <input checked="" type="checkbox"/> N/A			
1. Gas Vents	<input type="checkbox"/> Active	<input type="checkbox"/> Passive	
<input type="checkbox"/> Properly secured/locked	<input type="checkbox"/> Functioning	<input type="checkbox"/> Routinely sampled	<input type="checkbox"/> Good condition
<input type="checkbox"/> Evidence of leakage at penetration		<input type="checkbox"/> Needs Maintenance	<input checked="" type="checkbox"/> N/A
Remarks: _____			
2. Gas Monitoring Probes	<input type="checkbox"/> Functioning	<input type="checkbox"/> Good condition	
<input type="checkbox"/> Properly secured/locked		<input type="checkbox"/> Routinely sampled	
<input type="checkbox"/> Evidence of leakage at penetration		<input type="checkbox"/> Needs maintenance	<input checked="" type="checkbox"/> N/A
Remarks: _____			

3. Monitoring Wells (within surface area of landfill)			
<input checked="" type="checkbox"/> Properly secured/locked	<input checked="" type="checkbox"/> Functioning	<input checked="" type="checkbox"/> Routinely sampled	<input checked="" type="checkbox"/> Good condition
<input type="checkbox"/> Evidence of leakage at penetration		<input type="checkbox"/> Needs Maintenance	<input type="checkbox"/> N/A
Remarks: <u>The protective steel "stick up" casing and PVC casing for monitoring well P2M were damaged and broken at the ground surface.</u>			
4. Extraction Wells Leachate			
<input type="checkbox"/> Properly secured/locked	<input type="checkbox"/> Functioning	<input type="checkbox"/> Routinely sampled	<input type="checkbox"/> Good condition
<input type="checkbox"/> Evidence of leakage at penetration		<input type="checkbox"/> Needs Maintenance	<input checked="" type="checkbox"/> N/A
Remarks: _____			
5. Settlement Monuments			
<input type="checkbox"/> Located	<input type="checkbox"/> Routinely surveyed	<input checked="" type="checkbox"/> N/A	
Remarks: _____			
E. Gas Collection and Treatment			
		<input type="checkbox"/> Applicable	<input checked="" type="checkbox"/> N/A
1. Gas Treatment Facilities			
<input type="checkbox"/> Flaring	<input type="checkbox"/> Thermal destruction	<input type="checkbox"/> Collection for reuse	
<input type="checkbox"/> Good condition	<input type="checkbox"/> Needs Maintenance		
Remarks: _____			
2. Gas Collection Wells, Manifolds and Piping			
<input type="checkbox"/> Good condition	<input type="checkbox"/> Needs Maintenance		
Remarks: _____			
3. Gas Monitoring Facilities (e.g., gas monitoring of adjacent homes or buildings)			
<input type="checkbox"/> Good condition	<input type="checkbox"/> Needs Maintenance	<input type="checkbox"/> N/A	
Remarks: _____			
F. Cover Drainage Layer			
		<input type="checkbox"/> Applicable	<input checked="" type="checkbox"/> N/A
1. Outlet Pipes Inspected			
<input type="checkbox"/> Functioning	<input type="checkbox"/> N/A		
Remarks: _____			
2. Outlet Rock Inspected			
<input type="checkbox"/> Functioning	<input type="checkbox"/> N/A		
Remarks: _____			
G. Detention/Sedimentation Ponds			
		<input type="checkbox"/> Applicable	<input checked="" type="checkbox"/> N/A
1. Siltation			
Area extent _____	Depth _____	<input type="checkbox"/> N/A	
<input type="checkbox"/> Siltation not evident			
Remarks: _____			
2. Erosion			
Area extent _____	Depth _____		
<input type="checkbox"/> Erosion not evident			
Remarks: _____			
3. Outlet Works			
<input type="checkbox"/> Functioning	<input type="checkbox"/> N/A		
Remarks: _____			
4. Dam			
<input type="checkbox"/> Functioning	<input type="checkbox"/> N/A		
Remarks: _____			
H. Retaining Walls			
		<input type="checkbox"/> Applicable	<input checked="" type="checkbox"/> N/A
1. Deformations			
<input type="checkbox"/> Location shown on site map		<input type="checkbox"/> Deformation not evident	
Horizontal displacement _____	Vertical displacement _____		
Rotational displacement _____			
Remarks: _____			
2. Degradation			
<input type="checkbox"/> Location shown on site map		<input type="checkbox"/> Degradation not evident	
Remarks: _____			

I. Perimeter Ditches/Off-Site Discharge		<input checked="" type="checkbox"/> Applicable	<input type="checkbox"/> N/A
1. Siltation	<input type="checkbox"/> Location shown on site map	<input checked="" type="checkbox"/> Siltation not evident	
Area extent _____		Depth _____	
Remarks: _____			
2. Vegetative Growth	<input type="checkbox"/> Location shown on site map	<input type="checkbox"/> N/A	
<input checked="" type="checkbox"/> Vegetation does not impede flow			
Area extent _____		Type _____	
Remarks: _____			
3. Erosion	<input type="checkbox"/> Location shown on site map	<input checked="" type="checkbox"/> Erosion not evident	
Area extent _____		Depth _____	
Remarks: _____			
4. Discharge Structure	<input checked="" type="checkbox"/> Functioning	<input type="checkbox"/> N/A	
Remarks: <u>The shallow aquifer discharges to the city drain. The city drain was observed to be flowing and functioning as intended.</u>			
VIII. VERTICAL BARRIER WALLS		<input type="checkbox"/> Applicable	<input checked="" type="checkbox"/> N/A
1. Settlement	<input type="checkbox"/> Location shown on site map	<input type="checkbox"/> Settlement not evident	
Area extent _____		Depth _____	
Remarks: _____			
2. Performance Monitoring	Type of monitoring _____		
<input type="checkbox"/> Performance not monitored			
Frequency _____		<input type="checkbox"/> Evidence of breaching	
Head differential _____			
Remarks: _____			
IX. GROUNDWATER/SURFACE WATER REMEDIES		<input checked="" type="checkbox"/> Applicable	<input type="checkbox"/> N/A
A. Groundwater Extraction Wells, Pumps, and Pipelines		<input type="checkbox"/> Applicable	<input checked="" type="checkbox"/> N/A
1. Pumps, Wellhead Plumbing, and Electrical			
<input type="checkbox"/> Good condition	<input type="checkbox"/> All required wells properly operating	<input type="checkbox"/> Needs Maintenance	<input type="checkbox"/> N/A
Remarks: _____			
2. Extraction System Pipelines, Valves, Valve Boxes, and Other Appurtenances			
<input type="checkbox"/> Good condition	<input type="checkbox"/> Needs Maintenance		
Remarks: _____			
3. Spare Parts and Equipment			
<input type="checkbox"/> Readily available	<input type="checkbox"/> Good condition	<input type="checkbox"/> Requires upgrade	<input type="checkbox"/> Needs to be provided
Remarks: _____			
B. Surface Water Collection Structures, Pumps, and Pipelines		<input type="checkbox"/> Applicable	<input checked="" type="checkbox"/> N/A
1. Collection Structures, Pumps, and Electrical			
<input type="checkbox"/> Good condition	<input type="checkbox"/> Needs Maintenance		
Remarks: _____			
2. Surface Water Collection System Pipelines, Valves, Valve Boxes, and Other Appurtenances			
<input type="checkbox"/> Good condition	<input type="checkbox"/> Needs Maintenance		
Remarks: _____			
3. Spare Parts and Equipment			
<input type="checkbox"/> Readily available	<input type="checkbox"/> Good condition	<input type="checkbox"/> Requires upgrade	<input type="checkbox"/> Needs to be provided
Remarks: _____			
C. Treatment System		<input type="checkbox"/> Applicable	<input checked="" type="checkbox"/> N/A

<p>1. Treatment Train (Check components that apply)</p> <div style="display: flex; flex-wrap: wrap;"> <div style="width: 33%;"><input type="checkbox"/> Metals removal</div> <div style="width: 33%;"><input type="checkbox"/> Oil/water separation</div> <div style="width: 33%;"><input type="checkbox"/> Bioremediation</div> <div style="width: 33%;"><input type="checkbox"/> Air stripping</div> <div style="width: 33%;"><input type="checkbox"/> Carbon absorbers</div> <div style="width: 33%;"><input type="checkbox"/> Filters _____</div> <div style="width: 33%;"><input type="checkbox"/> Additive (e.g., chelation agent, flocculent) _____</div> <div style="width: 33%;"><input type="checkbox"/> Others _____</div> <div style="width: 33%;"><input type="checkbox"/> Good condition</div> <div style="width: 33%;"><input type="checkbox"/> Needs Maintenance</div> <div style="width: 33%;"><input type="checkbox"/> Sampling ports properly marked and functional</div> <div style="width: 33%;"><input type="checkbox"/> Sampling/maintenance log displayed and up to date</div> <div style="width: 33%;"><input type="checkbox"/> Equipment properly identified</div> <div style="width: 33%;"><input type="checkbox"/> Quantity of groundwater treated annually _____</div> <div style="width: 33%;"><input type="checkbox"/> Quantity of surface water treated annually _____</div> </div> <p>Remarks: _____</p>
<p>2. Electrical Enclosures and Panels (properly rated and functional)</p> <div style="display: flex; justify-content: space-between;"> <input type="checkbox"/> N/A <input type="checkbox"/> Good condition <input type="checkbox"/> Needs Maintenance </div> <p>Remarks: _____</p>
<p>3. Tanks, Vaults, Storage Vessels</p> <div style="display: flex; justify-content: space-between;"> <input type="checkbox"/> N/A <input type="checkbox"/> Good condition <div style="text-align: center;"> <input type="checkbox"/> Proper secondary containment </div> <input type="checkbox"/> Needs Maintenance </div> <p>Remarks: _____</p>
<p>4. Discharge Structure and Appurtenances</p> <div style="display: flex; justify-content: space-between;"> <input type="checkbox"/> N/A <input type="checkbox"/> Good condition <input type="checkbox"/> Needs Maintenance </div> <p>Remarks: _____</p>
<p>5. Treatment Building(s)</p> <div style="display: flex; justify-content: space-between;"> <input type="checkbox"/> N/A <input type="checkbox"/> Good condition (esp. roof and doorways) <input type="checkbox"/> Needs repair </div> <p><input type="checkbox"/> Chemicals and equipment properly stored</p> <p>Remarks: _____</p>
<p>6. Monitoring Wells (pump and treatment remedy)</p> <div style="display: flex; justify-content: space-between;"> <input type="checkbox"/> Properly secured/locked <input type="checkbox"/> Functioning <div style="text-align: center;"> <input type="checkbox"/> Routinely sampled </div> <input type="checkbox"/> Good condition </div> <div style="display: flex; justify-content: space-between; margin-top: 10px;"> <input type="checkbox"/> All required wells located <input type="checkbox"/> Needs Maintenance <input type="checkbox"/> N/A </div> <p>Remarks: _____</p>
<p>D. Monitoring Data</p>
<p>1. Monitoring Data</p> <div style="display: flex; justify-content: space-between;"> <input checked="" type="checkbox"/> Is routinely submitted on time <input checked="" type="checkbox"/> Is of acceptable quality </div>
<p>2. Monitoring data suggests:</p> <div style="display: flex; justify-content: space-between;"> <input checked="" type="checkbox"/> Groundwater plume is effectively contained <input type="checkbox"/> Contaminant concentrations are declining </div>
<p>E. Monitored Natural Attenuation</p>
<p>1. Monitoring Wells (natural attenuation remedy)</p> <div style="display: flex; justify-content: space-between;"> <input checked="" type="checkbox"/> Properly secured/locked <input checked="" type="checkbox"/> Functioning <div style="text-align: center;"> <input checked="" type="checkbox"/> Routinely sampled </div> <div style="text-align: center;"> <input checked="" type="checkbox"/> Good condition </div> </div> <div style="display: flex; justify-content: space-between; margin-top: 10px;"> <input type="checkbox"/> All required wells located <input type="checkbox"/> Needs Maintenance <input type="checkbox"/> N/A </div> <p>Remarks: <u>With the exception monitoring well P2M in which the protective steel “stick up” casing and PVC casing were damaged and broken at the ground surface, monitoring wells were found to be in good condition.</u></p>
<p>X. OTHER REMEDIES</p>

If there are remedies applied at the site and not covered above, attach an inspection sheet describing the physical nature and condition of any facility associated with the remedy. An example would be soil vapor extraction.

XI. OVERALL OBSERVATIONS

A. Implementation of the Remedy

The remedy for OU1 and OU2 is complete and consisted of removing and disposing of the CKD and chromium bearing bricks which were the source material for groundwater contamination at the Site. A series of groundwater monitoring wells were installed at the Site to ensure that groundwater RAOs are being achieved.

B. Adequacy of O&M

Annual groundwater and surface water monitoring and sampling is completed at the Site by UDEQ/DERR. Groundwater and surface water monitoring and sampling ensures that contaminated groundwater is not migrating to unprotected groundwater and surface water. An optimization review completed in February 2022 by EPA found that the current number of existing monitoring wells is adequate for evaluating the groundwater remedy.

C. Early Indicators of Potential Remedy Problems

None

D. Opportunities for Optimization

Not applicable at this time.