THIRD FIVE-YEAR REVIEW REPORT FOR RICHARDSON FLAT TAILINGS SUPERFUND SITE SUMMIT COUNTY, UTAH



Prepared by

U.S. Environmental Protection Agency Region 8 Denver, Colorado

BEN BIELENBERG Discussion 2023.09.26 08:25:58 -06'00'

Ben Bielenberg, Acting Director Superfund and Emergency Management Division

Table of Contents

LIST OF ABBREVIATIONS AND ACRONYMS	iv
I. INTRODUCTION	
Site Background	
FIVE-YEAR REVIEW SUMMARY FORM	3
II. RESPONSE ACTION SUMMARY	6
Basis for Taking Action	6
Response Actions	6
Status of Implementation	
Systems Operations/Operation and Maintenance (O&M)	11
III. PROGRESS SINCE THE PREVIOUS REVIEW	11
IV. FIVE-YEAR REVIEW PROCESS	
Community Notification, Community Involvement and Site Interviews	11
Data Review	
Site Inspection	
V. TECHNICAL ASSESSMENT	
QUESTION A: Is the remedy functioning as intended by the decision documents?	
QUESTION B: Are the exposure assumptions, toxicity data, cleanup levels and remedial action	
(RAOs) used at the time of the remedy selection still valid?	
QUESTION C: Has any other information come to light that could call into question the protect	ctiveness of the
remedy?	
VI. ISSUES/RECOMMENDATIONS	
OTHER FINDINGS	
VII. PROTECTIVENESS STATEMENT	
VIII. NEXT REVIEW	
APPENDIX A – REFERENCE LIST	
APPENDIX B – SITE CHRONOLOGY	
APPENDIX C – SITE MAPS	
APPENDIX D – PRESS NOTICE	
APPENDIX E – INTERVIEW FORMS	
APPENDIX F – SITE INSPECTION CHECKLIST	
APPENDIX G - SITE INSPECTION PHOTOS	G-1

Tables

Table 1: Summary of Planned and/or Implemented Institutional Controls (ICs)	9
Table 2: Protectiveness Determinations/Statements from the 2018 FYR	
Table 3: Status of Recommendations from the 2018 FYR	11
Table B-1: Site Chronology	B-1

Figures

Figure 1: Site Vicinity Map	4
Figure 2: Site Map	
Figure 3: Property Parcel Map	10
Figure C-1: Remedial Design Task Areas	.C-1

Figure C-2: 2008 Phase 2 Completion Map	C-2
Figure C-3: 2009 Phase 3 Completion Map	C-3
Figure C-4: 2010 Phase 4 Completion Map	C-4
Figure C-5: 2011 Phase 5 Completion Map	C-5

LIST OF ABBREVIATIONS AND ACRONYMS

ARAR CERCLA	Applicable or Relevant and Appropriate Requirement Comprehensive Environmental Response, Compensation, and Liability Act
CFR	Code of Federal Regulations
CIC	Community Involvement Coordinator
EPA	United States Environmental Protection Agency
FYR	Five-Year Review
IC	Institutional Control
LHM	Larry H Miller
µg/dL	micrograms per deciliter
mg/kg	Milligrams per Kilogram
NCP	National Contingency Plan
NPL	National Priorities List
O&M	Operation and Maintenance
OU	Operable Unit
PCV	Park City Ventures
RAO	Remedial Action Objective
RI	Remedial Investigation
ROD	Record of Decision
RPM	Remedial Project Manager
UPCM	United Park City Mines
UDEQ	Utah Department of Environmental Quality
UU/UE	Unlimited Use and Unrestricted Exposure
	······································

I. INTRODUCTION

The purpose of a five-year review (FYR) is to evaluate the implementation and performance of a remedy to determine if the remedy is and will continue to be protective of human health and the environment. The methods, findings and conclusions of reviews are documented in FYR reports such as this one. In addition, FYR reports identify issues, if any, found during the review and document recommendations to address them.

The U.S. Environmental Protection Agency (EPA) is preparing this FYR pursuant to the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA) Section 121, consistent with the National Oil and Hazardous Substances Pollution Contingency Plan (NCP) (40 Code of Federal Regulations (CFR) Section 300.430(f)(4)(ii)) and considering EPA policy.

This is the third FYR for the Richardson Flat Tailings Superfund site (Site). The triggering action for this statutory review is the completion date of the previous FYR. This FYR has been prepared because hazardous substances, pollutants or contaminants remain at the Site above levels that allow for unlimited use and unrestricted exposure (UU/UE).

The Site consists of four operable units (OUs) (Figure 1). This FYR addresses OU1, the Richardson Flat tailings impoundment (Figure 2). Remedial action has occurred at OU1, as discussed in Section II below. Site characterization investigations are ongoing at the remaining OUs. OU2 encompasses approximately 1,216 acres along Lower Silver Creek north and east of Highway 40. OU3 encompasses approximately 856 acres east of Park City in areas along Silver Creek. These two OUs are comprised of mine tailings that have come to be located in the Lower Silver Creek floodplain. Investigations to determine the nature and extent of contamination in the floodplain and upland areas are ongoing. OU4 is an ongoing discharge known as Prospector Drain. Investigations to determine the nature and extent of contamination at OU4 are ongoing.

EPA remedial project manager (RPM) James Hou led the FYR. Participants included EPA community involvement coordinator Katherine Jenkins, then Utah Department of Environmental Quality (UDEQ) project manager Doug Bacon, UDEQ community involvement coordinator Dave Allison, and Ryan Burdge from Skeo (EPA FYR support contractor). The review began on 7/14/2022.

Appendix A includes a list of documents reviewed as part of this FYR. Appendix B provides a site chronology of events.

The EPA has determined in the five-year review that the cleanup at Operable Unit 1 of the Richardson Flat Tailings Superfund site is protective in the short term. This means the remedy is currently protective of human health and the environment. In order for the remedy to be protective in the long term, restrictions on future use and development of the waste area are needed, as well as a documented plan for long-term maintenance of the waste area.

Site Background

The Site is located in and around Park City in Summit County, Utah, in the Silver Creek watershed (Figure 1). OU1 consists of approximately 258 acres of land, including a 160-acre tailings impoundment, and is located southeast of the junction of U.S. Highway 40 and Utah Highway 248 (Figure 2). The OU1 area is part of a 650-acre property previously owned by United Park City Mines (UPCM) Company.

Mining activities began in the upgradient mining district in the late 1860s. In total, approximately seven million tons of tailings lie within OU1. The OU1 impoundment was a mine tailings reservoir created prior to 1950. In 1970, with renewed mining activity in the area, Park City Ventures (PCV) entered into a lease agreement with UPCM allowing PCV to deposit additional mine tailings at the OU1 impoundment. To accommodate additional tailings, PCV built a large embankment along the western edge of the impoundment and containment dike structures along the southern and eastern borders. PCV also created a diversion ditch system along the higher

slopes north of the impoundment and outside of the containment dikes, along the east and south perimeters of the impoundment, to collect surface runoff. Over the course of PCV's use of the Site, about 450,000 additional tons of tailings were deposited at OU1. From 1979 to 1982, Noranda Mining, Inc. leased the mining and milling operations and placed an additional 70,000 tons of tailings at OU1.

Most of OU1 is a covered tailings impoundment bounded by containment dikes with the main embankment to the northwest (Figure 2). A parking area, Richardson Flat Park and Ride, and bus stop are at the east end of OU1. The parking area is subject to a 99-year lease to Park City. A recreation trail crosses the Site along Silver Creek.

Most of the land around OU1 is undeveloped open space, although there is development interest in the Silver Creek valley in the general area of OU1. Surface water features at OU1 include the south diversion ditch, the wetlands area below the embankment, and a pond (Figure 2). All the surface water and shallow groundwater at OU1 eventually discharges to Silver Creek. Silver Creek flows along the northwest border of OU1 and is classified by the state of Utah (State) as a potential drinking water source, a recreational use feature, a cold-water fishery and a potential irrigation source.

The shallow groundwater at OU1 is generally associated with the alluvial system of Silver Creek. The Silver Creek alluvial aquifer is high in total dissolved solids and is often contaminated due to water quality in Silver Creek and tailings that are present along the creek in many areas. The OU1 remedial investigation (RI) found the soil cover protects groundwater and other media at the Site from becoming heavily contaminated. On the surface, the soils used to cover the tailings function as a nearly impermeable cap, effectively preventing infiltration of surface water into the tailings. The tailings are effectively encapsulated, above and below, by low-permeability, clay-rich soil.


A diversion ditch serves as a barrier to both surface water and shallow groundwater and captures water that flows toward the impoundment. The captured water is channeled around the impoundment, through a small retention pond, and into the small wetland at the foot of the main embankment where it mixes with water from Silver Creek and the small amount of water seeping through the embankment. All of this water is eventually used by plants in the wetland or flows north away from the Site as surface water or shallow groundwater in the alluvium of Silver Creek. Flow in the alluvial groundwater system mimics the local topography. Groundwater flow is generally toward the wetlands south of the tailings impoundment. Groundwater beneath the clay-rich topsoil moves from northeast to southwest and is eventually captured by the south diversion ditch. Groundwater stored in the tailings impoundment moves northwesterly toward the embankment under a relatively flat hydraulic gradient.

A 12-square-mile downgradient groundwater well inventory conducted during the RI determined that area drinking-water wells are finished in the deeper consolidated sedimentary rocks (deeper than 150 feet) and there are no known wells located within a half-mile of OU1. The shallow groundwater at OU1 is generally associated with the alluvial system of Silver Creek. This water is very high in solids and is also often contaminated due to water quality in Silver Creek and tailings that are present along the Creek in many areas. There are no known uses for the shallow aquifer.

FIVE-YEAR REVIEW SUMMARY FORM

SITE IDENTIFICATION					
Site Name: Richardson F	Flat Tailings	5			
EPA ID: UTD98095284	0				
Region: 8	State: Uta	ıh	City/County: Park City/Summit		
		SI	TE STATUS		
NPL Status: Proposed					
Multiple OUs? Yes		Has the No	Site achieved construction completion?		
		REV	IEW STATUS		
Lead agency: EPA					
Author name: James Hou with contractor support provided by Skeo					
Author affiliation: EPA Region 8 and Skeo					
Review period: 10/18/2022 - 8/10/2023					
Date of site inspection: 10/12/2023					
Type of review: Statutory					
Review number: 3					
Triggering action date: 8/10/2018					
Due date (five years after triggering action date): 8/10/2023					

Figure 1: Site Vicinity Map



N Richardson Flat Tailings Superfund Site Park City, Summit County, Utah Disclaimer: This map and any boundary lines within the map are approximate and subject to change. The map is not a survey. The map is for informational purposes only regarding EPA's response actions at the Site. Map image is the intellectual property of Esri and is used herein under license. Copyright © 2020 Esri and its licensors. All rights reserved. Sources: Earthstar Geographics and the 2018 FYR.



Figure 2: Site Map

1,000

1,500

2,000 Feet

500



5

Last Modified: 10/5/2022

II. RESPONSE ACTION SUMMARY

Basis for Taking Action

The EPA began initial site assessments in 1984. High-volume air sampling at OU1 in 1986 found that wind-borne arsenic, cadmium, lead and zinc had been released to the air from the tailings. The EPA originally proposed the Site for listing on the National Priorities List (NPL) in 1988. After considering public comment, the EPA revised the hazard ranking score for the Site, and removed the Site from NPL consideration in 1991. By 1992, the Hazard Ranking System had been revised, and the EPA again proposed the Site for listing on the NPL. The Site remains proposed for NPL listing.

During the 1990s, UPCM completed voluntary work at OU1, including covering most of the tailings pile with clean, low-permeability soil and reseeding the Site and improving the diversion ditch. In September 2000, the EPA and UPCM signed an Administrative Order on Consent requiring UPCM to conduct an RI and focused feasibility study for OU1. Sampling confirmed contamination with heavy metals, primarily zinc, lead and arsenic in the sediments and surface water of the south diversion ditch, the on-site wetland, and Silver Creek.

OU1's 2003 baseline human health risk assessment characterized the risk to low and high intensity recreational users through exposure to the COCs at the Site. Lead exposure in surface soils was evaluated using the Integrated Exposure, Uptake and Biokinetic model for children and the Bower's model for adult receptors. Both models predicted blood lead levels below the EPA's health-based goal of a 5% probability of exceeding a blood lead level of 10//g/dL for all recreational use scenarios. The EPA deemed remedial action was necessary to maintain and improve the soil cover placed on the tailings and to prevent disturbances to the soil cover that could allow for exposure to the underlying tailings.

The ecological risk assessment identified substantial risks to ecological receptors at OU1 from exposure to zinc, cadmium, lead and arsenic. Exposure pathways included direct contact with the sediments in the south diversion ditch and the wetlands area. These exposure areas also presented risks to ecological receptors through contact or ingestion of surface water and sediment porewater found at the Site.

Response Actions

The EPA selected the final OU1 remedy in the Site's 2005 Record of Decision (ROD). To address existing and potential risks, as well as to accommodate the anticipated future recreational and ecological use of OU1, the EPA developed nine remedial action objectives (RAOs):

- Reduce risks to wildlife receptors in the wetland area and south diversion ditch such that hazard indexes for lead are less than or equal to 1.
- Ensure that recreational users, including children, continue to have no more than a five percent chance of exceeding a blood lead level of 10 micrograms per deciliter (μ g/dL) from exposure to lead in soils.
- Ensure that recreational users, including children, continue to have no more than 1 x 10⁻⁴ chance of contracting cancer from exposure to arsenic in soils.
- Eliminate the risk of catastrophic failure of the tailings impoundment.
- Ensure that surface water discharged from the Site meets applicable Utah water quality standards.
- Eliminate the possibility of future groundwater use and withdrawal at the Site.
- Allow for a variety of future recreational uses.
- Allow for future disposal of mine tailings from the Park City area within the tailings impoundment until the remedy is complete.
- Minimize post-cleanup disturbance of tailings and contaminated soil. Provide controls that ensure any necessary disturbance at the Site follows prescribed methods.

The selected remedy addressed mine tailings located in several areas of OU1, including the main impoundment, a section south of the diversion ditch, and the wetlands below the embankment. Other media addressed through the selected remedy were sediments and surface water within the OU1 boundary.

Major components of the remedy include:

- Excavating tailings in critical areas outside the impoundment and placing tailings inside the impoundment.
- Augmenting the soil cover to achieve a depth of at least 18 inches of soil above tailings. As an additional measure, no soils with concentrations greater than 500 milligram per kilogram (mg/kg) of lead will be left exposed. The 500 mg/kg level is below any calculated preliminary remediation goals for recreational uses.
- Allowing for placement of additional mine waste from the Silver Creek watershed within the impoundment that, upon completion, will require 18 inches of cover.
- Covering sediments in diversion ditch with clean fill.
- Excavating contaminated sediments and soils in the wetland below the embankment and place sediments inside the impoundment. A sediment remediation goal of 310 mg/kg lead was established.
 - The 310 mg/kg value is an ecological goal based on a low-end threshold toxicity reference value from the species sensitivity distribution for all birds. The EPA expected that attainment of this numerical level would reduce hazard indices for lead in sediment to less than 1.0.
- Fortifying the existing embankment to prevent catastrophic failure.
- Implementing institutional controls (easements and land-use restrictions) to protect soil cover and prevent groundwater use.
- Monitoring surface water.

The OU1 RI Report concluded that OU1 does not present a risk to off-site groundwater due to a confining layer below contaminated groundwater that limits migration to deeper aquifers. Groundwater use at the Site will be restricted through institutional controls to ensure no unacceptable exposures.

Status of Implementation

UPCM initiated the OU1 remedial design in August 2007 and completed it in October 2007. Remedial action began in February 2008. Remedy construction at OU1 performed by UPCM, with EPA oversight, included consolidating tailings material within the main impoundment, installing a wedge buttress to support the main embankment, and removing sediments in the wetland area. The remedial activities occurred in a phased approach based on the tasks described in the remedial design (Figure C-1 in Appendix C). In 2011, UPCM completed planned construction activities for OU1 except for the additional cover material in certain locations where there is currently only a temporary cover.

The main embankment fortification consisted of constructing a wedge buttress in 2008 in accordance with a 2001 slope stability evaluation. From 2008 to 2011, all tailings in critical areas outside the impoundment were excavated and moved inside the impoundment (see Appendix C for maps of removal areas). Approximately 46,000 cubic yards of contaminated material were removed from the embankment wetland. Wetland restoration consisted of grading and revegetation with appropriate plant species. As required by the Site's Remedial Design/Remedial Action Plan, confirmation sampling verified that soils remaining in each source removal area and soils placed as cover contain less than 500 mg/kg lead and 100 mg/kg arsenic. Sediment sampling results from 23 source removal lead confirmation samples collected in the embankment wetland area averaged 43.1 mg/kg and ranged from 33 mg/kg to 126 mg/kg.

Post-construction measurements of the impoundment indicated that all areas measured contain at least 18 inches of clean fill material with the exception of areas F-2 and F-3, which are covered with a temporary 6-inch soil cover (Figure C-1 in Appendix C). Due to the presence of tailings in other OUs, the ROD contemplated the consolidation of mine wastes at OU1 from other cleanup locations in the Silver Creek watershed. Therefore, certain areas of OU1, including F-2 and F-3, have a temporary 6-inch soil cover to facilitate further consolidation while the EPA continues OU2 and OU3 site characterization to determine if more material will be brought to these areas prior to placement of the full 18-inch cover material.

As required by the ROD, UPCM collected surface water samples annually from 2008 to 2013 and again in 2015 as part of OU2 and OU3 investigations to determine the effects of remediation on surface water quality. Surface water samples were collected primarily from the main flow of the embankment wetland, as well as at various points of the southern diversion ditch. The results of all samples were consistently below the surface water standards for the Silver Creek watershed. Since the 2018 FYR, no monitoring or response actions have taken place at OU1, and no Operation and Maintenance (O&M) Plan has been developed.

In 2022, following bankruptcy, UPCM entered into a Consent Decree with the EPA to make a cash payment: (1) to EPA to resolve alleged civil CERCLA liability; and (2) to DOI and the State to resolve alleged natural resource damage liability.

In January 2022, the OU1 property was sold to a third party in a Sheriff's sale. The OU1 property is now owned by the LHM DEV RIH LLC (LHM). Subsequently, Park City annexed 1,200 acres, including the OU1 property, from Summit County into Park City on July 14, 2022. The EPA and LHM are in negotiations to finalize a Work Plan and an Administrative Order on Consent for LHM to assume long-term responsibility for stewardship and O&M activities for OU1 areas.

Institutional Control (IC) Review

The ROD states that two primary institutional controls will be implemented to mitigate potential risks and ensure the long-term protectiveness of the remedy:

- Groundwater use restrictions within the site boundary: the goal is to preclude any use of shallow groundwater, as well as eliminate any significant alteration of the existing hydrogeologic system, such as mixing of aquifers. This institutional control will be in the form of a deed restriction and will be the responsibility of the owner of the Site.
- Land use restrictions within the site boundary: the goal is to preclude non-recreational uses and to ensure that the soil cover, or similar protections, are maintained. This institutional control will be in the form of an Environmental Covenant and will be the responsibility of the owner of the Site.

Institutional controls called for in the ROD were not recorded by UPCM (Table 1). The properties had been zoned as "rural residential" by Summit County prior to annexation by Park City in 2022 (Figure 3). The properties are currently zoned by Park City as "recreation open space." The EPA will pursue proprietary controls as called for in the ROD, which will ensure the OU1 is protected permanently from activities that could compromise the remedy.

Table 1: Summary of	f Planned a	and/or In	plemented	Institut	ional C	ontrols (ICs)

Media, Engineered Controls, and Areas That Do Not Support UU/UE Based on Current Conditions	ICs Needed	ICs Called for in the Decision Documents	Impacted Parcel(s)	IC Objective ^a	Title of IC Instrument Implemented and Date (or planned)
Groundwater	Yes	Yes	Site area within Parcels SS- 87 and SS- 88	Permanently restrict new groundwater well installation and use of shallow groundwater within the impoundment area.	To be determined
Soils	Yes	Yes	Site area within Parcels SS- 87 and SS- 88	Permanently limit the land use to open space with wildlife habitat and non- motorized recreational use. Permanently preserve the low-permeability tailings cap and specify the ongoing erosion control and maintenance requirements. Permanently prohibit unauthorized excavation at the Site and of the cap material.	To be determined
a. As stated in the Sit	e's 2018 FY	R Report.			

Figure 3: Property Parcel Map


1,000

500

1,500

2,000

2,500 Feet



Systems Operations/Operation and Maintenance (O&M)

OU1 is still in remedial action pending additional cover material in areas where future consolidation from OU2 and OU3 may occur. A formal O&M Plan has not been developed and maintenance has been limited. Prior monitoring activities included monitoring of site conditions, erosion, vegetation condition, water runoff and invasive plant management, as needed. The EPA anticipates that LHM, the new OU1 property owner, will develop and implement an O&M Plan.

III. PROGRESS SINCE THE PREVIOUS REVIEW

This section includes the protectiveness determinations and statements from the last FYR Report as well as the recommendations from the last FYR Report and the status of those recommendations.

OU #	Protectiveness Determination	Protectiveness Statement
1	Short-term Protective	The remedy at OU1 currently protects human health and the environment because tailings and sediments have been excavated, tailings are contained through capping with clean soil, and surface waters exiting the Site are below water quality standards. However, for the remedy to be protective in the long term, the following action needs to be taken: implement institutional controls that include restrictions on future land and groundwater use.

Table 2: Protectiveness Determinations/Statements from the 2018 FYR Report

Table 3: Status of Recommendations from the 2018 FYR Report

Issue	Recommendations	Current Status	Current Implementation Status Description	Completion Date (if applicable)
Institutional controls called for in the ROD are not yet in place.	Implement necessary institutional controls to ensure the soil cover is protected and the shallow groundwater is not used.	Ongoing	Institutional controls in the form of environmental covenants are not yet in place. The EPA will work with the new property owner to assess potential uses of OU1 areas and will record appropriate restrictions in an instrument that is part of the land title.	NA

IV. FIVE-YEAR REVIEW PROCESS

Community Notification, Community Involvement and Site Interviews

A public notice was made available by a newspaper posting in the *Park Record*, on 6/17/2023 (Appendix D). It stated that the FYR was underway and invited the public to submit any comments to the EPA. The results of the review and the report will be made available at the Site's information repository, Park City Public Library, located at 255 Park Avenue, Park City, Utah 84060. The report will also be placed on the EPA Site Profile Page at http://www.epa.gov/superfund/richardson-flat.

During the FYR process, interviews were conducted to document any perceived problems or successes with the remedy implemented to date. The interviews are summarized below.

Doug Bacon, UDEQ: Mr. Bacon is satisfied with the OU1 remedy, but noted the lack of adequate institutional controls. He is aware of the property transfer to LHM and was actively engaged in discussions about future land uses and LHM's responsibilities for OU1.

Greg Flint, LHM and Anna Rasmussen, Tetra Tech: Mr. Flint has recently learned about the Site following LHM's acquisition of the OU1 property and is engaging Tetra Tech for technical support regarding the OU1 remedy, site characterization and potential engineering needs.

Ryan Blair, Park City Environmental Regulatory Program Manager: Mr. Blair is aware of the Site and the OU1 status regarding property transfer to LHM and the annexation by Park City. He did not express any concerns with the current OU1 remedy.

Data Review

No monitoring data were collected during this FYR period.

Site Inspection

The site inspection took place on 10/18/2022. Participants included EPA RPM James Hou, Doug Bacon from UDEQ, and Ryan Burdge from Skeo. The purpose of the inspection was to assess the protectiveness of the remedy. The site inspection checklist and photographs are included in Appendix F and Appendix G, respectively.

Site inspection participants drove and walked OU1, including the parking area, stormwater diversion features and wetlands areas, covered areas within the tailings impoundment, and the embankment buttress. The gate into the impoundment area was not secured. Vegetation in the cover areas appeared to be well established. However, piles of soil and/or rubble of unknown origin were observed, as well as areas of recent soil disturbance. In addition, a trespasser residing in a well-established trailer was observed behind mounded material, unobservable from the roadway. The new property owner has since removed the trespasser.

V. TECHNICAL ASSESSMENT

QUESTION A: Is the remedy functioning as intended by the decision documents?

The OU1 remedy is performing as intended. Tailings outside of the impoundment have been excavated and placed under clean fill in the impoundment, and the main embankment has been stabilized. Post-construction measurements of the impoundment indicated that all areas measured contain at least 18 inches of clean fill material with the exception of areas F-2 and F-3. Areas F-2 and F-3 are covered with a temporary 6-inch soil cover while the EPA continues OU2 and OU3 site characterization to determine the volume of additional material to be brought to these areas prior to placing the full 18-inch cover material. In addition, the site inspection noted multiple piles of unknown materials in the vicinity of F-2 and F-3. The EPA intends for the new property owner to characterize these piles and sample areas F-2 and F-3 to confirm the condition of the temporary 6-inch soil cover.

During construction, monitoring had been performed as required by the ROD, but no O&M Plan has been prepared for OU1. Monitoring and maintenance activities have been limited. The EPA anticipates the new property owner will assume responsibility for O&M activities for OU1.

Institutional controls to protect the soil cover and restrict groundwater use have not yet been implemented. The ROD states that two primary institutional controls will be implemented to mitigate potential risks and ensure the long-term protectiveness of the remedy:

- Groundwater use restrictions within the site boundary. The goal is to preclude any use of shallow groundwater, as well as eliminate any significant alteration of the existing hydrogeologic system such as mixing of aquifers. It is anticipated that the institutional control will be in the form of a deed restriction and will be the responsibility of the owner of the Site.
- Land-use restrictions within the site boundary. The goal is to preclude non-recreational uses and to ensure the soil cover, or similar protections, are maintained. This institutional control will be in the form of an Environmental Covenant and will be the responsibility of the owner of the Site.

The EPA is working with the new property owner to determine potential uses of OU1 areas and will ensure appropriate restrictions in an instrument that is part of the land title. Recorded and legally-enforceable restrictions as called for in the ROD are necessary to ensure no potential exposures in the future. The property is zoned by Park City as "open space recreational," and public access to the repository is restricted through fencing and signage.

QUESTION B: Are the exposure assumptions, toxicity data, cleanup levels and RAOs used at the time of the remedy selection still valid?

The exposure assumptions, toxicity data, cleanup levels and RAOs used at the time of the OU1 remedy selection are still valid. The remedy anticipated a future recreational use, and public access to OU1 is currently restricted to the paved parking area.

Lead exposure in surface soils was evaluated using the Integrated Exposure, Uptake and Biokinetic model for children and the Bower's model for adult receptors. Both models predicted blood lead levels below the EPA's health-based goal of a 5% probability of exceeding a blood lead level of 10/g/dL for all recreational use scenarios. All soil contamination within the impoundment and a few small areas outside of the impoundment are covered with at least 18 inches of clean soil to eliminate appreciable residual human health risk due to incidental exposure except for cells F-2 and F-3, which remain partially covered.

The human health cleanup levels for the Site were based on EPA guidance that recommended 10 μ g/dL as the blood lead level of concern. EPA Region 8 will continue to use the current EPA policy, until the Agency finalizes and updates its policy.

QUESTION C: Has any other information come to light that could call into question the protectiveness of the remedy?

No other information has come to light that could call into question the protectiveness of the remedy.

VI. ISSUES/RECOMMENDATIONS

Issues/Recommendations
OU(s) without Issues/Recommendations Identified in the FYR:
None

Issues and Recommendations Identified in the FYR:

OU(s): 1	Issue Category: Institutional Controls				
	Issue: The proprietary restrictions called for groundwater and land use in the ROD are not yet recorded for the OU1 site property.				
	Recommendation: Finalize and implement appropriate proprietary restrictions with LHM, the new OU1 property owner.				
Affect Current Protectiveness	Affect FuturePartyOversight PartyMilestone DateProtectivenessResponsible				
No	Yes	Other – LHM	EPA	9/30/2025	

OU(s): 1	Issue Category: Operations and Maintenance				
Issue: No O&M Plan was developed by UPCM. LH owner, has yet to submit an O&M Plan.				M, the new OU1 property	
	Recommendation: Finalize and implement an O&M Plan for the OU1 repository.			the OU1	
Affect Current Protectiveness	· · 8 ·				
No	Yes	Other – LHM	EPA	9/30/2024	

OTHER FINDINGS

Several additional recommendations were identified during the FYR. These recommendations do not affect current and/or future protectiveness.

• The site inspection noted multiple piles of unknown materials in the vicinity of F-2 and F-3. The EPA intends for the new property owner to characterize these piles and sample areas F-2 and F-3 to confirm the condition of the temporary 6-inch soil cover. The site inspection noted a trespasser residing in a well-established trailer, behind mounded material and

The site inspection noted a trespasser residing in a well-established trailer, behind mounded material and unobservable from the roadway. The new property owner has since removed the trespasser.

VII. PROTECTIVENESS STATEMENT

	Protectiveness Statement(s)	
Operable Unit:1	Protectiveness Determination: Short-term Protective	

Protectiveness Statement:

The remedy at OU1 currently protects human health and the environment because tailings and sediments have been excavated, tailings are contained through capping with clean soil, and surface waters exiting the Site are below water quality standards. For the remedy to be protective over the long term, the following actions need to be taken: 1) finalize and implement appropriate proprietary restrictions with LHM; and 2) finalize and implement an O&M Plan for the OU1 repository.

VIII. NEXT REVIEW

The next FYR Report for the Richardson Flat Tailings Superfund site is required five years from the completion date of this review.

APPENDIX A – REFERENCE LIST

2005. United States Environmental Protection Agency, Record of Decision, Richardson Flat Tailings., EPA ID UT980952840.

2007. Resource Management Consultants, Inc., Remedial Design/Remedial Action Plan (RD/RA), Richardson Flat, Site ID Number: UT980952840.

2007. Resource Management Consultants, Inc., Phase 1 Field Construction Plan for 2008 Construction Season, Richardson Flat, Site ID Number: UT980952840.

2007. Resource Management Consultants, Inc., Phase 1 Task Completion Report, Richardson Flat, Site ID Number: UT980952840.

2008. Resource Management Consultants, Inc., Phase 2 Task Completion Report for 2008 Construction Season, Richardson Flat, Site ID Number: UT980952840.

2009. Resource Management Consultants, Inc., Phase 3 Task Completion Report for 2009 Construction Season, Richardson Flat, Site ID Number: UT980952840.

2010. Resource Management Consultants, Inc., Phase 4 Task Completion Report for 2010 Construction Season, Richardson Flat, Site ID Number: UT980952840.

2011. Resource Management Consultants, Inc., Phase 5 Task Completion Report for 2011 Construction Season, Richardson Flat, Site ID Number: UT980952840.

2011. Resource Management Consultants, Inc., Task Area Map, Richardson Flat, Site ID Number: UT980952840.

2012-2017. United Park City Mines Quarterly Status Reports, Richardson Flat, Site ID Number: UT980952840.

2013. United States Environmental Protection Agency, Five-Year Review, Richardson Flat Tailings, EPA ID UT980952840.

2018 United States Environmental Protection Agency, Five-Year Review, Richardson Flat Tailings, EPA ID UT980952840.

APPENDIX B – SITE CHRONOLOGY

Table B-1: Site Chronology

Event	Date
EPA discovered contamination	October 1, 1984
UPCM initiated the Site's RI and focused feasibility study for OU1	September 29, 1989
EPA proposed the Site for listing on the NPL	February 7, 1992
UPCM completed the Site's RI and focused feasibility study for OU1	July 1, 1992
The EPA signed the Site's ROD for OU1	July 6, 2005
UPCM initiated the Site's remedial design for OU1	August 7, 2007
UPCM completed the Site's remedial design for OU1 UPCM initiated the remedial action for OU1	February 7, 2008
UPCM and the EPA signed an administrative settlement agreement and order on consent for an RI and focused feasibility study for OU2	September 29, 2009
EPA approved completion of construction activities outlined in the Site's remedial design	November 2011
EPA signed the Site's first FYR Report	March 14, 2013
EPA signed the Site's second FYR Report	August 10, 2018
EPA and UPCM finalized a Consent Decree to resolve CERCLA liability	October 17, 2022
LHM purchased the OU1 property	January 2022
Park City annexed the OU1 property into the municipality	July 14, 2022

APPENDIX C – SITE MAPS

Figure C-1: Remedial Design Task Areas




Figure C-2: Phase 2 Completion Map, 2008




Figure C-3: Phase 3 Completion Map, 2009




Figure C-4: Phase 4 Completion Map, 2010





Figure C-5: Phase 5 Completion Map, 2011



APPENDIX D – PRESS NOTICE

The Park Record

Sat/Sun/Mon/Tues, June 17-20, 2023

 Loss is also in the DNA of the new album by multi-inrumentalist, singer-son r Meshell Ndegeocello.)mnichord Real Book" dbum made after she lo sarents. "This album is he way we see old thi ""Chanaveelli The featuring Jeff guitar lines Justin Hicks. produced by d also features by also features brose Akin-Jeff Parker, Julius Ro-iliana, Cory blice Woman an As Police Wo

ound cool and n of the Stone Age, 'riday, with the 10-t album "In Times 1 ..." On the sp "Fmotional 5 ray, with the 10-track um "In Times New 'On the spiky, "Emotional Sich Homme tonce and destroy' tings of pain A dose sickness I just can't to n"Carnavoyeur," mooth, distant cool: h, nealize/There are ountains to climb," netrainment Writer edy Mark Ke

NEW SERIES TO STREAM — The new "The Wonder Black about in Morechner exp. Alabama, in the 1960s, returns for its second season on Wodnesday on ABC. The show is told from the point of the view of 12-year-bid Dam Wolf, while the second season to be an any second season the second season two of Dean. If is already been an-nounced that season two will feature several guest stars in-feature several guest stars in-the second season two of "Star Trek". actor repris new season — Caitri NEW SERIES TO STREAM

of "Star Trek: on Thursday, watched yet, place about e "Star Trek: Series," so it younger versions of the "Star Trek" s viewers know and trange New Worlds" int as Captain when he led



MATADOR RECORDS, SERVIEUC RECORDS VIA AP This combination of album cover images shows, clockwise 1 top left, "Michael" by Killer Mike, "The Ornnichord Real Be Meshell Ndegeocello, "In Times New Roman.," by Queens Stone Age and "Strictly a One-Eyed Jack," by John Mellenc

Store Age and "Strictly a One-Eyed Jack," by John Mellencarne, the USS Enterprise, with a crew to help hin includus his rever that includes Ethan Peck and Store and Store and Store and Store thank Ricy (otherwise assist, if's a major task and thorn as Nuebed Poch, and assess is not gammeted. On Uhara. The season one finale includueed Paul Wesly in the and on one pushes your bai-nole of James T. Kirk and the tors quite like finally. "Holf-tocht repriste her olit in this med and the season one finale contramos the final start of the tors quite like finally." Holf-tocht repriste her olit in this med contramos the final start of the Harder are very competitive tors quite like finally. "Holf-tocht repriste her olit in this med the start of the season two the "Cuttings The season the "Mellen and Start Pockhart and the start of the season two the "Cuttings The season the start of the season two the "Cuttings" the season the start of the season two the "Cuttings" the season the start of the season two the "Cuttings" the season two the season two the "Cuttings" the season two the "Cuttings" the season two the "Cuttings" the season two the season tw

actor reprises the role in this according to the second s —Aikia Bancillo
—Aikia Bancillo
Experimental and the second se offi the book series by Diana — "Gold Rush" fan favor-ite Todd Hoffman is trying to turn his fortune around by re-habilitating a rundown mine in Alaska in Discovery Channel's "Hoffman Family Gold." In season two, Todd has a small



The U.S. Environmental Protection Agency, Region 8 Announces the Third Five-Year Review for the Richardson Flat Tailings Site, Park City, Utah

B7

The U.S. Environmental Protection Agency (EPA), in cooperation with the Utah Department of Environmental Quality (UDEQ), is conducting the third five-year review for operable unit 1 (OUI) of the Richardson Flat Tailings site in Park City, Utah. The purpose of the five-year review is to make sure that the cleanup actions completed to date are adequately protecting human health and the environment. The five-year review for OUI is scheduled to be completed by August 2023.

review for OU1 is scheduled to be completed by August 2023. The 160-acre site is located southeast of the intersection of State Highway 248 and U.S. Highway 40 approximately 2 miles northeast of Park City, Ulunk EPA proposed the Site for listing on the National Priorities List (NPL) in 1992. A tailings dam and impoundment on site were used to capture and hold mill tailings from 1953 until 1981, resulting in contamination of soil, groundwater, surface water and air. EPA, with the concurrence of UDEQ, selected a remedy in a 2005 Record of Decision. (ROD). Cleanup activities at OU1 include excartion, consolidation, and containment of mine tailings.

Autorgs.
We want to hear from you! Community members are always encouraged to share information that may help EPA and UDEQ make determinations regarding the protectiveness and effectiveness of the remedies at the site. Please contact Project Manager James Hou:

James Hou, EPA Remedial Project Manager Phone: 303-312-6210 Email: hou.james@epa.gov Mailing Address: U.S. EPA Region 8 (EPR-SR) 1595 Wynkoop Street, Denver, CO 80202-1129

Additional site information is available at: EPA Superfund Records Center 1595 Wynkoop Street Denver, CO 80202-1129 303-312-7273

Or online at: https://www.epa.gov/superfund/richardson-flat



APPENDIX E – INTERVIEW FORMS

RICHARDSON FLAT TAILINGS SUPERFUND SITE FIVE-YEAR REVIEW INTERVIEW FORM					
Site Name: Richardson Flat Tailings					
EPA ID: UTD980952840					
Interviewer name: Katherine Jenkins	Interviewer name: Katherine Jenkins Interviewer affiliation: EPA Region 8				
Subject name: Doug BaconSubject affiliation: UDEQ					
Interview format (circle one): In Person Phone Mail Email Other:					
Interview category: State Agency					

1. What is your overall impression of the project, including cleanup, maintenance and reuse activities (as appropriate)?

Overall, OU1 looks good. The State would like to see more of a holistic look at the mine waste. There are additional mine sites around beyond Richardson Flat, and a holistic approach would ensure what happening above and upstream does not impact downstream work already done. UPCM is gone, so the more collaboration and thinking of all mining waste in the area is important for Richardson Flat as it is furthest downstream. The State has high interest in the repository.

- 2. What is your assessment of the current performance of the remedy in place at the Site? I think the OU1 remedy is protective. There is renewed interest in the park and ride, and the property attracts wildlife, including waterfowl, kingfishers and raptors. It will be good to see any potential changes in land use in the area.
- 3. Are you aware of any complaints or inquiries regarding site-related environmental issues or remedial activities from residents in the past five years? I know the community does not want another repository and have expressed interest in OU1 being reopened. I have heard concerns about land development around the repository. I have not heard of concerns directly linked to protectiveness.
- Has your office conducted any site-related activities or communications in the past five years? If so, please
 describe the purpose and results of these activities.
 No, we have not done anything on our own.
- Are you aware of any changes to state laws that might affect the protectiveness of the Site's remedy? No. State ARARs will be considered for any additional work by LHM and future placement of materials from other OUs.
- 6. Are you comfortable with the status of the institutional controls at the Site? If not, what are the associated outstanding issues?I have concerns about institutional controls not being successful. Institutional controls work when parties are informed. Local ordinances are not failproof and when staff turn over, institutional knowledge is lost.
- Are you aware of any changes in projected land use(s) at the Site?
 Yes, I am aware of the new owner, LHM, and its potential plans for future land development outside of the repository.

8. Do you have any comments, suggestions or recommendations regarding the management or operation of the Site's remedy?

I would encourage continued outreach to the stakeholders and let them know what is changing. Transparency is helpful. News spreads quickly in this community, so it is important to keep sharing information.

 Do you consent to have your name included along with your responses to this questionnaire in the FYR Report? Yes.

RICHARDSON FLAT TAILINGS SUPERFUND SITE FIVE-YEAR REVIEW INTERVIEW FORM				
Site Name: Richardson Flat Tailings				
EPA ID: UTD980952840				
Interviewer name: Katherine Jenkins Interviewer affiliation: EPA Region 8				
Subject name: Greg Flint and Anna Rasmussen Subject affiliation: LHM and Tetra Tech				
Interview format (circle one): In Person Phone Mail Email Other:				
Interview category: Larry H Miller Group and Tetra Tech (contractor)				

- What is your overall impression of the remedial activities at the Site? We are still getting up to speed on the Site but have developed an understanding of the OU1 remedy and the expectation of additional material from other OUs being placed at OU1. Communication with EPA and the State has been great.
- 2. What have been the effects of the Site on the surrounding community, if any? The property has been in the news, most recently about the annexation into Park City. The discussions seem to be more about the land use and less about environmental concerns. LHM will continue to work with EPA, the State and the city regarding potential land uses.
- 3. What is your assessment of the current performance of the remedy in place at the Site? We are happy with the remedy based on available information. LHM and Tetra Tech are developing a work plan for EPA review that will likely include additional characterization of on-site soils. We will work with EPA for any future remedial needs.
- Are you aware of any complaints or inquiries regarding environmental issues or the remedial action from residents since implementation of the cleanup? No, we are not aware of anything.
- Do you feel well-informed regarding the Site's activities and remedial progress? If not, how might EPA convey site-related information in the future? Yes, communication has been great. This meeting and interview is one more example of that.
- Do you have any comments, suggestions or recommendations regarding the management or operation of the Site's remedy? No.
- Do you consent to have your name included along with your responses to this questionnaire in the FYR Report? Yes.

RICHARDSON FLAT TAILINGS SUPERFUND SITE FIVE-YEAR REVIEW INTERVIEW FORM				
Site Name: Richardson Flat Tailings				
EPA ID: UTD980952840				
Interviewer name: Katherine Jenkins Interviewer affiliation: EPA Region 8				
Subject name: Ryan BlairSubject affiliation: Park City, Env Reg Program Manager				
Interview format (circle one): In Person Pho	ne Mail Email Other:			
Interview category: Local Government				

1. Are you aware of the former environmental issues at the Site and the cleanup activities that have taken place to date?

Yes, I have reviewed some documents. The EPA webpage is great, and I have contact with EPA.

- Do you feel well-informed regarding the Site's activities and remedial progress? If not, how might EPA convey site-related information in the future? Yes, the webpage and maps are really good.
- Have there been any problems with unusual or unexpected activities at the Site, such as emergency response, vandalism or trespassing? No, not that I am aware of.
- Are you aware of any changes to state laws or local regulations that might affect the protectiveness of the Site's remedy?
 No, I am not aware of any new regulations that would affect the remedy.
- 5. Are you aware of any changes in projected land use(s) at the Site? I am aware of the current land use and that the property was recently annexed by Park City. My understanding is there is a conservation easement limiting land use to open space and the parking lot.
- 6. Has EPA kept involved parties and surrounding neighbors informed of activities at the Site? How can EPA best provide site-related information in the future? Yes, but there is room for improvement. Recently, there was a draft settlement agreement that was up for public comments, but the city was not informed. We would have liked to have been informed.
- 7. Do you have any comments, suggestions or recommendations regarding the project? No.
- Do you consent to have your name included along with your responses to this questionnaire in the FYR Report? Yes.

APPENDIX F – SITE INSPECTION CHECKLIST

FIVE-YEAR REVIEW SITE INSPECTION CHECKLIST					
I. SITE INF	ORMATION				
Site Name: Richardson Flat Tailings	Date of Inspection: <u>10/18/2022</u>				
Location and Region: Park City, Utah, EPA Region 8	EPA ID: UTD980952840				
Agency, Office or Company Leading the Five-Year Review: <u>EPA Region 8</u>	Weather/Temperature: <u>30 degreees, sunny</u>				
Remedy Includes: (check all that apply) Monitored natural attenuation Landfill cover/containment Monitored natural attenuation Access controls Groundwater containment Institutional controls Vertical barrier walls Groundwater pump and treatment Surface water collection and treatment Other: Other:					
Attachments: Inspection team roster attached	Site map attached				
II. INTERVIEWS	(check all that apply)				
Name Interviewed at site at office by phone P	Interviewed at site at office by phone Phone: Problems, suggestions Report attached:				
Interviewed at site at office by phone F Problems/suggestions Report attached:	Title Date				
	Agencies (i.e., state and tribal offices, emergency blic health or environmental health, zoning office, es). Fill in all that apply.				
Agency UDEQContactDoug Bacon NameProject ManagerNameManager TitleDate					
Problems/suggestions Report attached: 4. Other Interviews (optional) Report attached)	- d·				
III. ON-SITE DOCUMENTS AND RECORDS VERIFIED (check all that apply) 1. O&M Documents					
\square O&M manual \square Readily availab	ole Up to date N/A				
\boxtimes As-built drawings \boxtimes Readily availab					
$\boxtimes Maintenance logs \qquad \boxtimes Readily available ava$					
Remarks:					
2. Site-Specific Health and Safety Plan	☐ Readily available ☐ Up to date ⊠ N/A				
Contingency plan/emergency response plan					

	Remarks:	
3.	O&M and OSHA Training Records	☐ Readily available ☐ Up to date ⊠ N/A
	Remarks:	
4.	Permits and Service Agreements	
	Air discharge permit	🗌 Readily available 🛛 Up to date 🛛 N/A
	Effluent discharge	🗌 Readily available 🛛 Up to date 🛛 N/A
	Waste disposal, POTW	🗌 Readily available 🛛 Up to date 🛛 N/A
	Other permits:	🗌 Readily available 🛛 Up to date 🛛 N/A
	Remarks:	
5.	Gas Generation Records	🗌 Readily available 🛛 Up to date 🛛 N/A
	Remarks:	
6.	Settlement Monument Records	☐ Readily available ☐ Up to date ⊠ N/A
	Remarks:	
7.	Groundwater Monitoring Records	🗌 Readily available 🗌 Up to date 🛛 N/A
	Remarks:	
8.	Leachate Extraction Records	🗌 Readily available 🛛 Up to date 🛛 N/A
	Remarks:	
9.	Discharge Compliance Records	
	Air Readily availab	le \Box Up to date \overleftrightarrow N/A
	Water (effluent) Readily availab	le \Box Up to date \boxtimes N/A
	Remarks:	
10.	Daily Access/Security Logs	\Box Readily available \Box Up to date \boxtimes N/A
	Remarks:	
	IV. O&N	1 COSTS
1.	O&M Organization	
	State in-house	Contractor for state
	PRP in-house	Contractor for PRP
	Federal facility in-house	Contractor for Federal facility
	⊠ <u>LHM Group</u>	
2.	O&M Cost Records	
	Readily available	Up to date
	Funding mechanism/agreement in place	🛛 Unavailable
	Original O&M cost estimate: Breako	
		ar for review period if available
	From: To:	Breakdown attached
	Date Date	Total cost

	From:	То:		Breakdown a	ttached
	Date	Date	Total cost	_	
	From:	То:		Breakdown a	ttached
	Date	Date	Total cost	—	
	From:	То:		Breakdown a	ttached
	Date	Date	Total cost	_	
	From:	То:		Breakdown a	ttached
	Date	Date	Total cost		
3.	Unanticipated or U Describe costs and	• •	I Costs during Review Pe	riod	
			DNAL CONTROLS	Ameliachte 🗔 Nu	/ A
		5 AND INSTITUTIO	DNAL CONTROLS		A
A. F	encing				
1.	Fencing Damaged		nown on site map Ga	ites secured	N/A
	Remarks:				
	ther Access Restrictio				
1.	Signs and Other S	ecurity Measures	Location sł	hown on site map	□ N/A
	Remarks:				
C. Ir	stitutional Controls (
1.	Implementation and				
	Site conditions imply ICs not properly implemented \Box Yes \Box No \boxtimes N/ASite of the set of				
	Site conditions imply ICs not being fully enforced Yes No X/A				
		e.g., self-reporting, dr	ive by):		
	Frequency: Responsible party/ag	ency			
	Contact	ency			
	Name		Title	Date	Phone
		to.	The	Yes N	
	Reporting is up to da Reports are verified l				No $\boxed{N/A}$
	-		locuments have been met	$\Box \text{ Yes } \boxtimes \mathbb{N}$	
			ocuments have been met		_
	Violations have been	ggestions: 🗌 Report	attachad	Yes N	
	Other problems of su	iggestions: \square Keport	attached		
2.	Adequacy] ICs are adequate	ICs are ina	dequate	X/A
	Remarks: Long-term land use and groundwater restictions are called for in the ROD. However, they are not yet implemented.				
D. G	D. General				
1.	1. Vandalism/Trespassing 🗌 Location shown on site map 🛛 No vandalism evident				
	-		ed during the site inspectio		

2.	Land Use Changes On Site	X N/A	
	Remarks:		
3.	Land Use Changes Off Site	N/A	
	Remarks:		
		VI. GENERAL SITE CONDITIONS	8
A. R	oads 🛛 Applicable	N/A	
1.	Roads Damaged Remarks:	Location shown on site map 🛛 🕅 F	Roads adequate \square N/A
B. O	ther Site Conditions		
	Remarks: Native vegetation	is well established.	
	VII. LAN	DFILL COVERS Applicab	le 🗌 N/A
A. La	andfill Surface		
1.	Settlement (low spots)	Location shown on site map	Settlement not evident
	Arial extent:		Depth:
	Remarks:		·
2.	Cracks	Location shown on site map	Cracking not evident
	Lengths:	Widths:	Depths:
	Remarks:		
3.	Erosion	Location shown on site map	Erosion not evident
	Arial extent:		Depth:
	Remarks:		
4.	Holes	Location shown on site map	Holes not evident
	Arial extent:		Depth:
	Remarks:		
5.	Vegetative Cover	🔀 Grass	Cover properly established
	No signs of stress	Trees/shrubs (indicate size and lo	cations on a diagram)
	Remarks:		
6.	Alternative Cover (e.g., a	armored rock, concrete)	X/A
	Remarks:		
7.	Bulges	Location shown on site map	Bulges not evident
	Arial extent:		Height:
	Remarks:		
8.	Wet Areas/Water Dama	ge Wet areas/water damage not e	vident
	Wet areas	Location shown on site map	Arial extent:
	Ponding	Location shown on site map	Arial extent:
	Seeps	Location shown on site map	Arial extent:

	Soft subgrade	Location shown on site map	Arial extent:
	Remarks:		
9.	Slope Instability	Slides	Location shown on site map
	\boxtimes No evidence of slope in	istability	
	Arial extent:		
	Remarks:		
B. B	enches Applic		
		ounds of earth placed across a steep land ity of surface runoff and intercept and o	
1.	Flows Bypass Bench	Location shown on site map	N/A or okay
	Remarks:		
2.	Bench Breached	Location shown on site map	N/A or okay
	Remarks:		
3.	Bench Overtopped	Location shown on site map	□ N/A or okay
	Remarks:		
C. L	etdown Channels [Applicable 🛛 N/A	
		control mats, riprap, grout bags or gabic low the runoff water collected by the bo on gullies.)	
1.	Settlement (Low spots)	Location shown on site map	No evidence of settlement
	Arial extent:		Depth:
	Remarks:		
2.	Material Degradation	Location shown on site map	No evidence of degradation
	Material type:		Arial extent:
	Remarks:		
3.	Erosion	Location shown on site map	No evidence of erosion
	Arial extent:		Depth:
	Remarks:		
4.	Undercutting	Location shown on site map	No evidence of undercutting
	Arial extent:		Depth:
	Remarks:		
5.	Obstructions	Туре:	No obstructions
	Location shown on site	map Arial extent:	
	Size:		
	Remarks:		
6.	Excessive Vegetative Gro		
	No evidence of excessiv	ve growth	

	Uegetation in channels de	oes not obstruct flow	7				
	Location shown on site map Arial extent:						
	Remarks:						
D. Co	D. Cover Penetrations \Box Applicable \bigotimes N/A						
1.	Gas Vents	Cas Vents Active Passive		ive			
	Properly secured/locked	Functioning	Routinely sampled	Good condition			
	Evidence of leakage at po	enetration	Needs maintenance	N/A			
	Remarks:						
2.	Gas Monitoring Probes						
	Properly secured/locked	Functioning	Routinely sampled	Good condition			
	Evidence of leakage at pe	enetration	Needs maintenance	N/A			
	Remarks:						
3.	3. Monitoring Wells (within surface area of landfill)						
	Properly secured/locked	Functioning	Routinely sampled	Good condition			
	Evidence of leakage at pe	enetration	Needs maintenance	N/A			
	Remarks:						
4.	Extraction Wells Leachate						
	Properly secured/locked	Functioning	Routinely sampled	Good condition			
	Evidence of leakage at po	enetration	Needs maintenance	N/A			
	Remarks:						
5.	Settlement Monuments		Routinely surveyed	N/A			
	Remarks:						
E. Gas	s Collection and Treatment		N/A				
1.	Gas Treatment Facilities						
	Flaring	Thermal destru	iction	Collection for reuse			
	Good condition	Needs mainten	ance				
	Remarks:						
2.	Gas Collection Wells, Mani	folds and Piping					
	Good condition	Needs mainten	ance				
	Remarks:						
3.	Gas Monitoring Facilities (e	e.g., gas monitoring o	of adjacent homes or buildi	ngs)			
	Good condition	Needs mainten	ance 🗌 N/A				
	Remarks:						
F. Cover Drainage Layer							
1.	Outlet Pipes Inspected	Functioning	N/A				
	Remarks:						

2.	Outlet Rock Inspected	Functioning	N/A			
	Remarks:					
G. Detention/Sedimentation Ponds Applicable X/A						
1.	Siltation Area e	extent: Depth:	N/A			
	Siltation not evident					
	Remarks:					
2.		extent: Depth:				
	Erosion not evident					
	Remarks:					
3.	Outlet Works Fu	nctioning	N/A			
	Remarks:					
4.	Dam 🗌 Fu	nctioning	N/A			
	Remarks:					
H. R	etaining Walls	Applicable N/A				
1.	Deformations	Location shown on site map	Deformation not evident			
	Horizontal displacement:	Vertical disp	lacement:			
	Rotational displacement:					
	Remarks:					
2.	Degradation	Location shown on site map	Degradation not evident			
	Remarks:					
I. Pe	rimeter Ditches/Off-Site Disc	charge 🗌 Applicable 🔯	N/A			
1.	Siltation	Location shown on site map	Siltation not evident			
	Area extent:		Depth:			
	Remarks:					
2.	Vegetative Growth	Location shown on site map	N/A			
	Uegetation does not impo	ede flow				
	Area extent:		Туре:			
	Remarks:					
3.	Erosion	Location shown on site map	Erosion not evident			
	Area extent:		Depth:			
	Remarks:					
4.	Discharge Structure	Functioning	N/A			
	Remarks:					
VIII.	VERTICAL BARRIER WA	ALLS Applicable	🖾 N/A			
1.	Settlement	Location shown on site map	Settlement not evident			
	Area extent:		Depth:			

	Remarks:					
2.	Performance Monitoring Type of monitoring:					
	Performance not monitored					
	Frequency: Evidence of breaching					
	Head differential:					
	Remarks:					
IX. C	IX. GROUNDWATER/SURFACE WATER REMEDIES Applicable N/A					
A. G	A. Groundwater Extraction Wells, Pumps and Pipelines					
1.	Pumps, Wellhead Plumbing and Electrical					
	Good condition All required wells properly operating Needs maintenance N/A					
	Remarks:					
2.	Extraction System Pipelines, Valves, Valve Boxes and Other Appurtenances					
	Good condition Needs maintenance					
	Remarks:					
3.	Spare Parts and Equipment					
	☐ Readily available ☐ Good condition ☐ Requires upgrade ☐ Needs to be provided					
	Remarks:					
B. St	urface Water Collection Structures, Pumps and Pipelines Applicable N/A					
1.	Collection Structures, Pumps and Electrical					
	Good condition Needs maintenance					
	Remarks:					
2.	Surface Water Collection System Pipelines, Valves, Valve Boxes and Other Appurtenances					
	Good condition Needs maintenance					
	Remarks:					
3.	Spare Parts and Equipment					
	Readily available Good condition Requires upgrade Needs to be provided					
	Remarks:					
С. Т	Streatment System Applicable N/A					
1.	Treatment Train (check components that apply)					
	Metals removal Oil/water separation Bioremediation					
	Air strippingCarbon adsorbers					
	Filters:					
	Additive (e.g., chelation agent, flocculent):					
	Others:					
	Good condition					
	Sampling ports properly marked and functional					

Sampling/maintenance log displayed and up to date				
Equipment properly identified				
Quantity of groundwater treated annually:				
Quantity of surface water treated annually:				
Remarks:				
2. Electrical Enclosures and Panels (properly rated and functional)				
□ N/A □ Good condition □ Needs maintenance				
Remarks:				
3. Tanks, Vaults, Storage Vessels				
□ N/A □ Good condition □ Proper secondary containment □ Needs maintenance				
Remarks:				
4. Discharge Structure and Appurtenances				
□ N/A □ Good condition □ Needs maintenance				
Remarks:				
5. Treatment Building(s)				
□ N/A □ Good condition (esp. roof and doorways) □ Needs repair				
Chemicals and equipment properly stored				
Remarks:				
6. Monitoring Wells (pump and treatment remedy)				
Properly secured/locked Functioning Routinely sampled Good condition				
All required wells located Needs maintenance N/A				
Remarks:				
D. Monitoring Data				
1. Monitoring Data				
☐ Is routinely submitted on time ☐ Is of acceptable quality				
2. Monitoring Data Suggests:				
Groundwater plume is effectively contained Contaminant concentrations are declining				
E. Monitored Natural Attenuation				
1. Monitoring Wells (natural attenuation remedy)				
Properly secured/locked Functioning Routinely sampled Good condition				
All required wells located Needs maintenance N/A				
Remarks:				
X. OTHER REMEDIES If there are remedies applied at the site and not covered above, attach an inspection sheet describing the physical				
nature and condition of any facility associated with the remedy. An example would be soil vapor extraction.				
XI. OVERALL OBSERVATIONS A. Implementation of the Remedy				

1					
	Describe issues and observations relating to whether the remedy is effective and functioning as designed.				
	Begin with a brief statement of what the remedy is designed to accomplish (e.g., to contain contaminant				
	plume, minimize infiltration and gas emissions).				
	Construction specified in the remedial design has been completed. Vegetation is well established and				
	erosion is not an issue. Areas of the impoundment received regionally sourced mine waste and were				
	covered with a temporary 6-inch soil cover while EPA determines if more material will be brought to				
	these areas prior to placing the full 18-inch fill material.				
В.	Adequacy of O&M				
	Describe issues and observations related to the implementation and scope of O&M procedures. In				
	particular, discuss their relationship to the current and long-term protectiveness of the remedy.				
	O&M actitivities have not been performed during this FYR period.				
C.	Early Indicators of Potential Remedy Problems				
	Describe issues and observations such as unexpected changes in the cost or scope of O&M or a high				
	frequency of unscheduled repairs that suggest that the protectiveness of the remedy may be compromised				
	in the future.				
	None noted.				
D.	Opportunities for Optimization				
	Describe possible opportunities for optimization in monitoring tasks or the operation of the remedy.				
	None noted.				

APPENDIX G – SITE INSPECTION PHOTOS



The diversion ditch and parking area, northwest-facing view from the parking lot entrance



Signage at the entrance to the parking lot



Toe of the main embankment



Pile of material of unknown origin



Piles of material of unknown origin



The diversion ditch and cottonwood trees



The wetland area west of the impoundment