



State of Utah

Department of  
Environmental Quality

Richard W. Sprott  
*Executive Director*

DIVISION OF ENVIRONMENTAL  
RESPONSE AND REMEDIATION  
Brad T Johnson  
*Director*

JON M. HUNTSMAN, JR.  
*Governor*

GARY HERBERT  
*Lieutenant Governor*

FILE COPY

ERRU-0144-07

August 2, 2007

Stephen L. Johnson  
U.S. EPA Administrator  
Attn: State Government UST Compliance Report Submittal  
U.S. Environmental Protection Agency  
1200 Pennsylvania Avenue  
Washington, DC 20460-0001

Dear Mr. Johnson:

Enclosed you will find Utah's State Government UST Compliance Report as required by the Energy Policy Act of 2005 Grant Guidelines. Utah has 217 government owned UST facilities containing a total of 452 regulated USTs. Of these 217 facilities, 12 facilities containing 33 USTs are not in compliance as of the date of submission. If you have any questions concerning this report, or if you need additional information, please contact **Therron Blatter** at (801) 536-4141.

Sincerely,

Brad T Johnson, Executive Secretary (UST)  
Utah Solid and Hazardous Waste Control Board

BTJ/TKB/bjj

Enclosure

cc: Janice A. Pearson

# Utah Government Owned UST Compliance Report

Owner	Facility ID	# USTs	Facility Name	Address	City	State	Zip
STATE FUEL NETWORK	1200271	2	UDOT STA. # 125	9900 E HWY 39	HUNTSVILLE	UT	84317
	<b>Inspection Date</b>	<b>Citation</b>	<b>Citation Description</b>		<b>Date Resolved</b>		
	05-Apr-07	280.43(D)	Not doing proper automatic tank gauging				
		<b>Actions Taken</b>	<b>Issued</b>	<b>Due</b>	<b>Received</b>		
		Compliance Speed Memo	7/11/2007	8/11/2007			
	<b>Next Action:</b>	Notice of Non-compliance					
STATE FUEL NETWORK	1200360	2	WEBER COUNTY CORP. ROAD DEPT.	2222 S 1900 W	OGDEN	UT	84401
	<b>Inspection Date</b>	<b>Citation</b>	<b>Citation Description</b>		<b>Date Resolved</b>		
	04-Apr-07	280.33(A)	Failure to repair UST system in accordance with accepted codes and standards.				
	04-Apr-07	PEI-RP100	Petroleum Equipment Institute installation standards				
		<b>Actions Taken</b>	<b>Issued</b>	<b>Due</b>	<b>Received</b>		
		Compliance Speed Memo	7/16/2007	10/5/2007			
	<b>Next Action:</b>	Notice of Non-compliance					
STATE FUEL NETWORK	1200423	3	ROY CITY SHOPS	5460 S 2700 W	ROY	UT	84067
	<b>Inspection Date</b>	<b>Citation</b>	<b>Citation Description</b>		<b>Date Resolved</b>		
	04-Apr-07	280.43(F)8	Groundwater monitor wells not marked or secured				
	04-Apr-07	280.43(F)	Not doing proper groundwater monitoring for release detection				
	04-Apr-07	280.43(D)	Not doing proper automatic tank gauging				
	04-Apr-07	280.43(B)	Not doing proper manual tank gauging				
	04-Apr-07	280.31	Operation and maintenance of corrosion protection				
		<b>Actions Taken</b>	<b>Issued</b>	<b>Due</b>	<b>Received</b>		
		Compliance Speed Memo	7/16/2007	9/16/2007			
	<b>Next Action:</b>	Notice of Non-compliance					

Owner	Facility ID	# USTs	Facility Name	Address	City	State	Zip
ARMY & AIR FORCE EXCHANGE SERVICE/DMCR	3000475	3	ARMY & AIR FORCE EXCHANGE SERVICE	BLDG 1210	HILL AIR FORCE BA	UT	84056
	<b>Inspection Date</b>	<b>Citation</b>	<b>Citation Description</b>		<b>Date Resolved</b>		
		280.44(A)2	Failure to perform annual test of automatic line leak detector				
		<b>Actions Taken</b>	<b>Issued</b>	<b>Due</b>	<b>Received</b>		
		Compliance E-mail	6/14/2007	7/14/2007			
	<b>Next Action:</b>	Notice of Non-compliance					
JORDAN VALLEY WATER CONSERVANCY DISTRICT	4000871	1	S.E. REGIONAL WATER TREATMENT PLANT	11574 S 2580 E	SANDY	UT	84070
	<b>Inspection Date</b>	<b>Citation</b>	<b>Citation Description</b>		<b>Date Resolved</b>		
	19-Jun-02	280.20(C)1	Failure to install any spill prevention system.		3/5/2003		
	19-Jun-02	280.20(C)1	Failure to install any overfill prevention system.		3/5/2003		
	19-Jun-02	280.42(B)1	Failure to provide adequate secondary containment of tank for a hazardous substance UST.		3/5/2003		
		<b>Actions Taken</b>	<b>Issued</b>	<b>Due</b>	<b>Received</b>		
		Submitted Closure Plan			3/25/2003		
		Operational Inspection	6/19/2002				
		Speed Memo	7/25/2002	9/23/2002			
		Operational Inspection	6/8/2004				
	<b>Next Action:</b>	Verification Inspection - Temporary Closure					
STATE FUEL NETWORK	4001126	5	UTAH ARMY NATONAL GUARD	7650 S AIRPORT RD	WEST JORDAN	UT	84084
	<b>Inspection Date</b>	<b>Citation</b>	<b>Citation Description</b>		<b>Date Resolved</b>		
	09-May-07	280.41(B)1	Release detection for pressurized piping				
		<b>Actions Taken</b>	<b>Issued</b>	<b>Due</b>	<b>Received</b>		
		Compliance Phone Call	5/14/2007	7/14/2007			
		Notice of Non-compliance	8/1/2007	10/1/2007			
	<b>Next Action:</b>	Notice of Non-compliance					

Owner	Facility ID	# USTs	Facility Name	Address	City	State	Zip
SALT LAKE CITY DEPARTMENT OF AIRPORTS	4001916	2	BUDGET RENT A CAR	641 N 3800 W AMF BOX 22112	SALT LAKE CITY	UT	84122
	<b>Inspection Date</b>	<b>Citation</b>	<b>Citation Description</b>		<b>Date Resolved</b>		
	01-Nov-06	280.43(G)	Not doing proper interstitial monitoring for release detection				
	01-Nov-06	280.44(A)2	Failure to perform annual test of automatic line leak detector		11/29/2006		
		<b>Actions Taken</b>	<b>Issued</b>	<b>Due</b>	<b>Received</b>		
		Compliance Speed Memo	11/2/2006	12/15/2006			
		Compliance Speed Memo	11/30/2006	12/15/2006			
<b>Next Action:</b>	Verification Inspection - Repair of sensor						
SALT LAKE CITY DEPARTMENT OF AIRPORTS	4001918	1	DOLLAR RENT A CAR	601 N 3800 W AMF BOX 22083	SALT LAKE CITY	UT	84122
	<b>Inspection Date</b>	<b>Citation</b>	<b>Citation Description</b>		<b>Date Resolved</b>		
	17-Nov-05	280.43(G)	Not doing proper interstitial monitoring for release detection				
	17-Nov-05	280.44(A)2	Failure to perform annual test of automatic line leak detector		12/3/2005		
		<b>Actions Taken</b>	<b>Issued</b>	<b>Due</b>	<b>Received</b>		
		Compliance Speed Memo	11/18/2005	2/10/2006	12/3/2005		
<b>Next Action:</b>	Notice of Non-compliance						
GRANITE SCHOOL DISTRICT	4001977	1	GRANITE EDUCATION CENTER - CENTRAL PLANT	2500 S STATE STREET	SALT LAKE CITY	UT	84115
	<b>Inspection Date</b>	<b>Citation</b>	<b>Citation Description</b>		<b>Date Resolved</b>		
	14-Sep-06	280.44(A)2	Failure to perform annual test of automatic line leak detector				
		<b>Actions Taken</b>	<b>Issued</b>	<b>Due</b>	<b>Received</b>		
		Compliance E-mail	9/15/2006	10/15/2006			
		Compliance E-mail	12/8/2006	12/15/2006			
		Notice of Non-compliance	5/25/2007	7/25/2007			
<b>Next Action:</b>	Order to Comply						
CARBON COUNTY SCHOOL DISTRICT	5000033	2	CARBON COUNTY SCHOOL DISTRICT	609 E 400 N	PRICE	UT	84501
	<b>Inspection Date</b>	<b>Citation</b>	<b>Citation Description</b>		<b>Date Resolved</b>		

Owner	Facility ID	# USTs	Facility Name	Address	City	State	Zip
04-Jun-07	280.44(A)2		Failure to perform annual test of automatic line leak detector		6/28/2007		
04-Jun-07	280.31(B)1		Failure to meet one 3-year test for cathodic protection system.				
			<b>Actions Taken</b>	<b>Issued</b>	<b>Due</b>	<b>Received</b>	
			Compliance Speed Memo	6/19/2007	7/19/2007		
<b>Next Action:</b>			Notice of Non-compliance				

CITY OF ST GEORGE	6000780	1	ST GEORGE SEWER PLANT	3780 S 1550 W	SAINT GEORGE	UT	84790
Inspection Date	Citation	Citation Description	Date Resolved				
01-Jun-07	280.43	Allowable release detection methods for tanks					
01-Jun-07	19-6-412(1)(b)	7/1/91 Certificate of Compliance required					
01-Jun-07	19-6-407	Notification and update of tanks and facility					
			<b>Actions Taken</b>	<b>Issued</b>	<b>Due</b>	<b>Received</b>	
			Inspection (Operational)	6/1/2007			
			Invoices	6/7/2007			
			Personal Contact (Telephone)	7/31/2007			
<b>Next Action:</b>			Notice of Non-compliance				

US ARMY CORPS OF ENGINEERS	8000053	10	WENDOVER A.F. AUX. (DECKER ) AIR FIELD	~ 95 E 800 S OLD TANK FARM B-1A	WENDOVER	UT	84083
Inspection Date	Citation	Citation Description	Date Resolved				
15-Nov-96	280.70(B)2	Cap and secure lines, pumps, manways and dispensers					
15-Nov-96	280.70(C)	Failure to permanently close or upgrade a temporarily closed tank system after 12 months.					
19-Mar-92	19-6-407	Notification and update of tanks and facility					
19-Mar-92	19-6-408	Non-payment of tank registration fees					
19-Mar-92	19-6-412(1)(b)	7/1/91 Certificate of Compliance required					
19-Mar-92	19-6-413	Tank tightness test required by 6/30/91 or 6 months					
03-Nov-92	19-6-411	Petroleum Storage Tank Fund fee					
03-Nov-92	280.70	Temporary closure					
15-Nov-96	280.70(A)	Failure to continue operation and maintenance of release detection in a temporarily closed tank system.					

Owner	Facility ID	# USTs	Facility Name	Address	City	State	Zip
			<b>Actions Taken</b>	<b>Issued</b>	<b>Due</b>	<b>Received</b>	
			Notice of Non-compliance	3/16/1992	5/16/1992		
			Phone Contact	4/1/1992	5/1/1992		
			Phone Contact	4/2/1992	5/2/1992		
			Verification Inspection	10/28/1992	10/28/1992		
			Sent Information	2/5/1993	3/5/1993		
			Compliance Letter	5/7/1993	7/7/1993		
			Inspection (Operational)	2/10/1998			
			Letter	9/21/1999	12/22/1999		
			Referred to EPA Region VIII	4/10/2006			
			Personal Contact (E-mail)	7/12/2006			
			Submitted Closure Plan	10/19/2006		10/19/2006	
			Personal Contact (E-mail)	10/23/2006		10/23/2006	
			Personal Contact (E-mail)	10/23/2006			
			Submitted Closure Plan	7/17/2007		7/17/2007	
			Approved Closure Plan	7/23/2007			
			<b>Next Action:</b>				
			UST Closure Inspection				