



State of Utah
Department of
Environmental Quality

Richard W. Sprott
Executive Director

Division of Radiation Control
Dane L. Finerfrock
Director

JON M. HUNTSMAN, JR.
Governor

GARY HERBERT
Lieutenant Governor

August 6, 2008

Mr. Harold R. Roberts
Executive Vice President – US Operations
Denison Mines (USA) Corp. (DUSA)
1050 17th Street, Ste. 950
Denver, CO 80225

Dear Mr. Roberts:

SUBJECT: August 1, 2008 DUSA Response to Request for Information; July 22, 2008 DRC Findings and Request for Information; July 2, 2008 DUSA Cell 4A *Construction Quality Assurance Report*; **Request for Information**

We received the subject response to our request for information on August 4, 2008. The response contained the as-built primary and secondary liner drawings by Comanco construction and the final revised construction drawings of the original seven sheets by GeoSyntec Consultants.

We have reviewed the referenced submittals, and have comments, which follow the numeric format of our previous letter of July 22, 2008:

1. We note that the work of correcting the sandbag covering of the strip-drains, mentioned in previous correspondence, is progressing as documented in the photographs sent by DUSA on compact disk, received August 1, 2008. Our comments regarding that work will be pursued under separate cover.
2. An explanation regarding the repairs on the production seam summary log on pages 77/103 and 79/103 was received. However, the Comanco drawings for the primary liner do not show any panel numbers, as referenced in the explanation. Please provide a revised drawing showing the panel numbers for the primary liner.
3. Regarding location coordinates, the survey drawings from Comanco (Jones & DeMille Engineering) show the vertical elevations of numerous piping, drains, sumps etc. Please inform us of the extent of information you have regarding horizontal coordinates. Also, please supply the horizontal coordinates of important facilities in the LDS and slimes drain system such as beginning and end of sumps, "spine backbone" header pipes, collector drains to the headers, etc.
4. No comment.

Mr. Harold R. Roberts

August 6, 2008


Page 2

5. No comment.

6. No comment.

Please review the above comments, and submit the requested information. If you have any questions on the above, please contact me.

Sincerely,



David A. Rupp, P.E.

Geotechnical Services Section

DR:dr

Cc: Mr. Ron Hochstein, President DUSA
Mr. Greg Corcoran, GeoSyntec Consultants

F:\drupp\DUSA\4A\Completion Report\Request for Information 08-06-08