



INTERLOCK DESCRIPTION

408-1 IF O2 NOT BETWEEN 19.5% AND 22% OR LEL ABOVE 20% HORN BLOWS FOR 30 SEC, RED LIGHT FLASHES, PUMP SOLENOID CLOSES.

408-2 IF FAN STOPPED PUMP SOLENOID CLOSES

REVISIONS						REVISIONS					
NO	DESCRIPTION	DATE	BY	CHK	ENG MGR	NO	DESCRIPTION	DATE	BY	CHK	ENG MGR
AS-BUILT		04-05-22	KB	TH	KB	AS BUILT DECANTING INTO DBV		3-29-00	DVC		
AS BUILT UPDATE		01-13-94	DCP	GVC	CHW	ADD COMPATIBILITY STATION AND GENERAL REVISION		7-5-06	KDL		
NEW CRDN HOUSE, FAN, FLW MTRS		05-11-94	DCP			ADD CONTROL VALVE FOR DECANT PURGE, AND		11/02/15	MJM	LB	
TO CORRECT DRAFTING ERRORS		04-08-98	CRM			2015 PSM-PHA REQUIRED UPDATES.					
ADDED BACKFLOW PREVENTER		2-15-00	GVC			2ND DECANT PUMP, REMOVE ABANDON IN PLACE.		4-16-19	JWR		JWR

APPROVALS

BY	DATE
DCP	03-01-95
AS BUILT	

REGISTERED PROFESSIONAL ENGINEER
DATE:

Clean Harbors
BRANDTITE LLC

UTAH ENVIRONMENTAL SERVICE CENTER
INCINERATION PLANT FOR INDUSTRIAL WASTES
BLDG. E-4 DECANT P&ID

FOR: TOOELE SITE
SCALE: JOB NO:

CAD NO. I4137N
APTUS DWG NO. D-800-PI-408
REV. 8

