
Great Salt Lake
Waterfowl Management Areas
5 0 5 10 Miles
N
Locamotive Springs WMA 2B 3B 3D
Public Shooting Grounds WMA 2B 3C 3D
Bear River NWR
NWR
NWR
Promontory Mountains
Gunnison Bay 5B
Bear River Bay 5C
Harold Crane WMA 2B 3C 3D
Ogden Bay WMA 2B 3C 3D
Howard Slough WMA 2B 3C 3D
Gilbert Bay 5A
Antelope Island
Farmington Bay 5D
Farmington Bay WMA 2B 3C 3D
Timpie Springs WMA 2B 3B 3D
gsl wma.apr