

**Voluntary Cleanup Program/Brownfields Section
Sites at Which Response Actions are Planned or Have Been Completed (Calendar Years 2018-2019)**

Site Name	Address and City	Latitude/ Longitude	Name of Owner at Time of Cleanup	Type of Site	Assessment or Cleanup	Date Response Action is Planned	Date Response Action Completed	Unrestricted Land Use? (Y/N)	Land Use and Institutional Controls Specified in the Certificate of Completion	General Nature of Contamination	Site Size (Acres)
GENEVA NITROGEN VCP-C036	1165 NORTH 1600 WEST VINEYARD, UT	40°19'16" 111°49'29"	Geneva Nitrogen	Commercial Manufacturing	Assessment and Cleanup	Summer 2019	Cleanup not started	Cleanup not complete	Proposed but not outlined in this table until the response action as specified in the Remedial Action Plan is verified complete and a Certificate of Completion is issued. Free product removal on-going. Completing risk assessment.	Petroleum, Solvents	27.0
PRAXAIR 2300 EAST VCP-C049	6880 SOUTH 2300 EAST SALT LAKE CITY, UT	40°37'38" 111°49'32"	Praxair Corporation	Commercial Distribution	Assessment and Cleanup	Winter 2012	On-going	Cleanup not complete	Proposed but not outlined in this table until the response action as specified in the Remedial Action Plan is verified complete and a Certificate of Completion is issued. Vapor mitigation system currently operating.	Solvents	4.0
BROWN-STRAUSS STEEL VCP-C052	800 SOUTH CHESTNUT STREET SALT LAKE CITY, UT	40°45'9" 111°57'24"	Brown-Strauss Steel	Commercial Manufacturing	Assessment and Cleanup	Summer 2011	On-going	Cleanup not complete	Proposed but not outlined in this table until the response action as specified in the Remedial Action Plan is verified complete and a Certificate of Completion is issued. Sand blast grit removed in 2008. Groundwater remediation/monitoring on-going.	Lead, PAHs, Solvents	30.3
SILVER POINTE VCP-C053	145 ACRES NORTHWEST OF I-15 EXIT 23 LEEDS, UT	37°14'38" 113°21'41"	Crocker Capital, LLC	Vacant - Former Mine	Assessment and Cleanup	Fall 2013	On-going	Cleanup not complete	Proposed but not outlined in this table until the response action as specified in the Remedial Action Plan is verified complete and a Certificate of Completion is issued. Phase I soil removal completed March 2015. Site Management Plan and Environmental Covenant currently being developed.	Lead, Mercury, Uranium	143.4
CHROMALOX VCP-C073	2150 NORTH RULON WHITE BLVD OGDEN, UT	41°17'53" 112°0'38"	Chromalox, Inc.	Commercial Manufacturing	Assessment and Cleanup	Summer 2016	On-going	Cleanup not complete	Proposed but not outlined in this table until the response action as specified in the Remedial Action Plan is verified complete and a Certificate of Completion is issued. Interim remedial measures initiated in 2016 per Remedial Action Plan.	Solvents	14.0
OGDEN GAS COMPANY SITE VCP-C074	LINCOLN AVENUE AND RUSHTON STREET OGDEN, UT	41°13'49" 111°58'37"	Naylor Family	Commercial	Assessment and Cleanup	Summer 2014	On-going	Cleanup not complete	Proposed but not outlined in this table until the response action as specified in the Remedial Action Plan is verified complete and a Certificate of Completion is issued. Phase I soil removal completed October 2014. Further removal in winter 2019. Groundwater investigation on-going.	PAHs, Cyanide, Benzene	1.7
FAMILY CENTER AT FORT UNION VCP-C079	900 FORT UNION BLVD MIDVALE, UT	40°37'21" 111°51'41"	DDR Corporation	Commercial	Assessment and Cleanup	Fall 2014	On-going	Cleanup not complete	Proposed but not outlined in this table until the response action as specified in the Remedial Action Plan is verified complete and a Certificate of Completion is issued. Vapor mitigation system currently operating.	Solvents	8.1

Notes:

The information in this table is for general use only. All interested parties are encouraged to review the project file for further detail.

Sites closed prior to 2018 or that may currently be in early portions of the site characterization phase are not included in this table. Please refer to the Voluntary Cleanup Program list.

**Voluntary Cleanup Program/Brownfields Section
Sites at Which Response Actions are Planned or Have Been Completed (Calendar Years 2018-2019)**

Site Name	Address and City	Latitude/ Longitude	Name of Owner at Time of Cleanup	Type of Site	Assessment or Cleanup	Date Response Action is Planned	Date Response Action Completed	Unrestricted Land Use? (Y/N)	Land Use and Institutional Controls Specified in the Certificate of Completion	General Nature of Contamination	Site Size (Acres)
ALTA GATEWAY VCP-C082	100-160 SOUTH 500 WEST SALT LAKE CITY, UT	40°45'58" 111°54'21"	Wood Partners	Residential Development	Assessment and Cleanup	Spring 2015	11/1/2018	No	Comply with the Site Management Plan and Environmental Covenant. No access to groundwater for drinking water, irrigation or bathing purposes.	PAHs, Lead	3.2
REFINERY WASTE DUMP VCP-C083	3201 NORTH 3250 WEST SALT LAKE CITY, UT	40°50'29" 111°58'18"	Atlantic Richfield Company	Vacant - Undeveloped	Assessment and Cleanup	Fall 2019	Cleanup not started	Cleanup not complete	Proposed but not outlined in this table until the response action as specified in the Remedial Action Plan is verified complete and a Certificate of Completion is issued. Remedial pilot study completed Summer 2017.	Petroleum	20.0
OGDEN BUSINESS EXCHANGE PHASE I VCP-C084	600 WEST EXCHANGE ROAD OGDEN, UT	41°13'32" 111°59'31"	Ogden Redevelopment Agency	Commercial	Assessment and Cleanup	Winter 2015	2/15/2018	No	Commercial land use. No schools, hospitals, day cares, residential uses. No access of groundwater for drinking water, irrigation or bathing purposes.	PAHs, Lead	48.0
CENTRO CIVICO MEXICANO VCP-C087	155 SOUTH 600 WEST SALT LAKE CITY, UT	40°45'57" 111°54'28"	Centro Civico Mexicano	Residential Development	Assessment and Cleanup	Summer 2017	12/18/2018	No	COC issued for Parcel B. Comply with the Site Management Plan and Environmental Covenant. No access to groundwater for drinking water, irrigation or bathing purposes.	PAHs	1.2
KINGS FIRST STOP AUTO REPAIR AND TOM RANDALL DISTRIBUTING COMPANY VCP-C089	143 SOUTH MAIN STREET LAYTON, UT	41°3'30" 111°57'51"	North Utah Holdings	Mixed Use Development	Assessment and Cleanup	Summer 2017	On-going	Cleanup not complete	Proposed but not outlined in this table until the response action as specified in the Remedial Action Plan is verified complete and a Certificate of Completion is issued. Phase I soil removal initiated at the Kings facility in late 2017.	Petroleum	1.4
THE MAYFLOWER MINE AND ASSOCIATED AREAS IN THE BLUE LEDGE MINING DISTRICT VCP-C090	U.S. HIGHWAY 40, NEAR MAYFLOWER HIGHWAY EXIT 8 HEBER CITY, UT	40°37'1" 111°26'22"	BLX Mayflower, LLC	Mixed Use Development	Assessment and Cleanup	Summer 2019	Cleanup not started	Cleanup not complete	Proposed but not outlined in this table until the response action as specified in the Remedial Action Plan is verified complete and a Certificate of Completion is issued. Remedial Action Plan proposed for Phase I.	Lead, Metals	2278.0
DALTON'S EDGE MULTI- FAMILY VCP-C091	1040 SOUTH 400 WEST SALT LAKE CITY, UT	40°44'48" 111°54'5"	1030 Salt Lake City, LLC	Commercial	Assessment and Cleanup	Summer 2019	Cleanup not started	Cleanup not complete	Proposed but not outlined in this table until the response action as specified in the Remedial Action Plan is verified complete and a Certificate of Completion is issued. Remedial Action Plan proposed for site in February 2019.	Petroleum	2.8
AIRPORT WEST VCP-C092	581 NORTH JOHN GLENN ROAD SALT LAKE CITY, UT	40°46'40" 112°3'11"	SITLA	Commercial Development (former landfill)	Assessment and Cleanup	Fall 2019	Cleanup not started	Cleanup not complete	Proposed but not outlined in this table until the response action as specified in the Remedial Action Plan(s) is verified complete and a Certificate of Completion is issued. Site characterization on-going.	Solvents, Metals, Petroleum	769.9

Notes:

The information in this table is for general use only. All interested parties are encouraged to review the project file for further detail.

Sites closed prior to 2018 or that may currently be in early portions of the site characterization phase are not included in this table. Please refer to the Voluntary Cleanup Program list.

**Voluntary Cleanup Program/Brownfields Section
Sites at Which Response Actions are Planned or Have Been Completed (Calendar Years 2018-2019)**

Site Name	Address and City	Latitude/ Longitude	Name of Owner at Time of Cleanup	Type of Site	Assessment or Cleanup	Date Response Action is Planned	Date Response Action Completed	Unrestricted Land Use? (Y/N)	Land Use and Institutional Controls Specified in the Certificate of Completion	General Nature of Contamination	Site Size (Acres)
UTA LOTS VCP-C093	4800 SOUTH BOX ELDER STREET MURRAY, UT	40°39'58" 111°53'34"	Murray City	Commercial	Assessment and Cleanup	Winter 2018	On-going	Cleanup not complete	Proposed but not outlined in this table until the response action as specified in the Remedial Action Plan is verified complete and a Certificate of Completion is issued. Remedial work on-going.	Lead, Arsenic	2.7
GRANTON SQUARE VCP-C094	118 WEST 4800 SOUTH MURRAY, UT	40°40'4" 111°53'38"	Hamlet Square III, LLC	Mixed Use Development	Assessment and Cleanup	Fall 2018	2/27/2019	No	Comply with the Site Management Plan and Environmental Covenant. No access to groundwater for drinking water, irrigation or bathing purposes.	Lead, Arsenic	6.5
FORMER HENRIES DRY CLEANER - 9TH SOUTH VCP-C096	906 SOUTH 200 WEST SALT LAKE CITY, UT	40°44'58" 111°53'50"	Urban 9th, LLC	Mixed Use Development	Assessment and Cleanup	Spring 2019	Cleanup not started	Cleanup not complete	Proposed but not outlined in this table until the response action as specified in the Remedial Action Plan is verified complete and a Certificate of Completion is issued. Remedial Action Plan accepted January 2019.	Solvents	0.9

Notes:

The information in this table is for general use only. All interested parties are encouraged to review the project file for further detail.

Sites closed prior to 2018 or that may currently be in early portions of the site characterization phase are not included in this table. Please refer to the Voluntary Cleanup Program list.