



State of Utah

Department of
Environmental Quality

Dianne R. Nielson, Ph.D.
Executive Director

DIVISION OF RADIATION
CONTROL
Dane L. Finerfrock
Director

JON M. HUNTSMAN, JR.
Governor

GARY HERBERT
Lieutenant Governor

November 9, 2006

Mr. Harold Roberts
Vice President – Corporate Development
International Uranium (USA) Corporation
1050 Seventeenth Street, Suite 950
Denver, CO 80265

Re: October 6, 2006 DRC Round 5 Interrogatory on the Cell 4A Lining System Design Report;
October 20, 2006 GeoSyntec Consultants letter regarding a Geosynthetic Clay Liner Hydration
Demonstration Work Plan for International Uranium Corporation, White Mesa Mill, Cell 4A

Dear Mr. Roberts,

On October 20, 2006 we received the subject letter from GeoSyntec Consultants regarding a Geosynthetic Clay Liner Hydration Demonstration Work Plan. Similar to previous work, URS staff performed this review and prepared a Technical Memorandum, which is attached for your consideration and resolution.

As you are aware, the review schedule projected in our current memorandum of agreement is unfeasible. We suggest a new schedule be determined. Please contact us to do this.

Sincerely,

David A. Rupp, P.E.
Geotechnical Services Section

DAR:dr

Attachment

cc: Greg Corcoran, GeoSyntec Consultants
Britt Quinby, URS Corporation

F:/drupp/.../GCL Hydration Issues URS Tech Memo
File: IUC Cell 4A Relining Project