

SPENCER J. COX Lieutenant Governor

## Department of Environmental Quality

Amanda Smith
Executive Director

DIVISION OF SOLID AND HAZARDOUS WASTE Scott T. Anderson Director Solid and Hazardous Waste Control Board

Kevin Murray, Chair
Dennis Riding, Vice-Chair
Eugene Cole, DrPH
Jeff Coombs, MPH, LEHS
Mark Franc
Brett Mickelson
Amanda Smith
Shane Whitney
Dwayne Woolley
Scott T. Anderson
Executive Secretary

April 7, 2014

Maloy Dodds Garfield County Commissioner P.O. Box 77 Panguitch, Utah 84759

RE: Compliance Evaluation Inspection

Garfield County Ticaboo Class II Landfill

Dear Commissioner Dodds:

On, March 19, 2014, the Garfield County Ticaboo Class II Landfill was inspected by a representative of the Division of Solid and Hazardous Waste to determine compliance with the Utah Solid Waste Permitting and Management Rules and the landfill permit. Enclosed is a copy of the inspection checklist and copies of the photographs taken during the inspection.

During the inspection, the inspector documented the following operational issues:

- All the mattresses, boats and other non-construction and demolition material need to be removed from the C&D waste cell. This material is not allowed in this cell. It can be placed in the MSW waste cell.
- There was a lack of daily soil cover on the municipal solid waste. If the facility is only open two to three days per week, please make sure there is adequate soil cover prior to closing the landfill for several days.

Please provide a written response to the Division by May 15, 2014 outlining procedures to be implemented to address these issues.

If you have any questions, please call Rob Powers at (801) 536-0255.

Sincerely,

Scott T. Anderson, Director

Division of Solid and Hazardous Waste

STA/RDP/kl

(Over)

DSHW-2014-005479

Enclosure: Inspection checklist and photographs

c: David Blodgett, M.D., Health Officer/Director, Southwest Utah Public Health Dept. Robert Beers, MBA, EHS, Environmental Health Director, Southwest Utah Public Health Dept. Paul Wright, P.E., DEQ District Engineer Brian Bremner, Garfield County Engineer

### SOLID WASTE FACILITY INSPECTION REPORT CHECKLIST

### UTAH DIVISION OF SOLID & HAZARDOUS WASTE

Location         Inspection Date       3/19/14       Time In       Time Out         Routine Oversight       ✓ Follow up       ✓ Monitoring Evaluation       ✓ Facility Status       ✓ Construction Review         Announced       ✓ Unannounced       ✓ Weather Conditions       Sunny and warm			
Routine Oversight  Follow up  Monitoring Evaluation  Facility Status  Construction Review [			
Tubinity Status Construction review			
Announced Unannounced Weather Conditions Sunny and warm			
- Sum Julia Halli			
Inspection Goal Compliance with the Utah Solid Waste Rules and conditions of the approved landfill permit			
Facility Contact Brian Bremner			
Participants Rob Powers			
FOLLOW UP INSPECTION NEEDED Yes No Recommended Follow Up Date			
(X – indicates items reviewed)			
1. PRE-INSPECTION REVIEW			
1.1 Permit Review			
☐ 1.2 Annual Report Review			
3. SIGNS REQUIRED / PROPERLY POSTED			
<ul> <li>✓ 1.3 Previous Inspection Review</li> <li>✓ 3.1 Operating Days / Hrs.</li> <li>In compliance</li> </ul>	_		
□ 3.2 Directions & Procedure	$\dashv$		
1.4 Facility Contacts Confirmed	$\dashv$		
□ 3.3 Emergency Numbers	$\neg$		
Unannounced			
□ 3.4 List of Unacceptable Materials			
□ 35 Other	-		
1.7 Other	-		
	_		
2. FACILITY / OPERATIONAL CONTROLS  4. OPERATOR / REPRESENTATIVE / EMPLOYEES			
□ 2.1 Litter □ 4.1 On-site while open			
Litter needs to be picked up east and south of the working face. This  In compliance	$\dashv$		
should not leave the boundaries of the landfill.  4.2 Training			
should not leave the boundaries of the landfill.    2.2 Roads   4.2 Training			
should not leave the boundaries of the landfill.    2.2 Roads			
should not leave the boundaries of the landfill.    2.2 Roads			
should not leave the boundaries of the landfill.    2.2 Roads			
should not leave the boundaries of the landfill.    2.2 Roads			
should not leave the boundaries of the landfill.    2.2 Roads			
should not leave the boundaries of the landfill.    2.2 Roads			
should not leave the boundaries of the landfill.    2.2 Roads			
Should not leave the boundaries of the landfill.			
should not leave the boundaries of the landfill.			
should not leave the boundaries of the landfill.    2.2 Roads			
should not leave the boundaries of the landfill.			
should not leave the boundaries of the landfill.			
should not leave the boundaries of the landfill.			
should not leave the boundaries of the landfill.			
should not leave the boundaries of the landfill.			
should not leave the boundaries of the landfill.			
should not leave the boundaries of the landfill.			
should not leave the boundaries of the landfill.			
should not leave the boundaries of the landfill.			

#### SOLID WASTE FACILITY INSPECTION REPORT

Date: 3/19/14 Facility Name: Garfield Count	y Ticaboo Class II landfill
7.2 Batteries	9.8 Self Inspection (Quarterly) Reports
☐ 7.3 Hazardous Waste	9.9 Deviation from Plans
NA	7.7 Deviation from Flans
7.4 Infectious Waste	9.10 Permit, Permit Application and Rules Available
7.5 Tires	9.11 Other
The Thes	9.11 Otilei
7.6 Dead Animals	
☐ 7.7 Asbestos	10. MONITORING / SAMPLING / ANALYSIS RECORDS  10.1 Explosive Gas Monitoring
In compliance	NA 10.1 Explosive Gas Monitoring
☐ 7.8 Bulky Waste	□ 10.2 Leachate Sampling & Treatment
7.9 Contaminated Soil	NA    10.3 Ground Water Sampling Results
7.10 Ash	☐ 10.4 Other
7.11 Sludge	
/.11 Sludge	11. SPECIAL WASTE RECORDS
	11.1 Lab Analysis Results
Construction and demolition wastes. Boats, mattresses, furniture and other non C&D wastes needs to be removed and placed into	[ ] 112.Marifests
the MSW cell.	11.2 Manifests
a cover	☐ 11.3 Treatment Certification
8. COVER  8.1 Daily – Soil	TI III A D. A F. III TI A D. A.
Need to cover the waste with at least six inches of cover soil every	11.4 Paint Filter Test Results
day the landfill is in operation.	11.5 Onsite Treatment Documentation
8.2 Daily – Alternative	
8.3 Intermediate	11.6 Other
0.45	
8.4 Final	12. SPECIAL PERMIT REQUIREMENTS  12.1
8.5 Vegetation	12.1
	□ 12.2
8.6 Other	
9. INSPECTION RECORDS  9.1 Random Inspection Report	
□ 9.1 Random Inspection Report  Not reviewed	13. OTHER ITEMS
	Completed
NA	13.2
<ul> <li>✓ 9.3 Surface Drainage Control</li> <li>In compliance</li> </ul>	
□ 9.4 Daily Records	□ 13.3
Not reviewed	□   13.4
□ 9.5 Weight or Volumes  Not reviewed	
9.6 Intermediate Cover	□   13.5
9.7 Final Cover	
DSHW Inspector Signature:	

Page 2 of 2

4/01/14

Date:

DSHW Inspector Name (type or print): Rob Powers

# GARFIELD COUNTY TICABOO CLASS II LANDFILL INSPECTION MARCH 19, 2014



Entrance sign to the landfill



Looking west towards the old scale house



Looking south at the steep working face of the landfill




Looking at the working face and the lack of daily soil cover



Green waste pile



Looking west at the C&D waste cell. The boats, mattresses, furniture and other items that do not meet the definition of construction and demolition waste need to be removed and placed into the Class II MSW cell for final disposal.



Looking northwest at the boats in the C&D waste cell



Mattresses that need to be compacted and covered.



Litter along the south fence line that needs to be picked up and placed into the MSW cell.