

**SUMMARY OF DOCUMENTS
 UTAH DIVISION OF RADIATION CONTROL
 CELL 4A LINING SYSTEM – DENISON MINES CORPORATION
 WHITE MESA MILL BLANDING, UTAH**

	Document	Date	Comment #1	Comment #2
1	REVISED TECHNICAL SPECIFICATIONS For the Construction of Cell 4A Lining System, (Prepared by Geosyntec Consultants)	June 2007		
2	REVISED CONSTRUCTION QUALITY ASSURANCE PLAN for the Construction of Cell 4A Lining System, (Prepared by Geosyntec Consultants)	June 2007		
3	Revised Geosynthetic Clay Liner Hydration Demonstration Work Plan, (Prepared by Geosyntec Consultants)	March 27, 2007	Per conditions in DRC letter dated May 2, 2007	
4	Cell Seismic Study, (Prepared by MFG Consulting Scientists and Engineers)	November 27, 2006	As clarified by Round 6 Interrogatories dated February 8, 2007	
5	Calculation of Action Leakage Rate Through The Leakage Detection System Underlying a Geomembrane Liner (Prepared by Geosyntec Consultants)	October 6, 2006		
6	Settlement Evaluation of Berms (Prepared by Geosyntec Consultants)	June 23, 2006	As clarified by Round 6 Interrogatories dated February 8, 2007	
7	Pipe Strength Calculations (Prepared by Geosyntec Consultants)	August 22, 2006		

SUMMARY OF DOCUMENTS
UTAH DIVISION OF RADIATION CONTROL
CELL 4A LINING SYSTEM – DENISON MINES CORPORATION
WHITE MESA MILL BLANDING, UTAH

8	Slope Stability Analysis Cell 4A – Interim Conditions (Prepared by Geosyntec Consultants)	June 22, 2006		
	Drawings			
9	Title Sheet	June 2007	Sheet 1 of 7	
10	Site Plan	June 15, 2007	Sheet 2 of 7	Rev. 1
11	Base Grading Plan	June 15, 2007	Sheet 3 of 7	Rev. 1
12	Pipe Layout Plan	June 15, 2007	Sheet 4 of 7	Rev. 1
13	Lining System Details I	June 15, 2007	Sheet 5 of 7	Rev. 1
14	Lining System Details II	June 15, 2007	Sheet 6 of 7	Rev. 1
15	Lining System Details III	June 15, 2007	Sheet 7 of 7	Rev. 1