ear River	COUNTY		1		The state of the s	A contract of the contract of	11	1
		Owner name	City	State	System Type 2= Gravity; 3= Alternative	IN/OUT of compliance	Other- corrections, etc.,	Enforcement Actions Taken
ar River	Cache	USU	Wellsville	UT	2	IN- report 7/31/12 d-box repaired	In- new access risers installed	
	Cache	Cache Valley School Dist.	Logan	UT	3-Pressure	IN= Report 7/25/12		
ar River	Box Elder	Delbert Olsen	Snowville	UT	2- 8,070gpd		Limited use to rv park per letter from owner, will not be inspecting tanks this year.	
							will not be inspecting tanks this year.	
ear River	Box Elder	Marble Hills HOA	Thatcher	UT	2- 30 connections	IN- report 7/31/12 d-box repaired		
ar River	Box Elder	Gary Coleman	Willard	UT	2- 9So., 16No.MH		System repaired without approval or final inspection-out of compliance	
ar River	Box Elder	Cache Valley School Dist.	Brigham	UT	3-Pressure Dist, grease trap 8,500gpd	IN- New system 7/12	New system installed July 2012	
ar River	Rich	Richard County Schools	Randolph	UT	2 schools share system in Randolph and 2 schools share system in Laketown	IN- insp. 8/1/12 by County Health personnel		
vis	Davis	Utah State University	Logan	UT	3-Experimental System 170gpd	OUT- no annual report as of 8/7/12	IN- sample results included	
oele	Tooele	ATI Titanium, LLC	North Skull Valley	UT	3-Pressure 2-systems	·	IN- 7/31/12	
oele	Tooele	Excelsior Charter School	Tooele	UT	3-Pressure	IN- report 7/30/12	IN-Grease trap cleaned	
mmit	Summit	Town of Echo	Echo	UT	2	, , , , , , , , , , , , , , , , , , , ,	Under enf. Order of replacing LUWDS with Board	
						OUT- annual report showers draining	Enf. Letter sent 7/12. Received letter from BSA 8/6/12- shower house closed down, in	
ımmit	Summit	BS of America	Salt Lake City	UT	10,500gpd- Pressure System, grease trap	into pump tank, not turned on	process of making corrections.	
ımmit	Summit	BS of America	Salt Lake City	UT	7,000gpd- Pressure System, grease trap	OUT- system not turned on	Letter sent 7/ 2012	
nmit	Summit	LDS Church	Salt Lake City	UT	2- 7,000gpd	IN- report 7/30/12		
						OUT- no annual report as of 8/7/12.		
County	Uinta	Larry Murry	Vernal	UT	3- Pressure	2011 inspection- only one inspection made (requires two).	2011- letter sent	
County	Uinta	Bob Brown	Vernal	UT	Gravity, 24RV spaces, 27 mobile home spaces		tanks pumped 2Xyear (next in September)	
County t Lake	Daggett Salt Lake	Mark Wilson Emigration Oaks HOA	Dutch John Salt Lake City	UT UT	2-pump to gravity, 14,710gpd 2-pump to gravity-2 systems for 6 lots	IN- 7/12		
						IN- plans to replace df this year 2012,		
t Lake	Salt Lake	Kennecott, Corp.	West Jordan	UT	3- pressure system	new location.  IN- report sent in 8/9/12 with sample		
asatch	Wasatch	Brent Hill	Midway	UT	3-Advantax with drip dispersal	results		
satch	Wasatch	Suzanne Goodfellow	Heber	UT	<u></u>	IN- 7/30/12	maint.person reported that risers need to be	
satch	Wasatch	LDS Church	Salt Lake City	UT	2-Girls shower+1 rv	IN	installed.	
ah	Utah	BYU University	Provo	UT	2-Pump to gravity;20,732gpd; expansions need DWQ approval	IN- report 5/29/12	IN- filter partially plugge, cleaned	
							IN- 2nd year in a row, tanks needpumping	
ah	Utah	Utah County	Provo	UT	2	OUT- no annual report as of 8/7/12	(never were pumped!) Letter sent	
ntral	Piute Piute	Dee Lynn Faulin Jim & Terry Peterson	Marysville Marysville	UT UT	2 2- 10,460gpd	IN- report 5/1/2012 OUT- will submit at end of season	Needs pumping ST on row 5 needs pumping, ms notified to	
ntral ntral	Piute	Piute County School district	Junction	UT	New ST 10,000gal, 5,625gpd	IN- 7/30/12	or or row o needs partiping, this notified to	
ntral	Sanpete	Douglas M. Draper	Mt.Pleasant	UT	2-3 systems;46spaces	OUT- no annual report as of 8/7/12	IN- line our of d-box discovered crushed- was replaced	
ntral	Sanpete	Div.State Parks and Recreation	n Sterling	UT	4-ST, one pump to gravity (grinder pump)	IN- still needs ongoiing flow monitoring	Needs flow meter, flushing/vaccuming df	
ntral	Millard	Travis Kesler	Kanosh	UT	2-33RV's+3washer laundramat	OUT-no annual report as of 8/7/12	IN- Tank was pumbed	
ntral	Millard	Dave & Corinne Lewis (new)	Fillmore	UT	2- 3 systems	IN	Trench #3, repaired since last year	
ntral	Millard	Clint Conder	Scipio	UT	2- 5,955gpd	IN	. ,	
ntral	Millard	Gary Perea	Baker	NV	2- Motel and 19 spaces Rvpark- df. In Utah)	OUT- no annual report as of 8/7/12		
ntral	Sevier	Tim Christensen (new owner since March '12)	Monroe	UT	2- Carwash 2,000gpd	OUT- no annual report as of 8/7/12		
entral	Sevier	Kinley Peterson		UT	2- Car Wash and store	IN 7/12		
entral	Seviei	Milley Peterson	Elsinore	UI	z- Car wash and store	IIN 7/1Z		

8/20/2012 Page 1 of 2

EALTH DISTRICT	COUNTY	Owner name	City	State	System Type 2= Gravity; 3= Alternative	IN/OUT of compliance	Other- corrections, etc.,	Enforcement Actions Taken
entral	Wayne	Robert Brian	Loa	UT	2- carwash+auto shop	IN- report 7/28/12	Reports that tank is pumped yearly	
		Chris Johnson, Capital Reef			·			
entral	Wayne	Properties	Jackson	WY	2	IN- 7/12	IN- letter sent, all tanks need pumping	
entral	Wayne	Newell Harward, Redridge Special Service Dist.	Loa	UT	2	IN	individual tanks are owners responsibility	
						IN- all tank have been pumped, 1 tank	. ,	
entral outheast	Wayne Carbon	Southey Swede	Torrey	UT UT	2- 100seat restaurant, 10 unit motel = 2- 15,000gpd	needs lid repair and lock	numped out topks july 2011	
utheast	Carbon	Schofield SSD	Wellington Price	UT	2-multible systems	IN- reports 7/30/12	pumped out tanks july 2011	
					·	IN- report 7/31/12 (little information, just		
utheast	Carbon	Schofield Town	Helper	UT	2-pump to gravity, mult.systems 2-pump to gravity, Rvpark, store/gas station	est.flow) IN- st's pumped Mar. 2012 & filters		
utheast	Grand	Reed Slingleland	Durango	со	11,650gpd	cleaned	IN- Jim Adamson inspected	
utheast	Grand	Mark Stuenkel	Moab	UT	2-RV park- 2 systems	IN	tanks pumped 7/12- pump discharge leaking,	
the a set	0 1	Crair Siranaa	DI- #	UT	O. Bostoniand and Cit Chan	INI	Defficience corrected #4 tools peeds promine	
outheast	San Juan	Craig Simpson	Bluff	UT	2- Restaruand and Gift Shop	IN	Baffle was corrected, #1 tank needs pumping	
outheast	San Juan	San Juan School District	Blanding	UT	2- 3,125gpd (repaired in 2001)	OUT- no annual report as of 8/7/12	IN- recently pumped	
outheast	San Juan	San Juan School District	Banding	UT	2- 17,100 has grease trap	OUT- no annual report as of 8/7/12	IN- recently pumped	
outheast	San Juan	Amer & Cindy Tumeh	Bluff	UT	2 2 17,100 has grease trap	IN 7/12	Inv-recently pumped	
outheast	San Juan	Phil Glaze	Monticello	UT	2- 23 lots in subdivision	IN 7/12		
						repair/replacement, but it is still	9/11 rec. letter, d-box will be repaired in	8/1/12 report- no info on repair on report, MS
outhwest	Iron		Cedar City	UT		functioning.	"spring of 2012"	called made re-visit.
uthwest	Iron		Henderson	NV	2- 12 cabins, 2 tent sites, common kitchen	OUT- no annual report as of 8/7/12		
uthwest	Iron	Iron County School District	Cedar City	UT	2	IN		
outhwest	Garfield	Ron Stunich	Hatch	UT	6,000gpd, 120 RV pads	IN		
uthwest	Garfield	Closed 2 weeks ago 8/23/11 Harold Straton	Panguitch	UT	2- 6,300gpd, grease trap 2- Restaurand, may have motel on system	closed facility	IN- reported 7/17/12	
uthwest	Garfield	naroid Stratori	Panguitch	UT	2- Restaurand, may have moter on system		IN- reported 7/17/12	
uthwest	Garfield		Bryce	UT	2	IN- report 8/1/12 tank needs pumping		
uthwest	Garfield	John Hawkes	Cannonville	UT	3-Pressure 10,875gpd; 62 RV+Cabins; 18 tent sites	IN	IN-7/20/11	
uthwest	Garfield		Cannonville	UT	2- 26 unit hotel + convenience store	IN		
					2-Motel, Restaurant, country store and			
outhwest	Garfield		Bryce	UT	campground;q=11,779  2- Store & Shop and RV connections on 6 separate	IN- report 7/21/12	ST should be cleaned out in the next month	
uthwest	Garfield	Harold Bertola	Lake Powell	UT	drainfields	OUT- no annual report as of 8/7/12	or two"	
4	Gamera	. Idioid Boiloid	Zano i ovon	0.	2-Jennifers Kitchen (40seats), convience store and	00 : 110 di inidai report de 6: 0/1/12	or the	
uthwest	Garfield	Bill & Jennifer Wells	Ticaboo	UT	gas station	Not open this season (2011)	OSS- need more info. Due 8/10	
						OP not issued until alteration to system		
uthwest	Garfield	Scott Berry and Dave Mock	Boulder	UT	2- 24 units, 65 seat restaurant, office bathroom	installed/inspected 11/2012		
uthwest	Garfield	William D. Hobson	St. George	UT	2- 3 OSS systems	IN	Tank lids needs repairing (noted on 2011 too.	
					·	INI		
outhwest	Kane	Kevin McClaws	Santa Clara	UT	2- Restaurant (35seats)	IN	Needs pumping (2010 and 2011 report- letter	
uthwest	Kane	Kevin McClaws	Santa Clara	UT	2- 25 Residend/transient cabins	IN	sent)	
uthwest	Kane	Kevin McClaws	Santa Clara	UT	2- 25+ Transient Hotel	IN	Needs pumping "right away"	
uthwest	Kane	Kevin McClaws	Santa Clara	UT	2- 35 Rvsites, Laundry, Toilet/shower comples, Trading Post, Gas Station	IN	Pumping needed, add 23" to outlet pipe	
uthwest	Washington	TOTH WOORWS	St. George	UT	2- 114 connection Q=45,600gpd	IN	11/11 pumped out septic tank	
	J		3- 3-		,0,			
office of	M/ hi		I book a		0. 45.000 4	Academy closed down (moved to other		
outhwest outhwest	Washington Washington		Hurrican	UT UT	2- 15,000gpd 2- 18,280gpd	location). Not in use 8/12	report 7/27/12	
นแพธอเ	vvasiiiilgitiii		Virgin	UI	z 10,200gpu	II V	10POIL 1/21/12	

8/20/2012 Page 2 of 2