





Aerial Photo Flown: Aug, 2019

Figure 1
CAMU - Related Air Monitoring
Former Geneva Steel Facility
Vineyard, Utah

-  **Approximate Air Monitoring Location**
-  **Solid Waste Management Unit (SWMU)**
 Note: green shading indicates SWMU with Corrective Action Complete Status
-  **Corrective Action Management Unit**
-  **Excavation Area**

