

State of Utah

GARY R. HERBERT Governor

SPENCER J. COX Lieutenant Governor

Department of Environmental Quality

Amanda Smith Executive Director

DIVISION OF SOLID AND HAZARDOUS WASTE Scott T. Anderson Director Solid and Hazardous Waste Control Board Kevin Murray, Chair Dennis Riding, Vice-Chair Eugene Cole, DrPH Jeff Coombs, MPH, LEHS Mark Franc Brett Mickelson Amanda Smith Shane Whitney Dwayne Woolley Scott T. Anderson Executive Secretary

October 7, 2014

Rick York Intrepid Potash P.O. Box 1208 Moab, Utah 84532

RE: Compliance Evaluation Inspection Intrepid Potash-Moab Class III Landfill

Dear Mr. York:

On, September 25, 2014, a representative of the Division of Solid and Hazardous Waste inspected the Intrepid Potash-Moab Class III landfill to determine compliance with the Utah Solid Waste Permitting and Management Rules and the landfill permit.

Enclosed is a copy of the inspection checklist and brief comments and photographs taken during the inspection. The inspection documented that the landfill operations reviewed during the inspection were being conducted in accordance with the rules and permit requirements.

If you have any questions, please call Rob Powers at (801) 536-0255.

Sincerely,

Scott T. Anderson, Director Division of Solid and Hazardous Waste

STA/RDP/kl

Enclosures: Inspection checklist and photographs

c: David Cunningham, RN, MSN, Health Officer, Southeastern Utah Dist. Health Dept. Brady C. Bradford, MSPH, REHS, Env. Health Director, Southeastern Utah Dist. Health Dept. David Ariotti, P.E., DEQ District Engineer Chad Harris, Intrepid Potash-Moab

DSHW-2014-012953

195 North 1950 West • Salt Lake City, UT Mailing Address: P.O. Box 144880 • Salt Lake City, UT 84114-4880 Telephone (801) 536-0200 • Fax (801) 536-0222 • T.D.D. (801) 536-4414 www.deq.utah.gov Printed on 100% recycled paper

SOLID WASTE FACILITY INSPECTION REPORT CHECKLIST UTAH DIVISION OF SOLID & HAZARDOUS WASTE

Facility Name Intrepid Potash-Moab Class III Landfill	County Grand
Location	
Inspection Date 9/25/14 Time In	Time Out
Routine Oversight 🛛 Follow up 🗌 Monitoring	Evaluation Facility Status Construction Review
Announced Unannounced Weather Condit	
Inspection Goal Compliance with the Utah Solid Waste	Rules and conditions of the approved landfill permit
Facility Contact Chad Harris	
Participants Rob Powers, Chad Harris and Kevin Harmison	
	No Recommended Follow Up Date
(X - indica	tes items reviewed)
1. PRE-INSPECTION REVIEW	
1.1 Permit Review	
Image: 1.2 Annual Report Review	3. SIGNS REQUIRED / PROPERLY POSTED 3.1 Operating Days / Hrs.
	In compliance
1.3 Previous Inspection Review	3.2 Directions & Procedure
Image: 1.4 Facility Contacts Confirmed	In compliance 3.3 Emergency Numbers
I.5 Facility Contacted (if announced inspection)	3.4 List of Unacceptable Materials
Discussed the site visit with Chad Harris prior to my arrival Image: Discussed the site visit with Chad Harris prior to my arrival Image: Discussed the site visit with Chad Harris prior to my arrival Image: Discussed the site visit with Chad Harris prior to my arrival Image: Discussed the site visit with Chad Harris prior to my arrival Image: Discussed the site visit with Chad Harris prior to my arrival	
	3.5 Other
1.7 Other	
	4. OPERATOR / REPRESENTATIVE / EMPLOYEES
2. FACILITY / OPERATIONAL CONTROLS	4.1 On-site while open
2.1 Litter	In compliance
In compliance	- Did not review
In compliance	4.3 Other
Image: Second state of the secon	
In compliance	5 MONITODING
In compliance	5. MONITORING 5.1 Methane
2.5 Communications	NA
	5.2 Random Inspections
2.6 Recycling Area	In compliance 5.3 Leachate
In compliance 2.7 Fugitive Dust Control	NA S.5 Leachate
In compliance	S.4 Ground Water
2.8 Waste Inspection Area	NA
	5.5 Other
2.9 Scavenging Control Not allowed	
Image: Second and wear Image: Seco	6. DRAINAGE / EROSION
NA	6.1 Water Run-on
2.11 Fences, Gates, Locks, Access Control	In compliance
In compliance 2.12 Working Face	In compliance
In compliance	6.3 Other
2.13 Leachate Collection System	
NA 2.14 Other	7. PROPER STORAGE / ISOLATION / DISPOSAL
	7.1 Special Waste

SOLID WASTE FACILITY INSPECTION REPORT

Date:	9/25/14
-------	---------

Facility Name: Intrepid Potash-Moab Class III Landfill

	7.2 Batteries
\square	7.3 Hazardous Waste
NA	
	7.4 Infectious Waste
	7.5 Tires
\square	7.6 Dead Animals
NA	
\square	7.7 Asbestos
In cor	npliance
	7.8 Bulky Waste
	7.9 Contaminated Soil
NA	
	7.10 Ash
	7.11 Sludge
\square	7.12 Other
Const	ruction and demolition waste was in compliance

8. COVER

\square	8.1 Daily - Soil	
In con	In compliance, it is required to cover the waste once every month	
\square	8.2 Daily - Alternative	
In compliance		
	8.3 Intermediate	
	8.4 Final	
	8.5 Vegetation	
	8.6 Other	

9. INSPECTION RECORDS

\square	9.1 Random Inspection Report	
In com	pliance	
\square	9.2 Gas Monitoring System	13. OTHE
NA		☑ 13.
\square	9.3 Surface Drainage Control	Complete
In com	pliance	13.
\square	9.4 Daily Records	
In com	pliance	13.
\square	9.5 Weight or Volumes	
In com	pliance	13.4
\square	9.6 Intermediate Cover	
In com	pliance	13.:
	9.7 Final Cover	
	9.8 Self Inspection (Quarterly) Reports	7
DOUNU	in Dat Da	
DSHW I	nspector Signature:	ale_

	9.9 Deviation from Plans
\boxtimes	9.10 Permit, Permit Application and Rules Available
Maintained in the office for review	
	9.11 Other
Maintai	ned in the office for review

10. MONITORING / SAMPLING / ANALYSIS RECORDS

\boxtimes	10.1 Explosive Gas Monitoring
NA	
\boxtimes	10.2 Leachate Sampling & Treatment
NA	
\boxtimes	10.3 Ground Water Sampling Results
NA	
	10.4 Other

11. SPECIAL WASTE RECORDS

\square	11.1 Lab Analysis Results	
Not re	Not reviewed	
\square	11.2 Manifests	
Not reviewed		
\square	11.3 Treatment Certification	
Not reviewed		
\square	11.4 Paint Filter Test Results	
Not reviewed		
	11.5 Onsite Treatment Documentation	
	11.6 Other	

12. SPECIAL PERMIT REQUIREMENTS

12.1

12.2

12.3

13. OTHER ITEMS
□ 3.1 Notice of Inspections Form Completed and Signed
Completed
13.2
13.3
13.4
13.5

DSHW Inspector Name:

Rob Powers

Date:

9/30/14


INTREPID POTASH-MOAB CLASS III LANDFILL INSPECTION SEPTEMBER 25, 2014



Looking east at the asbestos working face



Looking northwest at the working face of the construction and demolition waste cell



This material is being stored and will be recycled soon