

GARY R. HERBERT

Governor

SPENCER J. COX Lieutenant Governor

Department of Environmental Quality

Amanda Smith Executive Director

DIVISION OF SOLID AND HAZARDOUS WASTE Scott T. Anderson Director Solid and Hazardous Waste Control Board

Kevin Murray, Chair
Dennis Riding, Vice-Chair
Eugene Cole, DrPH
Jeff Coombs, MPH, LEHS
Mark Franc
Brett Mickelson
Amanda Smith
Shane Whitney
Dwayne Woolley
Scott T. Anderson
Executive Secretary

September 16, 2014

Wayne Nielson Nielson Construction Company P.O. Box 620 Huntington, Utah 84528

RE:

Compliance Evaluation Inspection

Nielson Construction Class V Landfill

Dear Mr. Nielson:

On August 26, 2014, the Nielson Construction Class V Landfill was inspected by a representative of the Division of Solid and Hazardous Waste to determine compliance with the Utah Solid Waste Permitting and Management Rules and the landfill permit. Enclosed is a copy of the inspection photographs and the inspection checklist.

Please ensure that the waste is covered once per calendar month with six inches of cover soil. If you have any questions, please call Rob Powers at (801) 536-0255.

Sincerely,

Scott T. Anderson, Director Division of Solid and Hazardous Waste

STA/RDP/k1

Enclosures: Inspection checklist and photographs

c: David Cunningham, RN, MSN, Health Officer, Southeastern Utah Dist. Health Dept. Brady C. Bradford, MSPH, REHS, Env. Health Director, Southeastern Utah Dist. Health Dept. David Ariotti, P.E., DEQ District Engineer Wayne McCandless, Safety/Environmental Officer, Nielson Construction Company

SOLID WASTE FACILITY INSPECTION REPORT CHECKLIST

UTAH DIVISION OF SOLID & HAZARDOUS WASTE

Facility Name Nielson Construction Class V Landfill	County Emery
Location	
Inspection Date 8/26/14 Time In Time Out	
Routine Oversight	Evaluation Facility Status Construction Review
Announced Unannounced Weather Conditi	
Inspection Goal Compliance with the Utah Solid Waste	Rules and conditions of the approved landfill permit
Facility Contact Wayne McCandless	The second secon
Participants Rob Powers	
FOLLOW UP INSPECTION NEEDED Yes N	o Recommended Follow Up Date
TODEOW OF INSPECTION NEEDED	Recommended Follow Op Date
1. PRE-INSPECTION REVIEW (X - indicate	es items reviewed)
1.1 Permit Review	
	3. SIGNS REQUIRED / PROPERLY POSTED
	In compliance 3.2 Directions & Procedure
Tis Trevious Inspection Review	3.2 Directions & Procedure
	3.3 Emergency Numbers
Unannounced	In compliance
☐ 1.6 Local Heath Contacted	☐ 3.5 Other
1.7 Other	
1.7 Suite	A OPERATOR (PERPEGENTATIVE ARMED OVER
A FLOW YEAR (ODER LEVEL) A COMPANY	4. OPERATOR / REPRESENTATIVE / EMPLOYEES 4.1 On-site while open
2. FACILITY / OPERATIONAL CONTROLS 2.1 Litter	In compliance
In compliance	4.2 Training
	Did not review 4.3 Other
In compliance	4.5 Ottlet
2.3 Gate House Operations In compliance	,
☐ 2.4 Vectors	5. MONITORING
In compliance	∑ 5.1 Methane
2.5 Communications	In compliance S.2 Random Inspections
	Did not review
In compliance	
	NA
In compliance	S.4 Ground Water NA
2.8 Waste Inspection Area	5.5 Other
Not allowed	
2.10 Open Burning	6. DRAINAGE / EROSION
NA 2.11 Fences, Gates, Locks, Access Control	6.1 Water Run-on
In compliance	In compliance 6.2 Water Run-off
	In compliance
Reminder to cover the waste monthly with six inches of soil	6.3 Other
	7 PRODER CTORACE / ICOLATION / PICROSAL
2.14 Other	7. PROPER STORAGE / ISOLATION / DISPOSAL 7.1 Special Waste

SOLID WASTE FACILITY INSPECTION REPORT

Date: 8/26/14 Facility Name: Nielson Construction Class V Landfill	
7.2 Batteries	9.8 Self Inspection (Quarterly) Reports
☐ 7.3 Hazardous Waste	9.9 Deviation from Plans
NA	9.9 Deviation from Plans
☐ 7.4 Infectious Waste	9.10 Permit, Permit Application and Rules Available
NA	5.10 Termit, Termit Application and Rules Available
7.5 Tires	9.11 Other
☐ 7.6 Dead Animals	
NA	10. MONITORING / SAMPLING / ANALYSIS RECORDS
☐ 7.7 Asbestos	☐ 10.1 Explosive Gas Monitoring
NA	NA
7.8 Bulky Waste	
57	NA
7.9 Contaminated Soil	☐ 10.3 Ground Water Sampling Results
NA STATE OF THE ST	NA
7.10 Ash	□ 10.4 Other
NA 7.11 Sludge	
NA	11 SPECIAL WASTE DECORDS
7.12 Other	11. SPECIAL WASTE RECORDS 11.1 Lab Analysis Results
Industrial waste	Not reviewed
maddiai waste	☐ 11.2 Manifests
8. COVER	Not reviewed
8.1 Daily - Soil	☐ 11.3 Treatment Certification
Reminder to cover the waste once per month with six inches of	Not reviewed
soil	☐ 11.4 Paint Filter Test Results
⊠ 8.2 Daily - Alternative	Not reviewed
In compliance	☐ 11.5 Onsite Treatment Documentation
8.3 Intermediate	
	☐ 11.6 Other
8.4 Final	
8.5 Vegetation	14 CRECIAL REPLAIT REQUIREMENTS
3.5 vegetation	12. SPECIAL PERMIT REQUIREMENTS 12.1
□ 8.6 Other	
CIO CALLEI	□ 12.2
	12.2
9. INSPECTION RECORDS	12.3
Not reviewed	
9.2 Gas Monitoring System	13. OTHER ITEMS
NA	
9.3 Surface Drainage Control	Completed
In compliance	□ 13.2
9.4 Daily Records	
Not reviewed 9.5 Weight or Volumes	□ 13.3
Solution 9.5 Weight or Volumes Not reviewed	
9.6 Intermediate Cover	□ 13.4
In compliance	□ 13.5
9.7 Final Cover	L 13.3
200/	
DSHW Inspector Signature:	wie

8/28/14

Date:

DSHW Inspector Name (type or print): Rob Powers

$\frac{\text{NIELSON CONSTRUCTION CLASS V LANDFILL INSPECTION}}{\text{AUGUST 26, 2014}}$



Looking west at the working face. The backhoe was placing cover soil during the site visit.



Looking north at the working face.



Looking northeast