

Governor

GREG BELL Lieutenant Governor

Department of **Environmental Quality**

Amanda Smith Executive Director

DIVISION OF SOLID AND HAZARDOUS WASTE Scott T. Anderson Director

Solid and Hazardous Waste Control Board

Kevin Murray, Chair Dennis Riding, Vice-Chair Eugene Cole, DrPH Jeff Coombs, MPH, LEHS Mark Franc Brett Mickelson Amanda Smith Shane Whitney Dwayne Woolley Scott T. Anderson Executive Secretary

May 31, 2013

Reginald Soepnel PacificCorp Energy P.O. Box 569 Castle Dale, Utah 84513

RE: Hunter Power Plant Class IIIb Landfill Inspection

Dear Mr. Soepnel:

On May 20, 2013, a representative of the Division of Solid and Hazardous Waste conducted an inspection of the Class IIIb Landfill at the Hunter Power Plant. The purpose of the inspection was to determine compliance with the Utah Solid Waste Permitting and Management Rules and the landfill permit.

Enclosed is a copy of the inspection checklist and photographs taken during the inspection. The site was well operated and in good shape. No deficiencies were noted in aspects of the landfill operation covered by the inspection.

If you have any questions, please call Rob Powers at (801) 536-0255.

Sincerely

Scott T. Anderson, Director

Division of Solid and Hazardous Waste

STA/RDP/kk

Enclosure: Inspection Report Checklist and Photographs

c: David Cunningham, RN, MSN, Health Officer, Southeast Utah District Health Department Bradon C. Bradford, MSPH, REHS, Environmental Health Director, Southeast Utah District Health Department David Ariotti, DEQ District Engineer Tyson Ekker, PacificCorp Energy

SOLID WASTE FACILITY INSPECTION REPORT CHECKLIST UTAH DIVISION OF SOLID & HAZARDOUS WASTE

Facility Name Hunter Power Plant Class III landfill	County Emery
Location	
Inspection Date 5/20/13 Time In 12:30 pm	Time Out 1:15 pm
Routine Oversight Follow up Monitoring Eva	duation Facility Status Construction Review
	s Partly cloudy and warm
Inspection Goal Compliance with the Utah Solid Waste Ru	les and conditions of the permit
Facility Contact Tyson Ekker	
Participants Tyson Ekker and Rob Powers	
FOLLOW UP INSPECTION NEEDED Yes No	Recommended Follow Up Date
(X - indicates i	items reviewed)
1. PRE-INSPECTION REVIEW	201201000)
1.1 Permit Review	NA
	2.14 Other
1.2 Annual Report Review	
Reviewed in May prior to the inspection	
1.3 Previous Inspection Review Reviewed prior to site visit	3. SIGNS REQUIRED / PROPERLY POSTED
1.4 Facility Contacts Confirmed	3.1 Operating Days / Hrs.
Yes	3.2 Directions & Procedure
1.5 Facility Contacted (if announced inspection)	3.2 Directions & Frocedure
Yes	3.3 Emergency Numbers
1.6 Local Heath Contacted	In compliance
Yes, did not participate	3.4 List of Unacceptable Materials
1.7 Other	In compliance
	3.5 Other
2. FACILITY / OPERATIONAL CONTROLS	
2.1 Litter	A OPER LEON OPERATION OF THE
In compliance	4. OPERATOR / REPRESENTATIVE / EMPLOYEES 4.1 On-site while open
2.2 Roads	In compliance
In compliance	4.2 Training
2.3 Gate House Operations	In compliance
In compliance 2.4 Vectors	4.3 Other
In compliance	
2.5 Communications	
	5. MONITORING
2.6 Recycling Area	5.1 Methane
NA	NA
2.7 Fugitive Dust Control	5.2 Random Inspections
In compliance	5.3 Leachate
2.8 Waste Inspection Area	NA S.S.Ecachate
2.9 Scavenging Control	5.4 Ground Water
In compliance	NA
2.10 Open Burning	5.5 Other
NA	
2.11 Fences, Gates, Locks, Access Control	
In compliance	6. DRAINAGE / EROSION
2.12 Working Face	6.1 Water Run-on
In compliance, see photos 2.13 Leachate Collection System	In compliance
2.13 Leachaic Concetion System	6.2 Water Run-off

SOLID WASTE FACILITY INSPECTION REPORT

Date: Error! Reference source not found.	Facility Name: Hunter Power Plant Class III landfil
In compliance	9.7 Final Cover
☐ 6.3 Other	
	9.8 Self Inspection (Quarterly) Reports
7. PROPER STORAGE / ISOLATION / DISPOSAL	
7.1 Special Waste	9.9 Deviation from Plans
7.2 Batteries	9.10 Permit, Permit Application and Rules Available
7.2 Batteries	In compliance
7.3 Hazardous Waste	9.11 Other
7.4 Infectious Waste	
	10. MONITORING / SAMPLING / ANALYSIS RECORDS
☐ 7.5 Tires	10.1 Explosive Gas Monitoring
	NA 10.2 Leachate Sampling & Treatment
7.6 Dead Animals	NA 10.2 Leachate Sampling & Treatment
7.7 Asbestos	☐ 10.3 Ground Water Sampling Results
7.7 Tisbestos	NA
7.8 Bulky Waste	10.4 Other
In compliance	
7.9 Contaminated Soil	
	11. SPECIAL WASTE RECORDS
☐ 7.10 Ash	11.1 Lab Analysis Results
In compliance	11.2 Manifests
7.11 Sludge	11.2 Wiamitests
In compliance	11.3 Treatment Certification
7.12 Other	11.5 Heatment Certification
	11.4 Paint Filter Test Results
8. COVER	In compliance. Use on the wet sludge materials.
8.1 Daily - Soil	☐ 11.5 Onsite Treatment Documentation
In compliance, see photos	
8.2 Daily - Alternative	☐ 11.6 Other
8.3 Intermediate	12 SDECIAL DEDMIT DECLIDEMENTS
8.4 Final	12. SPECIAL PERMIT REQUIREMENTS 12.1
0.41 mar	
8.5 Vegetation	
□ 8.6 Other	
A INCRECITION DECORDS	14 000000 10000 10
9. INSPECTION RECORDS 9.1 Random Inspection Report	13. OTHER ITEMS 13.1 Notice of Inspections Form Completed and Signed
In compliance	Complete
9.2 Gas Monitoring System	Complete 13.2
NA	13.2
9.3 Surface Drainage Control	□ 13.3
In compliance	
9.4 Daily Records	□ 13.4
In compliance	
9.5 Weight or Volumes	□ 13.5
In compliance	
9.6 Intermediate Cover	
DSHW Inspector Signatures	
DSHW Inspector Signature:	

5/28/13

Date:

DSHW Inspector Name (type or print): Rob Powers

$\frac{\text{HUNTER POWER PLANT CLASS III LANDFILL INSPECTION}}{\text{MAY 20, 2013}}$



Looking south at the working face



Looking west at the working face