

GARY R. HERBERT Governor

SPENCER J. COX Lieutenant Governor

Department of Environmental Quality

Amanda Smith Executive Director

DIVISION OF SOLID AND HAZARDOUS WASTE Scott T. Anderson Director Solid and Hazardous Waste Control Board Kevin Murray, Chair Dennis Riding, Vice-Chair Eugene Cole, DrPH Jeff Coombs, MPH, LEHS Mark Franc Brett Mickelson Amanda Smith Shane Whitney Dwayne Woolley Scott T. Anderson *Executive Secretary*

May 13, 2014

Lori Talbot, City Manager Panguitch City P.O. Box 75 Panguitch, Utah 84726

RE: Compliance Evaluation Inspection Panguitch City Class IVb Landfill

Dear Ms. Talbot:

On April 15, 2014, a representative of the Division of Solid Waste and Hazardous Waste inspected the Panguitch City Class IVb Landfill to determine compliance with the Utah Solid Waste Permitting and Management Rules and the landfill permit. Enclosed is a copy of the inspection checklist and copies of the photographs taken during the inspection. The facility was found to be in compliance with the Rules and the Permit in the areas covered by the inspection.

If you have any questions, please call Rob Powers at (801) 536-0255.

Sincerely,

Scott T. Anderson, Director Division of Solid and Hazardous Waste

STA/RDP/kl

Enclosure: Inspection Checklist, Inspection Photographs

c: David Blodgett, M.D., Health Officer/Director, Southwest Utah Public Health Dept. Robert Beers, MBA, EHS, Environmental Health Director, Southwest Utah Public Health Dept. Paul Wright, P.E., DEQ District Engineer

SOLID WASTE FACILITY INSPECTION REPORT CHECKLIST UTAH DIVISION OF SOLID & HAZARDOUS WASTE

-	y Name Panguitch Class IVb landfill	County Garfield		
Locatio				
Inspect	tion Date <u>4/15/14</u> Time In Ti	me Out		
Routin	ne Oversight 🛛 Follow up 🔲 Monitoring Evalu	ation 🔲 Facility Status 🗌 Construction Review 🗌		
Annou	nced 🛛 Unannounced 🔲 Weather Conditions	Sunny and nice		
Inspect	tion Goal Compliance with the Utah Solid Waste Rule	s and conditions of the approved landfill permit		
-	y Contact Lori Talbot			
-	pants Rob Powers and Allen Moore	·····		
-				
FOLLC	OW UP INSPECTION NEEDED Yes 🗌 No	Recommended Follow Up Date		
1. PRE-IN	(X - indicates ites NSPECTION REVIEW	ms reviewed)		
	1.1 Permit Review			
	1.2 Annual Report Review	3. SIGNS REQUIRED / PROPERLY POSTED		
		3.1 Operating Days / Hrs.		
	1.3 Previous Inspection Review	In compliance		
	1.4 Facility Contacts Confirmed	3.2 Directions & Procedure		
	1.4 Facility contacts commined			
	1.5 Facility Contacted (if announced inspection)	3.3 Emergency Numbers		
Unannou	nced	3.4 List of Unacceptable Materials		
	1.6 Local Heath Contacted			
Yes, via e		3.5 Other		
	1.7 Other			
2. FACIL	ITY / OPERATIONAL CONTROLS	4. OPERATOR / REPRESENTATIVE / EMPLOYEES		
	2.1 Litter	In compliance		
In compli		Im compliance Image: A state of the state of		
In compli	2.2 Roads	Did not review		
	2.3 Gate House Operations	4.3 Other		
In compli				
	2.4 Vectors			
In compli		5. MONITORING		
2	2.5 Communications	S 5.1 Methane		
		In compliance 5.2 Random Inspections		
In compli	2.6 Recycling Area	S.2 Random Inspections		
	2.7 Fugitive Dust Control	5.3 Leachate		
In complia		NA		
	2.8 Waste Inspection Area	5.4 Ground Water		
_		NA		
	2.9 Scavenging Control	5.5 Other		
In compliant \square 2				
	2.10 Open Burning green wastes			
	2.11 Fences, Gates, Locks, Access Control	6. DRAINAGE / EROSION 6.1 Water Run-on		
In compli		In compliance		
2	2.12 Working Face	6.2 Water Run-off		
In complia	ance. Just a reminder to cover the waste once per calendar	In compliance		
	th six inches of cover soil.	6.3 Other		
2 2 NA	2.13 Leachate Collection System			
	2.14 Other	7. PROPER STORAGE / ISOLATION / DISPOSAL		
	· · · · · · · · · · · · · · · · · · ·	7.1 Special Waste		

SOLID WASTE FACILITY INSPECTION REPORT

SOLID WASTE FACILITY INSPECTION REPORT		
Date: 4/15/14 Facility Name: Panguitch Class	s IVb landfill	
	9.8 Self Inspection (Quarterly) Reports	
7.2 Batteries		
	9.9 Deviation from Plans	
7.3 Hazardous Waste		
7.4 Infectious Waste	9.10 Permit, Permit Application and Rules Available	
	9.11 Other	
7.5 Tires		
In compliance		
7.6 Dead Animals	10. MONITORING / SAMPLING / ANALYSIS RECORDS	
	10.1 Explosive Gas Monitoring	
7.7 Asbestos	NA	
7.9 Dulla: Works	10.2 Leachate Sampling & Treatment	
7.8 Bulky Waste	☑ 10.3 Ground Water Sampling Results	
7.9 Contaminated Soil	NA	
	10.4 Other	
7.10 Ash		
7.11 Sludge	11. SPECIAL WASTE RECORDS	
7.12 Other	11.1 Lab Analysis Results	
Image: C & D waste cell in compliance	11.2 Manifests	
e a b waste een in compnance		
8. COVER	11.3 Treatment Certification	
8.1 Daily - Soil		
In compliance. Just a reminder to cover the waste once a month.	11.4 Paint Filter Test Results	
8.2 Daily - Alternative		
8.3 Intermediate	11.5 Onsite Treatment Documentation	
	11.6 Other	
8.4 Final		
8.5 Vegetation	12. SPECIAL PERMIT REQUIREMENTS	
	12.1	
8.6 Other	12.2	
9. INSPECTION RECORDS	12.3	
9.1 Random Inspection Report		
Not reviewed		
9.2 Gas Monitoring System	13. OTHER ITEMS	
NA	□ 13.1 Notice of Inspections Form Completed and Signed	
9.3 Surface Drainage Control	Completed	

15. OTHER ITEMS			
\boxtimes	13.1 Notice of Inspections Form Completed and Signed		
Completed			
	13.2		
	13.3		
	13.4		
	13.5		

DSHW Inspector Signature:_

9.4 Daily Records

9.5 Weight or Volumes

9.7 Final Cover

9.6 Intermediate Cover

In compliance

Not reviewed

Not reviewed

 \boxtimes

win

DSHW Inspector Name (type or print): Rob Powers

Date: <u>4/22/14</u>


PANGUITCH CLASS IVb LANDFILL INSPECTION APRIL 15, 2014



Looking south at the metal recycling area



Green waste pile



Metal recycling area



Looking east at the working face of the construction and demolition waste cell



Looking east at the working face. Just a reminder to cover the waste with six inches of cover soil once a month.



Furniture and mattresses are segregated wastes and should be transported to Johns Valley Class I landfill once a year