



State of Utah

GARY HERBERT
Governor

GREG BELL
Lieutenant Governor

Department of
Environmental Quality

Amanda Smith
Executive Director

DIVISION OF SOLID AND
HAZARDOUS WASTE
Scott T. Anderson
Director

Solid and Hazardous Waste Control Board

Kevin Murray, *Chair*
Dennis Riding, *Vice-Chair*
Jeff Coombs, MPH, LEHS
Eugene Cole, DrPH
Mark Franc
Brett Mickelson
Amanda Smith
Shane Whitney
Dwayne Woolley
Scott T. Anderson
Executive Secretary

May 2, 2013

Valeen Brown
Piute County Clerk
550 North Main Street
P.O. Box 99
Junction, Utah 84740

RE: Landfill Inspection

Dear Ms. Brown:

On April 23, 2013, representatives of the Division of Solid and Hazardous Waste conducted an inspection of the Marysvale Class IVb landfill. The purpose of the inspection was to determine compliance with the permit and the Solid Waste Permitting and Management Rules.

For the areas covered by the inspection, the facility was found to be in compliance and no violations were noted. Enclosed are copies of the photographs taken during the inspection and a copy of the inspection checklist.

If you have any questions, please call Matt Sullivan at (801) 536-0241 or Rob Powers at (801) 536-0255.

Sincerely,

Scott T. Anderson, Director
Division of Solid and Hazardous Waste

STA/RDP/kk

Enclosures: Inspection checklist, Inspection photographs

c: Bruce Costa, PhD., Health Director, Central Utah Health Department
Phil Bondurant, MPH, REHS, HHS, Environmental Health Director, Central Utah Health Department
John Chartier, P.E., District Engineer

SOLID WASTE FACILITY INSPECTION REPORT CHECKLIST

UTAH DIVISION OF SOLID & HAZARDOUS WASTE

Facility Name Marysville Class IV landfill County Piute
 Location _____
 Inspection Date 4/23/13 Time In _____ Time Out _____
 Routine Oversight Follow up Monitoring Evaluation Facility Status Construction Review
 Announced Unannounced Weather Conditions Sunny and cold
 Inspection Goal Compliance with the Utah Solid Waste Rules and conditions of the Permit
 Facility Contact Valeen Brown
 Participants Rob Powers
 FOLLOW UP INSPECTION NEEDED Yes No Recommended Follow Up Date _____

(X - indicates items reviewed)

1. PRE-INSPECTION REVIEW

<input type="checkbox"/>	1.1 Permit Review
<input type="checkbox"/>	1.2 Annual Report Review
<input type="checkbox"/>	1.3 Previous Inspection Review
<input type="checkbox"/>	1.4 Facility Contacts Confirmed
<input checked="" type="checkbox"/>	1.5 Facility Contacted (if announced inspection) Unannounced
<input checked="" type="checkbox"/>	1.6 Local Health Contacted Yes
<input type="checkbox"/>	1.7 Other

NA
<input type="checkbox"/> 2.14 Other

3. SIGNS REQUIRED / PROPERLY POSTED

<input type="checkbox"/>	3.1 Operating Days / Hrs.
<input type="checkbox"/>	3.2 Directions & Procedure
<input type="checkbox"/>	3.3 Emergency Numbers
<input type="checkbox"/>	3.4 List of Unacceptable Materials
<input type="checkbox"/>	3.5 Other

2. FACILITY / OPERATIONAL CONTROLS

<input checked="" type="checkbox"/>	2.1 Litter In compliance
<input checked="" type="checkbox"/>	2.2 Roads In compliance
<input checked="" type="checkbox"/>	2.3 Gate House Operations In compliance
<input type="checkbox"/>	2.4 Vectors
<input type="checkbox"/>	2.5 Communications
<input type="checkbox"/>	2.6 Recycling Area
<input type="checkbox"/>	2.7 Fugitive Dust Control
<input type="checkbox"/>	2.8 Waste Inspection Area
<input type="checkbox"/>	2.9 Scavenging Control
<input checked="" type="checkbox"/>	2.10 Open Burning In compliance, see photos of green waste pile
<input checked="" type="checkbox"/>	2.11 Fences, Gates, Locks, Access Control Entrance gate is not secure
<input checked="" type="checkbox"/>	2.12 Working Face In compliance, see photographs
<input checked="" type="checkbox"/>	2.13 Leachate Collection System

4. OPERATOR / REPRESENTATIVE / EMPLOYEES

<input type="checkbox"/>	4.1 On-site while open
<input type="checkbox"/>	4.2 Training
<input type="checkbox"/>	4.3 Other

5. MONITORING

<input checked="" type="checkbox"/>	5.1 Methane NA
<input type="checkbox"/>	5.2 Random Inspections
<input checked="" type="checkbox"/>	5.3 Leachate NA
<input checked="" type="checkbox"/>	5.4 Ground Water NA
<input type="checkbox"/>	5.5 Other

6. DRAINAGE / EROSION

<input checked="" type="checkbox"/>	6.1 Water Run-on In compliance
<input checked="" type="checkbox"/>	6.2 Water Run-off

SOLID WASTE FACILITY INSPECTION REPORT

Date: 4/23/13

Facility Name: Marysville Class IV landfill

In compliance	
<input type="checkbox"/>	6.3 Other

7. PROPER STORAGE / ISOLATION / DISPOSAL

<input type="checkbox"/>	7.1 Special Waste
<input type="checkbox"/>	7.2 Batteries
<input checked="" type="checkbox"/>	7.3 Hazardous Waste Stored near the waste tire pile, see photos
<input type="checkbox"/>	7.4 Infectious Waste
<input type="checkbox"/>	7.5 Tires
<input type="checkbox"/>	7.6 Dead Animals
<input type="checkbox"/>	7.7 Asbestos
<input checked="" type="checkbox"/>	7.8 Bulky Waste In compliance
<input type="checkbox"/>	7.9 Contaminated Soil
<input type="checkbox"/>	7.10 Ash
<input type="checkbox"/>	7.11 Sludge
<input type="checkbox"/>	7.12 Other

8. COVER

<input checked="" type="checkbox"/>	8.1 Daily - Soil In compliance, make sure you cover waste once per month
<input type="checkbox"/>	8.2 Daily - Alternative
<input type="checkbox"/>	8.3 Intermediate
<input type="checkbox"/>	8.4 Final
<input type="checkbox"/>	8.5 Vegetation
<input type="checkbox"/>	8.6 Other

9. INSPECTION RECORDS

<input type="checkbox"/>	9.1 Random Inspection Report
<input checked="" type="checkbox"/>	9.2 Gas Monitoring System NA
<input checked="" type="checkbox"/>	9.3 Surface Drainage Control In compliance
<input checked="" type="checkbox"/>	9.4 Daily Records Did not review
<input checked="" type="checkbox"/>	9.5 Weight or Volumes Did not review
<input type="checkbox"/>	9.6 Intermediate Cover

<input type="checkbox"/>	9.7 Final Cover
<input type="checkbox"/>	9.8 Self Inspection (Quarterly) Reports
<input type="checkbox"/>	9.9 Deviation from Plans
<input type="checkbox"/>	9.10 Permit, Permit Application and Rules Available
<input type="checkbox"/>	9.11 Other

10. MONITORING / SAMPLING / ANALYSIS RECORDS

<input checked="" type="checkbox"/>	10.1 Explosive Gas Monitoring NA
<input checked="" type="checkbox"/>	10.2 Leachate Sampling & Treatment NA
<input checked="" type="checkbox"/>	10.3 Ground Water Sampling Results NA
<input type="checkbox"/>	10.4 Other

11. SPECIAL WASTE RECORDS

<input type="checkbox"/>	11.1 Lab Analysis Results
<input type="checkbox"/>	11.2 Manifests
<input type="checkbox"/>	11.3 Treatment Certification
<input type="checkbox"/>	11.4 Paint Filter Test Results
<input type="checkbox"/>	11.5 Onsite Treatment Documentation
<input type="checkbox"/>	11.6 Other

12. SPECIAL PERMIT REQUIREMENTS

<input type="checkbox"/>	12.1
<input type="checkbox"/>	12.2
<input type="checkbox"/>	12.3

13. OTHER ITEMS

<input checked="" type="checkbox"/>	13.1 Notice of Inspections Form Completed and Signed Done
<input type="checkbox"/>	13.2
<input type="checkbox"/>	13.3
<input type="checkbox"/>	13.4
<input type="checkbox"/>	13.5

DSHW Inspector Signature: 

DSHW Inspector Name (type or print): Rob Powers

Date: 4/23/13

MARYSVALE CLASS IV LANDFILL INSPECTION
APRIL 23, 2013



Municipal Solid Waste containers for the local residence of Marysvale, this waste is transported to the Garfield County Class I landfill



Tire pile



Construction and demolition waste working face



This waste is stored on site and then transported for final disposal to the Garfield County landfill



Green waste pile



The entrance to the landfill